


# SERIES CONNECTION




VARIES TORQUE


FIELD COIL

MAIN FIELD COIL

MAJOR INSULATION



# COMPOUND CONNECTION



GOOD FOR STABILITY.

INSULATION - LIQUID INSULATION


INTERWINDING INSULATION




# DIRECT MACHINE

GENERATOR — CONVERT MECHANICAL ENERGY → ELECTRICAL ENERGY  
 MOTOR — CONVERT ELECTRICAL ENERGY → MECHANICAL ENERGY

## GENERATOR ACTION



## MOTOR ACTION



GENERATOR  
 AN EM  
 MOVES  
 THAT  
 THE MA  
 OF CUT  
 MOTOR  
 MOTOR  
 FORCE  
 A MA  
 ON T

HERE

ITE BOARD



ELECTRICAL ENERGY

MECHANICAL ENERGY

TION

→ MAGNETIC  
FIELD (I)


Voltage

### GENERATOR

AN EMF IS INDUCED IN A CONDUCTOR WHEN THE CONDUCTOR MOVES IN SUCH A DIRECTION RELATIVE TO A MAGNETIC FIELD THAT THE CONDUCTOR CUTS THE MAGNETIC FIELD. THE MAGNITUDE OF THE EMF IS GOVERNED BY THE RATE OF CUTTING.

### MOTOR

MOTOR ACTION IS BASED UPON THE FACT THAT A MECHANICAL FORCE IS EXERTED ON A CURRENT CARRYING CONDUCTOR IN A MAGNETIC FIELD. THE MAGNITUDE OF THE FORCE DEPENDS ON THE FIELD STRENGTH AND CURRENT.



COPPER  
COPPER






CONDUCTOR  
MAGNETIC FIELD

THE RATE

MECHANICAL  
CONDUCTOR IN  
FORCE DEPENDS



CURRENT IN COIL

CURRENT IN LOAD



## GENERATED VOLTAGE EQUATION

$$e = B L V \sin \theta$$


$e$  = GENERATED VOLTAGE (VOLT)

$B$  = FIELD FLUX DENSITY (TESLA)

$L$  = EFFECTIVE LENGTH OF CONDUCTOR (m)

$V$  = VELOCITY OF CONDUCTOR

$\theta$  = ANGLE BETWEEN FLUX AND MOVEMENT



ELECTRICAL

PARTS

MAIN  
POLE

INTERPOLE






ELECTRICAL POWER OUTPUT:  $(P) = B L V \sin \theta \ I$

$P$  = ELECTRICAL POWER (WATT)  
 $I$  = CURRENT (AMPERE)




### PARTS OF DC MACHINE

Yoke (FRAME, BODY)






I



- COMMUTATOR
- HARD DRAWN
- INSULATION
- BRUSH
- CARBON BRUSH




1 → 1.5mm  
THICK  
STEEL PLATES.



2 → 0.8mm  
LAMINATED STEEL  
SHEET


VENTILATION  
DUCTS.




COMMUTATOR

- HARD DRAWN OR SILVERED COPPER
- INSULATION VEE ARE FILLED WITH MICA


BRUSH




(A) SHUNT CONN



(B) SEPARATELY EXC









## CONNECTION OF DC MACHINES


### (A) SHUNT CONNECTION




### (B) SEPARATELY EXCITATION



### (C) SERIES CONNECTION




### (D) COMPOUND CONNECTION





LONG SHUNT COMPOUND MOTOR




$$I_{sh} = \frac{V_t}{R_{sh}}$$

$$E_b = V_t - I_a(R_{se} + R_a + 2R_b)$$

$$I_a = I_L - I_{sh}$$

SHORT SHUNT COMPOUND MOTOR



$$I_{sh} = \frac{V_t - I_L R_{se}}{R_{sh}}$$

$$E_b = V_t - (I_L R_{se} + I_a(R_a + 2R_b))$$

$$I_a = I_L - I_{sh}$$




9044

# Types of DC ARMATURE WINDINGS




COMMUTATOR




WAVE WINDING

LAP WINDING



WINDING



COMMUTATOR

SHAFT

SHAFT



COIL PITCH


$$Y_k = \frac{S}{P} \pm k$$

S = NO. OF SLOTS

P = NO. OF POLES

K = A FRACTION  
ADDED TO  
FROM  $\frac{S}{P}$   
INTEGER






COIL PITCH

$$Y_p = \frac{S}{P} \pm k$$

$S$  = NO. OF SLOTS

$P$  = NO. OF POLES

$k$  = A FRACTION THAT IS EITHER  
ADDED TO OR SUBTRACTED  
FROM  $\frac{S}{P}$  TO MAKE  $Y_p$  TO BE  
INTEGER



SLOT PITCH

pb

CALCULATE THE COIL PITCH  $Y_p$  AND INDICATE THE SLOT  
NUMBERS IN WHICH THE FIRST COIL IS WOUND FOR  
EACH OF THE FOLLOWING CASES ASSUMING THAT THE  
DETAILS REFER TO A 4 POLE MACHINE.

(a)  $S = 35$  (b)  $S = 36$  (c)  $S = 37$  (d)  $S = 42$

(a)  $Y_p = \frac{S}{P} = \frac{35}{4} = 8 \frac{1}{4} - \frac{1}{4} = 8$  slot 1  $\rightarrow$  9

(b)  $Y_p = \frac{S}{P} = \frac{36}{4} = 9$  slot 1  $\rightarrow$  10

(c)  $Y_p = \frac{S}{P} = \frac{37}{4} = 9 \frac{1}{4} - \frac{1}{4} = 9$  slot 1  $\rightarrow$  10

(d)  $Y_p = \frac{S}{P} = \frac{42}{4} = 10 \frac{1}{2} - \frac{1}{2} = 10$  slot 1  $\rightarrow$  11



AND INDICATE THE SLOT  
ST COIL IS WOUND FOR  
ES ASSUMING THAT THE  
OLE MACHINE.

(c)  $S=37$  (d)  $S=42$

$$\frac{1}{4} - \frac{1}{4} = 8 \quad \text{slot } 1 \rightarrow 9$$

$$\text{slot } 1 \rightarrow 10$$

$$\frac{1}{4} - \frac{1}{4} = 9 \quad \text{slot } 1 \rightarrow 10$$

$$0 \frac{1}{2} - \frac{1}{2} = 10 \quad \text{slot } 1 \rightarrow 11$$

pb

REPEAT THE ABOVE EXAMPLE FOR  
THE FOLLOWING CASES ASSUMING THAT IN  
EACH INSTANCE THE DATA REFERS TO A  
6 pole machine.


(a)  $S=72$  (b)  $S=37$  (c)  $S=77$

$$(a) \quad Y = \frac{S}{P} = \frac{72}{6} = 12 \quad 1 \rightarrow 13$$


$$(b) \quad Y = \frac{S}{P} = \frac{37}{6} = 6 \frac{1}{6} - \frac{1}{6} = 6 \quad 1 \rightarrow 7$$

$$(c) \quad Y = \frac{S}{P} = \frac{77}{6} = 12 \frac{5}{6} - \frac{5}{6} = 12 \quad 1 \rightarrow 13$$

### PROGRESSIVE AND RETROGRESSIVE WINDINGS



FOR SIMPLE X  
LAP  
PROGRESSIVE WINDING



$Y_c = \text{commutator pitch} = -1$  FOR SIMPLE X LAP  
RETROGRESSIVE  
WINDING



## WAVE WINDING

IN SIMPLEX WAVE WINDING, THE CIRCUIT RETURNS TO A SEGMENT ADJACENT TO THE STARTING SEGMENT AFTER TRANSVERSING  $\frac{P}{2}$  COILS

$$Y_c = \frac{C \pm m}{P/2}$$

C = NO OF COMMUTATOR SEGMENT

m = 1 FOR SIMPLEX WAVE  
2 FOR DUPLEX WAVE

+ PROGRESSIVE  
- RETROGRESSIVE

P = NO. OF POLES.

pb) FIND THE COMMUTATOR PITCH OF THE FOLLOWING WINDINGS 4 poles

- |              |              |               |
|--------------|--------------|---------------|
| (a) 35 slots | Simplex wave | PROGRESSIVE   |
| (b) 35 slots | Simplex wave | RETROGRESSIVE |
| (c) 34 slots | Duplex wave  | PROGRESSIVE   |
| (d) 34 slots | Duplex wave  | RETROGRESSIVE |

$$(a) \frac{34-2}{4/2} = 1$$

$$\frac{32}{2} = 16$$


$$(a) Y_c = \frac{C \pm m}{P/2} = \frac{35 + 1}{4/2} = \frac{36}{2} = 18 \quad 1 \rightarrow 19$$

$$(b) Y_c = \frac{C \pm m}{P/2} = \frac{35 - 1}{4/2} = \frac{34}{2} = 17 \quad 1 \rightarrow 18$$

$$(c) Y_c = \frac{C \pm m}{P/2} = \frac{34 + 2}{4/2} = \frac{36}{2} = 18 \quad 1 \rightarrow 19$$




# MECHANICAL ACTION OF DC GENERATOR AND MOTOR



⊗ ⊙ CURRENT DIRECTION

GENERATOR ACTION



MOTOR ACTION

$$T = I \alpha$$



pb


A motor of 10 N

200 RAD

The motor calculate



# GENERATOR AND MOTOR



MOTOR ACTION


$$T = I \alpha$$

$T = \text{TORQUE } N-m$

$I = \text{MOMENT OF INERTIA } N-m/s^2$

$\alpha = \text{ANGULAR ACCELERATION } RAD/s^2$

$t \text{ sec}$



$w = \text{ANGULAR VELOCITY } RAD/s$

$$w_2 = w_1 + \alpha t$$

pb

A motor HAS A COMBINED MOMENT OF INERTIA OF  $10 N-m/s^2$  AND INITIAL VELOCITY OF  $200 RAD/s$ . IF THE TORQUE PRODUCED BY THE MOTOR IS INCREASED BY  $50 N-m$  CALCULATE (a) THE TIME FOR THE SPEED TO REACH  $300 RAD/s$

(b) THE FINAL SP  
(c) THE TORQUE OF  $50 N$

$$I = 10 N-m$$

$$T = 50 N$$

(a)  $w_1$

$$T = I$$

$$50 = 10$$

$$\alpha = \frac{50}{10}$$



$T = \text{TORQUE}$   $\text{N-m}$

$I = \text{MOMENT OF INERTIA}$   $\text{N-m/s}^2$

$\alpha = \text{ANGULAR ACCELERATION}$   $\text{RAD/s}^2$

$\omega = \text{ANGULAR VELOCITY}$   $\text{RAD/s}$

$$\boxed{\omega_2 = \omega_1 + \alpha t}$$

A COMBINED MOMENT OF INERTIA

$\text{AND INITIAL VELOCITY OF}$

IF THE TORQUE PRODUCED BY

INCREASED BY  $50 \text{ N-m}$

THE TIME FOR THE SPEED TO REACH

$\text{RAD/s}$

(b) THE FINAL SPEED IF THE TORQUE WAS MAINTAINED FOR 10 sec

(c) THE TORQUE INCREASE NECESSARY TO OBTAIN AN INCREASE  
OF  $50 \text{ RAD/s}$  IN  $2.5 \text{ SEC}$ .

$$I = 10 \text{ N-m/s}^2 \quad \omega_1 = 200 \text{ RAD/s}$$

$$T = 50 \text{ N-m} \quad \omega_2 = 300 \text{ RAD/s}$$

$$t = ?$$

$$(a) \quad \omega_2 = \omega_1 + \alpha t$$

$$T = I \alpha$$

$$50 = 10 \alpha$$

$$\alpha = \frac{50}{10} = 5 \text{ RAD/s}^2$$

$$\omega_2 = \omega_1 + \alpha t$$

$$300 = 200 + 5 \times t$$

$$t = \frac{300 - 200}{5}$$

$$= \frac{100}{5} = 20 \text{ sec}$$



(b)  $t = 10 \text{ sec}$

$\omega_2 = ?$

$$\omega_2 = \omega_1 + \alpha t$$

$$= 200 + 5 \times 10$$

$$= 250 \text{ RAD/s}$$

(c)  $\omega_2 - \omega_1 = 50 \text{ RAD/s}$


$t = 2.5 \text{ sec}$

$T = ?$

$$\alpha = \frac{\omega_2 - \omega_1}{t} = \frac{50}{2.5} = 20 \text{ RAD/s}^2$$

$$T = I \alpha = 10 \times 20 = 200 \text{ N-m}$$

### CONFIGURATION OF DC MACHINE WINDINGS



SHUNT GENERATOR

$R_{sh}$  = SHUNT FIELD RESISTANCE

$R_a$  = ARMATURE RESISTANCE

$R_b$  = BRUSH RESISTANCE


$E_g$  = GENERATED VOLTAGE

$V_t$  = TERMINAL VOLTAGE

$$I_a = I_L + I_{sh}$$

$$I_{sh} = \frac{V_t}{R_{sh}}$$

$$E_g = V_t + I_a(R_a + 2R_b)$$



SERIES GENERATOR

$$I_a = I_L$$

$$E_g = V_t + I_L(R_a + 2R_b)$$

$$I_L = \frac{\text{LOAD POWER}}{V_t}$$



MACHINE WINDINGS



RATOR

STANCE


RESISTANCE

ANCE

VOLTAGE

VOLTAGE

h




$$I_a = I_L$$

$$E_g = V_t + I_L (R_{se} + R_a + 2R_b)$$

$$I_L = \frac{\text{LOAD POWER}}{V_t}$$

LONG SHUNT COMPOUND GENERATOR




$$I_{sn} = \frac{V_t}{R_{sh}}$$

$$I_a = I_{sn} + I_L$$

$$E_g = V_t + I_a (R_{se} + R_a + 2R_b)$$

$$E_g = V_t + I_a (R_a + 2R_b)$$






SHORT SHUNT Compound

$$I_a = I_L + I_{sh}$$

$$I_{sh} = \frac{V_t + I_L R_{se}}{R_{sh}}$$

$$E_g = V_t + I_a (R_a + 2R_b)$$




SERIES motor

$E_b = \text{BACK EMF}$

$$I_L = I_a$$

$$E_b = V_t - I_a (R_a + 2R_b)$$



SHUNT motor

$$I_{sh} = \frac{V_t}{R_{sh}}, \quad E_b = V_t - I_a (R_a + 2R_b)$$

$$I_a = I_L - I_{sh}$$



e-com

G043 + G045

7762AF

G043 - G045 - 7762AF Notes 1

G043 - G045 - 7762AF Notes 2

G046 - G040 - G043 - G045 - G042 Tutorial

SLAA  
AG  
AG

7762AF 7762AF

7762AF

7762AF  
4269T

## GENERATED VOLTAGE + BACK EMF

$$E_g = \frac{\phi Z N}{60} \times \frac{P}{a} \quad (\text{GENERATOR})$$

$E_g$  = GENERATED VOLTAGE

$Z$  = NO. OF CONDUCTORS

$N$  = RPM


$P$  = NO. OF POLES

$a$  = NO. OF ARMATURE PARALLEL PATHS


$a = m \times p$  (LAP)

$a = m \times 2$  (WAVE)

$$E_b = \frac{\phi Z N}{60} \times \frac{P}{a} \quad (\text{MOTOR})$$



GENERATOR




MOTOR



# MAGNETIC ACTION OF ARMATURE FIELD DISTORTION



MAGNETIC NEUTRAL




ARMATURE  
MAGNETIC  
FLUX

(ATC)

UNIT


FIELD  
POLE  
WAVEFORM



Motor



ARMATURE  
CONDUCTORS



GENERATOR



RESULTANT  
WAVEFORM

ARMATURE  
REACTION

OPPOSING  
MAIN FIELD FLUX → DEMAGNETIZING FLUX

CROSSING  
MAIN FIELD  
FLUX → CROSS MAGNETIZING  
FLUX


EFFECTS GENERATED  
VOLTAGE & TORQUE



(ATC) CROSS MAGNETIZING FLUX =  $\frac{\gamma Z I_a}{2 a P}$

UNIT  $\rightarrow$  (Amp-TURNS/POLE)

$\gamma = \frac{\text{POLE ARC}}{\text{POLE PITCH}}$




$Z$  = NO. OF ARMATURE CONDUCTORS  
 $a$  = NO. OF ARMATURE PARALLEL PATHS  
 $P$  = NO. OF POLES.

ING  
 FIELD FLUX  $\rightarrow$  DEMAGNETIZING FLUX  
 CROSSING  
 IN FIELD  
 FLUX  $\rightarrow$  CROSS MAGNETIZING FLUX  
 ERATED  
 Torque

pb  
 AN ARMATURE 0.5m DIAMETER OF 6 POLES LAP WOUND GENERATOR HAS 378 CONDUCTORS CARRIES 800 AMP AND HAS A POLE ARC 0.17m. CALCULATE CROSS MAGNETIZING ARMATURE REACTION AMPERE TURN.

$AT_c = \frac{\gamma Z I_a}{2 a P}$

$\gamma = \frac{\text{POLE ARC}}{\text{POLE PITCH}}$



$= \frac{0.17}{\frac{\pi D}{\text{No. of poles}}}$   
 $= \frac{0.17}{\frac{3.1416 \times 0.5}{6}} = 0.65$

$a = ?$   
 $a = ?$   
 $AT_c =$   
 $=$



0.5m DIAMETER OF  
AND GENERATOR HAS 378  
ES 800 AMP AND HAS  
17mm. CALCULATE

ARMATURE REACTION  
SIMPLEX (AP)


$I_a$

$P$

POLES

$= 0.65$

0.5



$$a = m \times P$$

$n = 1$  SIMPLEX  
 $m = 2$  DUPLEX


$$a = 2m$$

$m = 1$  SIMPLEX  
 $m = 2$  DUPLEX

$$a = m \times P = 1 \times 6 = 6$$


$$AT_c = \frac{0.65 \times 378 \times 800}{2 \times 6 \times 6}$$

$$= 2740 \text{ AT / POLE}$$




METHODS TO REDUCE ARMATURE

(1) INTER POLE



(2) SHIFT THE BRUSH








$a = m \times p$   $m=1$  Simplex  $m=2$  Duplex


$a = 2m$   $m=1$  Simplex  $m=2$  Duplex

$6 = 6$   
 $78 \times 800$   
 $6$   
 $AT / POLE$



# METHODS TO REDUCE ARMATURE REACTION


(1) INTER POLE



$$AT_d = \text{DEMAGNETIZING} \frac{\text{AMP-TURNS}}{\text{POLE}} = \frac{\beta}{2P}$$

$$AT_c = \text{CROSS MAGNETIZING} \frac{\text{AMP-TURNS}}{\text{POLE}} = \frac{Z I_a}{2P}$$

(2) SHIFT THE BRUSH




ELECTRICAL DEGREE DIFFERENCE BETWEEN ORIGINAL & FINAL BRUSH POSITION  $(\beta)$

Pd THE BRUSHES ON A ROTATED 0.03 m 6 POLES, LAP WOUND ARMATURE CURRENT AND DEMAGNETIZING



# DUCE ARMATURE REACTION



$$AT_d = \text{DEMAGNETIZING} \\ \text{AMP-TURNS / POLE} = \frac{\beta Z I_a}{360 a}$$

$Z$  = NO. OF CONDUCTORS

$I_a$  = ARMATURE CURRENT

$a$  = ARMATURE PARALLEL PATH

$$AT_c = \text{CROSS MAGNETIZING} \\ \text{AMP-TURNS / POLE} = \frac{Z I_a}{2 P} \left( \frac{360 - 2 P \beta}{720} \right)$$

$P$  = NO. OF POLES.

Pb

THE BRUSHES ON A 0.4 m DIAMETER COMMUTATOR ARE ROCKED 0.03 m CIRCUMFERENTIALLY. THE MACHINE HAS 6 POLES, LAP WOUND (SIMPLEX), 378 CONDUCTORS, 800 AMP ARMATURE CURRENT. CALCULATE CROSS MAGNETIZING AND DEMAGNETIZING AMP-TURNS / POLE.


NO SPARKING

ELECTRICAL DEGREE  $(\beta)$   
DIFFERENCE BETWEEN  
ORIGINAL & FINAL BRUSH POSITION



## METHODS TO REDUCE ARMATURE REACTION

(1) INTER POLE



$$AT_d = \text{DEMAGNETIZING} \quad \text{AMP-TURNS / POLE} = \frac{\beta Z I_a}{360 a}$$

$Z$  = NO. OF CONDUCTORS



$I_a$  = ARMATURE CURRENT

$a$  = ARMATURE PARALLEL PATHS

$$AT_c = \text{CROSS MAGNETIZING} \quad \text{AMP-TURNS / POLE} = \frac{Z I_a}{2P} \left( \frac{360 - 2P\beta}{720} \right)$$

$\beta$  = SHIFTING OF BRUSH ANGLE

(2) SHIFT THE BRUSH



ELECTRICAL DEGREE DIFFERENCE BETWEEN ORIGINAL & FINAL BRUSH POSITION ( $\beta$ )


Pb

THE BRUSHES ON A 0.4 m DIAMETER COMMUTATOR ARE ROCKED 0.03 m CIRCUMFERENTIALLY. THE MACHINE HAS 6 POLES, LAP WOUND (SIMPLEX), 378 CONDUCTORS, 800 AMP ARMATURE CURRENT. CALCULATE CROSS MAGNETIZING AND DEMAGNETIZING AMP-TURNS / POLE. (SIMPLEX LAP)

$P$  = NO. OF POLES.

WWW.POWER SEMESTER 4.ZOOMSHARE.COM





$$\beta = \frac{\text{SHIFTING CIRCUMFERENTIAL DISTANCE}}{\pi \times \text{DIAMETER}} \times 360$$


$$= \frac{0.03}{3.1416 \times 0.4} \times 360 = 8.6$$

$$\text{DE MAGNETIZING (AT}_d) = \frac{\beta Z I_a}{360 a} = \frac{8.6 \times 378 \times 800}{360 \times 6}$$

$$\left( \begin{array}{l} a = m \times p \\ = 1 \times 6 = 6 \end{array} \right) = 1210 \text{ AT / pole.}$$

$$\begin{aligned} \text{CROSS MAGNETIZING (AT}_c) &= \frac{Z I_a}{2p} \left( \frac{360 - 2p\beta}{720} \right) \\ &= \frac{378 \times 800}{2 \times 6} \left( \frac{360 - 2 \times 6 \times 8.6}{720} \right) \\ &= 3000 \text{ AT / pole} \end{aligned}$$





$$\beta = \frac{\text{SHIFTING CIRCUMFERENTIAL DISTANCE}}{\pi \times \text{DIAMETER}} \times 360$$

$$= \frac{0.03}{3.1416 \times 0.4} \times 360 = 8.6$$

$$\text{DE MAGNETIZING (AT}_d) = \frac{\beta Z I_a}{360 a} = \frac{8.6 \times 378 \times 800}{360 \times 6}$$

$$\left( \begin{array}{l} a = m \times p \\ = 1 \times 6 = 6 \end{array} \right)$$

$$= 1210 \text{ AT / pole}$$

$$\text{CROSS MAGNETIZING (AT}_c) = \frac{Z I_a}{2p} \left( \frac{360 - 2p\beta}{720} \right)$$

$$= \frac{378 \times 800}{2 \times 6} \left( \frac{360 - 2 \times 6 \times 8.6}{720} \right)$$

$$= 3000 \text{ AT / pole}$$

Simplex


Duplex

4 poles

SERIES

4 poles

SERIES / PARA





360


$0.6 \times 378 \times 800$   
 $360 \times 6$

210 AT / pole.


$\left( \frac{360 - 2p\beta}{720} \right)$

$\left( \frac{360 - 2 \times 6 \times 8.6}{720} \right)$   
 / pole

Simplex




Duplex




$a = m \times p$  Lap  
 $a = 2 \times m$  wave

4 poles  
 Series



4 poles  
 Series / Parallel



VOLTA

THE VOL

N=

t=

Z=

$\phi_c=$

- THE

IN

SHO


- TO

THE

FO



$m \times p$  LAP  
 $2 \times m$  WAVE



### VOLTAGE OF SELF INDUCTION

$$\text{THE VOLTAGE OF SELF INDUCTION} = \frac{N Z \phi_c}{t} \quad \text{VOLT}$$

$N$  = TURN / COIL SHORT CIRCUITED DURING COMMUTATION

$t$  = TIME DURING WHICH CURRENT IS REVERSING

$Z$  = NO. OF ARMATURE CONDUCTORS

$\phi_c$  = FLUX


- THE BRUSH CONTACT RESISTANCE PLAYS A VERY IMPORTANT PART IN LIMITING THE CIRCULATING CURRENT WHEN THE BRUSH SHORT CIRCUITS THE COIL.
- TO IMPROVE THE COMMUTATION, IT NEEDS TO MOVE A LITTLE THE BRUSH IN FORWARD DIRECTION OF MACHINE ROTATION FOR GENERATOR AND BACKWARD FOR MOTOR.



### METHODS TO

(1) INTER POLE

(2) SHIFT THE





www.PowerSemester4.zoomshare.com

STAGE (4)

G044 | 7762AC

G044\_7762AC1

G044\_7762AC2

G044\_Tutorial

G043 + G045

7762AF

G043\_G045\_7762AF Notes 1

G043\_G045\_7762AF Notes 2

G045\_G046\_G040\_G043\_G045\_G042 Tutorial

7762AA  
AC  
AG

7762AE

7762AQ

7762AF

7762AH

4269T

GENERATED

$$E_g = \frac{\phi}{\dots}$$

$$E_g = \frac{G}{\dots}$$

$$Z = \frac{N}{\dots}$$

$$N = RP$$

$$P = NO.$$

$$a = NO$$

$$E_b = \dots$$






# POWER FLOW DIAGRAM IN DC MOTOR

$$V - V_t I_f = V_t I_L$$


ELECTRICAL  
LOAD



ph THE  
MOTOR

IF THE  
DETER

(a)  
(b)



(out)

$I_{sh}$

$$\eta = \frac{\text{OUTPUT}}{\text{INPUT}} \times 100 = \left( 1 - \frac{\text{Power loss}}{P_{out} + P_{loss}} \right) \times 100$$



## LOSSES AND EFFICIENCY IN DC MACHINE

CONSTANT LOSS

### ROTATIONAL LOSSES

- HEAT PRODUCED BY BEARING
- HEAT PRODUCED BY ARMATURE CONDUCTOR

BEARING FRICTION, WIND FRICTION, BRUSH FRICTION,  
EDDY CURRENT & HYSTERESIS LOSS, WINDAGE LOSS,

AMOUNT OF LOSS DEPENDS ON

- MAGNETIC IRON
- FREQUENCY OF SUPPLY
- FLUX DENSITY
- MASS OF IRON

### HYSTERESIS LOSS


$$K_h = \text{CONST}$$

$$f = \text{FREQUENCY}$$

$$B = \text{MAX FLUX DENSITY}$$

$$m = \text{MASS OF IRON}$$

### EDDY CURRENT LOSS



$$K_e = \text{CONSTANT}$$

& DI

$$f = \text{FREQUENCY}$$

$$t = \text{THICKNESS OF LAMINATIONS}$$

$$B = \text{MAX FLUX DENSITY}$$

$$V = \text{VOLUME OF IRON}$$



MACHINE

ED BY BEARING

ED BY ARMATURE

BRUSH FRICTION,

WINDAGE LOSS,

IRON

OF SUPPLY

TY

IRON

Hysteresis loss

$$P_h = K_h f B^{1.6} m \quad \text{WATT}$$

$K_h$  = CONSTANT DEPENDING ON MATERIALS & UNIT USED

$f$  = FREQUENCY OF SUPPLY

$B$  = MAXIMUM FLUX DENSITY OF SUPPLY (T)

$m$  = MASS OF CORE (Kg)

EDDY CURRENT  
LOSS

$$P_e = K_e f^2 t^2 B^2 V \quad \text{WATT}$$



$K_e$  = CONSTANT DEPENDS ON RESISTIVITY OF IRON & DIMENSION

$f$  = FREQUENCY (Hz)

$t$  = THICKNESS OF LAMINATION (m)


$B$  = MAXIMUM FLUX DENSITY IN CORE (T)

$V$  = VOLUME OF IRON CORE (m<sup>3</sup>)

COPPER LOSS

DC COMPOUND GENERATOR

SHORT SHUNT COMPOUND




$$I_a = I_{sh} + I_L$$

$$I_{sh} = \frac{V_t + I_L \times R_{se}}{R_{sh}}$$

$$\text{TOTAL COPPER LOSS} = I_a^2 R$$

LONG SHUNT COMPOUND





WATT

WATT

IALS & UNIT USED

SUPPLY (T)

$B^2 V$

WATT

RESISTIVITY OF IRON

ATION (m)


Y IN CORE (T)

(m<sup>3</sup>)

COPPER LOSS

DC COMPOUND GENERATOR

SHORT SHUNT COMPOUND




$$I_a = I_{sh} + I_L$$

$$I_{sh} = \frac{V_t + I_L \times R_{se}}{R_{sh}}$$

$$\text{TOTAL COPPER LOSS} = I_a^2 R_a + 2 I_a^2 R_b + I_{sh}^2 R_{sh} + I_L^2 R_{se}$$

LONG SHUNT COMPOUND



$$I_a = I_L + I_{sh}$$


$$I_{sh} = \frac{V_t}{R_{sh}}$$

UNARIABLE LOSS

TOTAL COPPER LOSS

DC Compound mo

SHORT SHUNT COMPOUND



$$I_{sh} = \frac{V_t}{R_{sh}}$$

$$I_a = I_L + I_{sh}$$

TOTAL COPPER LOSS

TOTAL LOSS


INPUT POWER

INPUT EMF



$$\text{TOTAL COPPER LOSS} = I_a^2 R_a + 2I_a^2 R_b + I_a^2 R_{se} + I_{sh}^2 R_{sh}$$

DC Compound motor




$$I_{sh} = \frac{V_t - I_L R_{se}}{R_{sh}}$$

$$I_a = I_L - I_{sh}$$

$$\text{TOTAL COPPER LOSS} = I_a^2 R_a + 2I_a^2 R_b + I_{sh}^2 R_{sh} + I_L^2 R_{se}$$

Long SHUNT Compound



$$I_{sh} = \frac{V_t}{R_{sh}}$$

$$I_a = I_L - I_{sh}$$

$$\text{TOTAL COPPER LOSS} = I_a^2 R_a + I_a^2 R_{se} + 2I_a^2 R_b + I_{sh}^2 R_{sh}$$

$$\text{TOTAL LOSSES} = \text{IRON LOSS} + \text{WINDAGE \& FRICTION LOSS} + \text{TOTAL COPPER LOSS}$$

$$\text{INPUT POWER (MECHANICAL POWER) GENERATOR} = \text{OUTPUT ELECTRICAL POWER} + \text{TOTAL LOSSES}$$

$$\text{INPUT ELECTRICAL POWER (MOTOR)} = \text{OUTPUT MECHANICAL POWER} + \text{TOTAL LOSSES}$$




pb THE WINDING RESISTANCE OF A 500V, 60KW DC SHUNT MOTOR ARE  $R_a = 0.2 \Omega$ ,  $R_f = 200 \Omega$

IF THE ROTATIONAL LOSSES CAN BE TAKEN AS 1.4 KW, DETERMINE THE EFFICIENCY OF THE MACHINE.

(a) WHEN THE LINE CURRENT IS 102.5 AMP

(b) AT FULL LOAD



(OUT PUT POWER = 60KW FULL LOAD.)

$$I_{sh} = \frac{V_t}{R_{sh}} = \frac{500}{200} = 2.5 \text{ Amp}$$

$$I_a = I_L - I_{sh}$$

$$= 102.5 - 2.5$$

$$= 100 \text{ Amp}$$

$$\begin{aligned} \text{TOTAL COPPER LOSS} &= I_a^2 R_a + I_{sh}^2 R_{sh} \\ &= 100^2 \times 0.2 + 2.5^2 \times 200 \\ &= 3250 \text{ W} \end{aligned}$$

$$\text{TOTAL LOSS} = \text{COPPER LOSS} + \text{IRON LOSS} / \text{FRICTION LOSS}$$

$$= 3250 + 1400$$

$$= 4650 \text{ W}$$

$$\text{INPUT POWER} = V_t I_L = 500 \times 102.5 =$$

$$\begin{aligned} \text{OUT PUT POWER} &= \text{INPUT} - \text{TOTAL LOSS} \\ &= 500 \times 102.5 - 4650 \end{aligned}$$

$$\text{Efficiency} = \frac{\text{OUT PUT POWER}}{\text{IN PUT POWER}} \times 100$$

$$= \frac{500 \times 102.5 - 4650}{500 \times 102.5} \times 100$$

$$= 90.93\%$$




pb THE WINDING RESISTANCE OF A 500V, 60KW DC SHUNT MOTOR ARE  $R_a = 0.2\Omega$ ,  $R_f = 200\Omega$

IF THE ROTATIONAL LOSSES CAN BE TAKEN AS 1.4KW, DETERMINE THE EFFICIENCY OF THE MACHINE.

(a) WHEN THE LINE CURRENT IS 102.5 AMP

(b) AT FULL LOAD



(OUT PUT POWER = 60KW FULL LOAD.)

$$I_{sh} = \frac{V_t}{R_{sh}} = \frac{500}{200} = 2.5 \text{ Amp}$$

$$I_a = I_L - I_{sh}$$

$$= 102.5 - 2.5$$

$$= 100 \text{ Amp.}$$

$$\begin{aligned} \text{TOTAL COPPER LOSS} &= I_a^2 R_a + I_{sh}^2 R_{sh} \\ &= 100^2 \times 0.2 + 2.5^2 \times 200 \\ &= 3250 \text{ W} \end{aligned}$$

$$\text{TOTAL LOSS} = \text{COPPER LOSS} + \text{IRON / FRICTION LOSS}$$

$$= 3250 + 1400$$

$$= 4650 \text{ W}$$

$$\text{INPUT POWER} = V_t I_L = 500 \times 102.5 =$$

$$\text{OUT PUT POWER} = \text{INPUT} - \text{TOTAL LOSS}$$


$$= 500 \times 102.5 - 4650$$

$$\text{Efficiency} = \frac{\text{OUT PUT POWER}}{\text{IN PUT POWER}} \times 100$$

$$= \frac{500 \times 102.5 - 4650}{500 \times 102.5} \times 100$$

$$= 90.93\%$$





Power OUT PUT ( $P_{OUT}$ ) = 60,000 WATT

$P_{OUT} = 60,000 \text{ W}$

$P_{OUT} + \text{IRON LOSS} + \text{FRICITION LOSS} + \text{COPPER LOSS} = \text{TOTAL POWER INPUT}$

$60,000 + 1400 + I_{sn}^2 R_{sh} + I_a^2 R_a = V I_L$

$61400 + (2.5)^2 \times 200 + (I_L + I_{sn})^2 \times 0.2 = 500 \times I_L$

$61400 + 6.25 \times 200 + (I_L + 2.5)^2 \times 0.2 = 500 I_L$

$62650 + (I_L^2 + 5I_L + 6.25) \times 0.2 = 500 I_L$

$(I_L + 2.5)^2$

$I_L + 2.5$   
 $I_L + 2.5$

$\frac{I_L^2 + 2.5I_L}{I_L^2 + 5I_L + 6.25}$

$62650 + 0.2I_L^2$

$0.2I_L^2 - 499.8I_L + 62650 = 0$

$Ax^2 + Bx + C = 0$

$x = \frac{-B \pm \sqrt{B^2 - 4AC}}{2A}$

$I_L = \frac{-B \pm \sqrt{B^2 - 4AC}}{2A}$

$I_L =$

$= 499.8$

$I_a = I_L$



$$62650 + 0.2 I_L^2 + 1 I_L + 1.25 = 500 I_L$$

$$0.2 I_L^2 - 499 I_L + 62651.25 = 0$$

$$Ax^2 + Bx + C = 0$$

$$x = \frac{-B \pm \sqrt{B^2 - 4AC}}{2A}$$

$$I_L = \frac{-(-499) \pm \sqrt{499^2 - 4 \times 0.2 \times 62651.25}}{2 \times 0.2}$$

$$\frac{499 \pm \sqrt{249001 - 50121}}{0.4}$$

$$I_L = \frac{499 \pm 445.95}{0.4}$$

$$= \frac{499 + 445.95}{0.4} \text{ (or) } \frac{499 - 445.95}{0.4}$$

$$= 2362 \text{ A (or) } 132.65 \text{ A} \checkmark$$

Impossible

$$I_a = I_L - I_{sh} = 132.65 - 2.5 = 130.15 \text{ Amp.}$$

$$\begin{aligned} \text{TOTAL COPPER LOSS} &= I_a^2 R_a + I_{sh}^2 R_{sh} \\ &= (130.15)^2 \times 0.2 + (2.5)^2 \times 200 \\ &= 4637 \text{ WATT.} \end{aligned}$$

$$\begin{aligned} \text{TOTAL IRON LOSS} &= 1400 \text{ WATT} \\ \text{ROTATIONAL LOSS} & \end{aligned}$$

$$\text{TOTAL LOSSES} = 4637 + 1400 = 6037 \text{ WATT}$$

$$\begin{aligned} \text{INPUT POWER} &= \text{OUTPUT POWER} + \text{TOTAL LOSSES} \\ &= 60,000 + 6037 \\ &= 66037 \text{ WATT} \end{aligned}$$


$$\begin{aligned} \text{EFFICIENCY} &= \frac{\text{OUTPUT POWER}}{\text{INPUT POWER}} \times 100 \\ &= \frac{60,000}{66037} \times 100 \\ &= 90.85\% \end{aligned}$$



## POWER FLOW DIAGRAM IN DC GENERATOR


$$P_{out} = V_t \times I$$

$$P_{in} = E_g I_a + \text{ROTATIONAL LOSSES}$$



$$\eta \% = \frac{\text{OUTPUT}}{\text{INPUT}} \times 100 = \left( 1 - \frac{\text{Power loss}}{P_{out} + P_{loss}} \right) \times 100$$

## POWER FLOW DIAGRAM






## Power Flow Diagram in DC Generator

$$P_{out} = V_t \times I$$

$$P_{in} = E_g I_a + \text{ROTATIONAL LOSSES}$$



$$\eta \% = \frac{P_{out}}{P_{in}} \times 100 = \left( 1 - \frac{P_{loss}}{P_{out} + P_{loss}} \right) \times 100$$

## Power Flow Diagram in DC Motor

