

Review questions

Small containers that have held flammable substances are extremely dangerous if they are welded or cut. List **three** of the flammable substances that are classified as dangerous.

- _____
- _____
- _____

List **two** treatments that will remove flammable substances from small containers.

- _____
- _____

ANSWERS TO REVIEW QUESTIONS

Section 1

1. To shield the weld from the atmosphere.
2. A continuous wire electrode.
3. Oxygen and acetylene.
4. (a) Gas tungsten arc welding.
(b) Light fabrication, general engineering.
5. Submerged arc welding.
6. (a) Resistance or spot welding.
(b) Light fabrication, vehicle or transport industries.
7. To keep the surface of the metal at the required ignition temperature (815°C).
8. (a) Plasma arc cutting.
(b) Any two of the following:
 - Stainless steel
 - aluminium
 - cast iron
 - alloy steels
 - carbon steels

Section 2

1. *Eyes* - protective goggles
Body - close-fitting work clothes
gloves
safety shoes
Ventilation - open, well ventilation area or forced air exhaust system
2. Any three of the following:
 - steel
 - copper
 - stainless steel
 - brass
3.
 - oxygen and acetylene
 - oxygen and LP gas
4. Lap joint.

5.
 - greater strength
 - greater cost
 - greater temperature

Section 4

1.
 - different joint preparations
 - filler metal
 - welding techniques
2.
 - copper
 - zinc
3. Cleaning the metal's surface during welding.
4.
 - copper
 - steel
 - cast iron
5. Any one of the following:
 - repairing machinery
 - maintenance work
 - leak-proof joints on small tanks
 - constructing furniture from hollow sections
6. Any two of the following *advantages*:
 - requires much less heat input
 - causes less distortion
 - joins a wide range of dissimilar metals including ferrous and non-ferrous

Any two of the following *disadvantages*:

 - high consumable costs
 - loss of strength at moderately high temperatures (above 260°C)
 - will corrode if in contact with ammonia
7. Any two of the following:
 - fumes
 - heat
 - poisonous fluxes

Section 6

1. Any four of the following:
 - welding tips
 - welding torch
 - regulators
 - gas cylinders
 - hoses
2.
 - (a) black
 - (b) crimson
3. Any two of the following:
 - light fabrication
 - repairs
 - farm machinery
 - general maintenance
4.
 - carburising
 - neutral
 - oxidising
5. By the flame covering the weld zone.
6. Any three of the following:
 - shade 5 or 6 lens - Australian Standards approved
 - a shirt and trousers of tough flame-resistant material
 - firm fitting leather shoes or boots
 - leather gloves
 - head covering

Section 10

1. 815°C
2.
 - release a high speed jet of oxygen on the heated section
 - by controlling the direction of the blowpipe nozzle and combining it with the oxidising action, cut through the metal
3. Any two of the following:
 - acetylene
 - coal gas
 - LP gas
 - hydrogen
4. Oxygen.

5.
 - grea
 - grea
 - grea

Section 4

- diffe
- filler
- weld

- copp
- zinc

Cleaning

- copp
- steel
- cast i

Any one o

- repair
- main
- leak-
- const

Any two o

- requir
- cause
- joins

Any two o

- high c
- loss o
- will c

Two of

- fumes
- heat
- poison

5. Any five of the following:

- overalls
- oxy-goggles
- leather gloves
- leather apron
- steel-capped boots
- spats

6. Type 41: acetylene taper seat
No. 12: nozzle size or ϕ 1.2 cutting jet hole


7. Nozzle size: 8
Acetylene: 100 kPa
Oxygen: 200 kPa

8.
 - metal composition
 - cutting nozzle size and condition
 - gas pressures
 - size of preheat flame
 - distance of nozzle from job

Section 12

1.
 - acetylene
 - LPG

2.



3.
 - (a) Higher.
 - (b) 813°
 - (c) 30°

Section 14

1.
 - flux coating
 - corewire

2. 6000° .

3. Any four of the following:

- adjustable helmet
- flame resistant overalls
- leather gloves
- safety boots
- safety glasses
- skull cap or hat

4.
 - rays - ultraviolet and infrared
 - Effects - damage to eyes and skin

5. Any three of the following:

- wear dry insulated boots
- wear dry leather gloves
- never change electrodes with bare hands or wet gloves
- never cool electrode holders by immersion in water
- work on a dry insulated floor where possible
- never hold the electrode and holder under your arm

Section 18

1. To stop contamination from the atmosphere.

2. Any three of the following:

- structural
- boilers and pressure vessels
- earth moving equipment
- light fabrication (sheet metal)
- general engineering

3. Eyes - head shield with correct lens shade
safety glasses

- Body - overalls
gloves
head covering (cap or hat)

- Feet - solid boots or shoes
spats

4.
 - natural ventilation
 - respirator
 - forced ventilation

5. Contact tip.

Section 22

1. Any three of the following:
 - alcohol distilleries
 - oil refineries
 - paint factories
 - explosives manufacturers
 - coal crushers
 - flour mills
 - plastics manufacturers
 - saw mills
 - wheat silos
 - clothing factories
 - paper mills
2. Obtain a work permit.
3. (a) A confined working space is a location with restricted ventilation and/or access.
(b) Any three of the following:
 - tanks and containers (road and rail tankers)
 - bins and silos (quarries, grain handlers, mines)
 - ship hull compartments
 - ducts and chutes
 - pipelines (large diameters)
4.
 - make sure there is adequate ventilation
 - have an assistant outside the location watching you work
 - have rescue apparatus on hand
 - leave gas cylinders outside the location in a well ventilated position
 - light blowpipes outside the location, wherever practicable, and remove them from the location when not in use
 - use low current electrical hand tools and lighting
5. Any three of the following:
 - petroleum products
 - acids
 - bitumen
 - flammable solids
6.
 - steaming
 - boiling

SAMPLE ASSESSMENT (THEORY)

Assessment event 10 (theory)

Suggested time: 1 hour

To pass this assessment event you must correctly answer 3 of the 5 questions in each part.

Tick the correct box.

Part 1

1. An inert shielding gas used in gas tungsten arc welding is:
 - ☐ oxygen
 - ☐ nitrogen
 - ☐ hydrogen
 - ☐ argon.
2. The welding process which uses a continuous electrode is:
 - ☐ manual metal arc welding
 - ☐ oxyacetylene welding
 - ☐ gas metal arc welding
 - ☐ gas tungsten arc welding.
3. Spot welding is used for:
 - ☐ light fabrication
 - ☐ heavy fabrication
 - ☐ bridge repair
 - ☐ flame cutting.
4. Manual metal arc welding uses:
 - ☐ shielding gas mixtures
 - ☐ flux covered electrodes
 - ☐ continuous bare wire electrodes
 - ☐ liquid flux.
5. The welding process which uses a loose flux mixture to protect the arc is:
 - ☐ oxyacetylene welding
 - ☐ manual metal arc welding
 - ☐ submerged arc welding
 - ☐ gas tungsten arc welding.

Sample assessment (theory)

Part 2

1. Brazing flux:
 - ☐ assists the filler metal to flow
 - ☐ cleans the joint surfaces
 - ☐ prevents oxides from forming while brazing
 - ☐ does all of the above.
2. A safety problem when brazing can be:
 - ☐ poor lighting
 - ☐ poor ventilation
 - ☐ a change from LPG to acetylene fuel gas
 - ☐ an attempt to join unlike metals.
3. When brazing, the molten filler metal is drawn between the close-fitting parts of a joint with:
 - ☐ gravitational pull
 - ☐ the creation of a vacuum
 - ☐ capillary action
 - ☐ the melting of the parts being joined.
4. Brazing is often used instead of soldering because it is:
 - ☐ stronger
 - ☐ cheaper
 - ☐ a lower temperature process
 - ☐ softer.
5. The major element in brazing filler metal is:
 - ☐ copper
 - ☐ tin
 - ☐ aluminium
 - ☐ iron.

Sample assessment (theory)

Part 3

1. The flame setting used for braze welding is:
 - ☐ neutral
 - ☐ slightly carburising
 - ☐ slightly oxidising.
2. A braze welded joint strength is achieved through:
 - ☐ the weld metal thickness
 - ☐ capillary action
 - ☐ the lower welding temperature
 - ☐ the thickness of the filler rod.
3. Braze welding is not suitable for:
 - ☐ welding steel
 - ☐ maintenance applications
 - ☐ service temperatures above 500°C
 - ☐ copper sheet less than 1.6 mm.
4. The element contained in a braze welding filler rod is:
 - ☐ iron
 - ☐ aluminium
 - ☐ lead
 - ☐ zinc.
5. The flux is added during the braze welding process by:
 - ☐ an inert gas
 - ☐ the filler rod
 - ☐ neither of the above because flux isn't needed.

Sample assessment (theory)

Part 4

1. The temperature of the oxyacetylene welding flame is approximately:
 - ☐ 1300°C
 - ☐ 2500°C
 - ☐ 3100°C
 - ☐ 3900°C.
2. With oxyacetylene welding:
 - ☐ the parts are melted and fused together
 - ☐ filler rods should *not* be used
 - ☐ only non-ferrous metals can be joined
 - ☐ an inert gas is used.
3. The colour of an oxygen cylinder is:
 - ☐ black
 - ☐ red
 - ☐ silver
 - ☐ green.
4. Oxyacetylene welding is often preferred to other welding processes because it:
 - ☐ welds faster
 - ☐ is more versatile
 - ☐ is easier to use
 - ☐ has no distortion problems.
5. The shade of the filters used for general oxyacetylene welding is:
 - ☐ 3
 - ☐ 5
 - ☐ 7
 - ☐ 10.

Part 7 (theory)

1. One function of the flux on an electrode is to:

- ☐ insulate the core wire
- ☐ form a protective

Sample assessment (theory)

Part 5

1. In oxy-fuel gas flame cutting, the *cutting* oxygen is needed to:
 - ☐ increase the flame temperature
 - ☐ reduce the metal's ignition temperature
 - ☐ oxidise the heated metal
 - ☐ keep the metal from overheating.
2. Conventional flame cutting requires a metal's oxide layer to:
 - ☐ melt below the melting point of the metal
 - ☐ melt above the melting point of the metal
 - ☐ be non-existent
 - ☐ melt at the same temperature as the metal.
3. The method that produces the most accurate and consistent flame cut surface is:
 - ☐ free hand cutting
 - ☐ guided cutting
 - ☐ machine guided cutting.
4. Flame cutting is unsuitable for:
 - ☐ low carbon steel
 - ☐ structural steel sections
 - ☐ brass
 - ☐ steel castings.
5. To successfully flame cut a metal, it must:
 - ☐ be heated above its melting point
 - ☐ have an ignition point above the melting point
 - ☐ be less than 50 mm thick
 - ☐ have a high iron content.

Sample assessment (theory)

Part 6

1. A common fuel gas used for flame gouging is:
 - ☐ hydrogen
 - ☐ oxygen
 - ☐ argon
 - ☐ acetylene.
2. Flame gouging is used on:
 - ☐ low carbon steel
 - ☐ stainless steel
 - ☐ non-ferrous metals
 - ☐ cast iron.
3. In comparison with fuel gas cutting, the gouging process relies upon a:
 - ☐ low velocity high volume oxygen stream
 - ☐ high velocity low volume oxygen stream
 - ☐ high velocity high volume oxygen stream
 - ☐ low velocity low volume oxygen stream.
4. The flame process is used extensively to:
 - ☐ prepare single bevel weld joints
 - ☐ pre-heat weld joints
 - ☐ remove defective welds
 - ☐ trim plate edges.
5. The angle of the gouging nozzle to the plate surface is normally:
 - ☐ 5°
 - ☐ 10°
 - ☐ 20°
 - ☐ 30°.

Sample assessment (theory)

Part 7

1. One function of the flux on an electrode is to:
 - ☐ insulate the core wire
 - ☐ form a protective slag
 - ☐ carry the electric current
 - ☐ reduce radiation.
2. An increase in welding current (amps) will:
 - ☐ make it more difficult to strike an arc
 - ☐ reduce welding speed
 - ☐ cause the electrode to stick
 - ☐ increase the melting rate of the electrode.
3. Welders should:
 - ☐ inspect all cables for damage
 - ☐ always have good ventilation
 - ☐ wear safety glasses
 - ☐ do all of the above.
4. The temperature of the electric arc in manual metal arc welding is approximately:
 - ☐ 160°C
 - ☐ 800°C
 - ☐ 2400°C
 - ☐ 6000°C.
5. Manual metal arc welding:
 - ☐ is used for welding low carbon steel
 - ☐ is used for welding aluminium
 - ☐ can be used as a fully automatic process
 - ☐ uses a continuous electrode.

Sample assessment (theory)

Part 8

1. Gas metal arc welding:

- ☐ is completely manually controlled
- ☐ uses a tungsten electrode
- ☐ uses a flammable gas shield
- ☐ is a semi-automatic process.

2. The welding current in gas metal arc welding is supplied to the electrode by the:

- ☐ feed rolls
- ☐ wire spool
- ☐ work
- ☐ contact tip.

3. Excessive fumes generated by gas metal arc welding:

- ☐ are not harmful
- ☐ will contaminate the weld
- ☐ will require fume extraction
- ☐ contain flammable gases.

4. The shielding gas mixture used for gas metal arc welding low carbon steel is:

- ☐ oxygen/nitrogen
- ☐ nitrogen/acetylene
- ☐ acetylene/oxygen
- ☐ argon/CO₂.

5. The electrode (wire) diameter range used for gas metal arc welding is:

- ☐ 0.3 to 1.0 mm
- ☐ 0.6 to 1.6 mm
- ☐ 1.0 to 3.0 mm
- ☐ 1.6 to 6.0 mm.

4. Is more versatile.

Sample assessment (theory)

Part 9

1. When working in a confined space, the electrical equipment must be:

- ☐ low voltage
- ☐ high voltage
- ☐ high amperage
- ☐ low resistance.

2. When welding is required at a saw mill:

- ☐ fireproof gloves must be worn
- ☐ all timber must be removed
- ☐ the area is classed as a hazardous location
- ☐ an assistant is required.

3. When working in a confined space:

- ☐ an assistant is required
- ☐ milk must be consumed to overcome fumes
- ☐ table salt must be available
- ☐ gas cylinders should be inside.

4. Before attempting to work in a hazardous location you must:

- ☐ work with a mate
- ☐ isolate the power
- ☐ obtain a work permit
- ☐ work only at weekend.

5. Which one of the following is a confined space?

- ☐ fabrication workshop
- ☐ building site
- ☐ ship
- ☐ foundry.

Answers to sample assessment (theory)

Part 1

1. Argon.
2. Gas metal arc welding.
3. Light fabrication.
4. Flux covered electrodes.
5. Submerged arc welding.

Part 2

1. Does all of the above.
2. Poor ventilation.
3. Capillary action.
4. Stronger.
5. Copper.

Part 3

1. Slightly oxidising.
2. The weld metal thickness.
3. Service temperatures above 500°C.
4. Zinc.
5. The filler rod.

Part 4

1. 3100°C.
2. The parts are melted and fused together.
3. Black.

4. Is more versatile.

5. 5.

Part 5

1. Oxidise the heated metal.
2. Melt below the melting point of the metal.
3. Machine guided cutting.
4. Brass.
5. Have a high iron content.

Part 6

1. Acetylene.
2. Low carbon steel.
3. Low velocity high volume oxygen stream.
4. Remove defective welds.
5. 30°.

Part 7

1. Form a protective slag.
2. Increase the melting rate of the electrode.
3. Do all of the above.
4. 6000°C.
5. Is used for welding low carbon steel.

Part 8

1. Is a semi-automatic process.
2. Contact tip.
3. Fume extraction.

Argon/CO₂

0.6 to 1.6 mm

art 9

Low voltage.

The area is classed as a hazardous location.

An assistant is required.

Obtain a work permit.

Ship.

TERMS AND DEFINITIONS

∅	the symbol for diameter
acetone	a flammable and volatile liquid used as a solvent to dissolve and stabilise acetylene under pressure
acetylene	a highly combustible gas composed of carbon and hydrogen (C ₂ H ₂) and used as a fuel gas in oxyacetylene welding and cutting
alloy	a mixture of two or more metals in solid solution
arc	an electric current crossing a gap between an electrode and the work
automatic welding	welding in which the means of making the weld are controlled by a machine
backfire	a loud popping noise caused when the blowpipe flame goes out suddenly and re-lights from the hot work
backhand welding	(rightward, backward) welding with the blowpipe flame pointing in the opposite direction to that in which the weld progresses - the opposite of forehand welding
backing strip	material (such as metal, carbon) used to support and protect the root of a butt weld
blowhole	a cavity in the weld metal caused by a bubble of gas becoming trapped in the solidifying metal
blowpipe (torch)	the hand held device used to mix the fuel gas and oxygen, control the flame and direct it to where it's required
bonding	the joining of two or more metals
brazing	a welding process in which the parent metal isn't melted, but the joint design is similar to fusion welding - the filler metal is a non-ferrous alloy with a melting point lower than that of the metal being joined.
brazing	a joining process more like soldering than welding in which the molten filler metal is drawn by capillary action between two closely adjacent surfaces to be joined - the filler metal is a non-ferrous metal or alloy with a melting point lower than that of the metal being joined

4.	capillary action	the flow of molten filler metal between the properly fitted surfaces of the joint
5.	celsius (C)	a temperature scale that registers the freezing point of water as 0°C and the boiling point as 100°C under normal atmospheric pressure
Part 1		
1. 1	clear lens	a clear glass used to protect the filter in goggles and welding helmets
2. T	combustion	the process of burning
3. A1	conduction	the transmission of electric current or heat through a medium
Ob	consumable	material that is used for making welds eg electrodes, filler metals, fluxes, gases
Ship	cutting attachment	an attachment to a welding torch handle which converts it to a cutting torch
	cutting torch	equipment used in oxygen-fuel gas cutting designed to control the gases for preheating and the oxygen for cutting
	cutting oxygen	the jet of oxygen from the central opening of the cutting nozzle which oxidises the preheated metal and allows the cutting action to take place
	de-oxidising	the process of removing oxygen particularly from the weld area
	deposition rate	the volume of metal deposited in a specified time
	diameter	the distance from one side of a circle to the other measured through the centre of the circle
	downhand welding	see flat position
	ductility	the ability to be permanently bent or deformed without fracture
	ferrous	a metal that contains iron
	filter (lens)	a coloured lens, usually made of glass, designed to protect a welder's eyes from glare and harmful radiation
	flashback	the burning back of the flame into the torch or into one of the gas lines

flat position	welding from above the joint when the weld face is nearly horizontal
flux	a chemical powder or paste which dissolves oxides, cleans the metal and prevents further oxidation during welding
flux inclusion	a cavity in the weld metal containing flux caused by a quantity of flux becoming trapped as the metal hardens
forehand welding	(leftward, forward) welding with the blowpipe flame pointing in the direction of the weld, that is towards the unfinished seam - the opposite of backhand welding
freehand flame cutting	the cutting process in which the operator both holds and guides the hand cutting torch
fusion weld	a joining of pieces of metal at faces made plastic or liquid by heat pressure or both - filler metal may be used
hazardous locations	the meaning of the term "hazardous locations" is specific and additional to general OH&S issues related to welding & thermal cutting in the workshop. For a full definition of the term, refer to Australian Standard AS 1674 Part 1
horizontal welding	welding in a position in which the line of the weld is horizontal but the surface of the work is vertical
ignition temperature	the temperature at which a material will ignite (burn) eg. 815°C for iron
kerf	the space left during flame cutting by the removal of metal
manual	working by hand
non-ferrous	a metal that does not contain iron
overhead welding	welding in which the filler metal is deposited from the underside of the joint and the face of the weld is approximately horizontal
oxide	a compound of oxygen with another element or substance - rust and mill scale are examples of iron oxides
oxidisation	the process of forming an oxide eg. a section of rusting steel
oxygen	a colourless and odourless gas which supports combustion - oxygen makes up about one-fifth of the atmosphere
parent metal	the metal parts being welded

	capillary action	the flow of molten filler metal between the properly fitted surfaces of the joint
	celsius (C)	a temperature scale that registers the freezing point of water as 0°C and the boiling point as 100°C under normal atmospheric pressure
	clear lens	a clear glass used to protect the filter in goggles and welding helmets
3	combustion	the process of burning
4	conduction	the transmission of electric current or heat through a medium
5	consumable	material that is used for making welds eg electrodes, filler metals, fluxes, gases
	cutting attachment	an attachment to a welding torch handle which converts it to a cutting torch
	cutting torch	equipment used in oxygen-fuel gas cutting designed to control the gases for preheating and the oxygen for cutting
	cutting oxygen	the jet of oxygen from the central opening of the cutting nozzle which oxidises the preheated metal and allows the cutting action to take place
	de-oxidising	the process of removing oxygen particularly from the weld area
	deposition rate	the volume of metal deposited in a specified time
	diameter	the distance from one side of a circle to the other measured through the centre of the circle
	downhand welding	see flat position
	ductility	the ability to be permanently bent or deformed without fracture
	ferrous	a metal that contains iron
	filter (lens)	a coloured lens, usually made of glass, designed to protect a welder's eyes from glare and harmful radiation
	flashback	the burning back of the flame into the torch or into one of the gas lines

	flat position	welding from above the joint when the weld face is nearly horizontal
	flux	a chemical powder or paste which dissolves oxides, cleans the metal and prevents further oxidation during welding
	flux inclusion	a cavity in the weld metal containing flux caused by a quantity of flux becoming trapped as the metal hardens
	forehand welding	(leftward, forward) welding with the blowpipe flame pointing in the direction of the weld, that is towards the unfinished seam - the opposite of backhand welding
	freehand flame cutting	the cutting process in which the operator both holds and guides the hand cutting torch
	fusion weld	a joining of pieces of metal at faces made plastic or liquid by heat pressure or both - filler metal may be used
	hazardous locations	the meaning of the term "hazardous locations" is specific and additional to general OH&S issues related to welding & thermal cutting in the workshop. For a full definition of the term, refer to Australian Standard AS 1674 Part 1
	horizontal welding	welding in a position in which the line of the weld is horizontal but the surface of the work is vertical
	ignition temperature	the temperature at which a material will ignite (burn) eg. 815°C for iron
	kerf	the space left during flame cutting by the removal of metal
	manual	working by hand
	non-ferrous	a metal that does not contain iron
	overhead welding	welding in which the filler metal is deposited from the underside of the joint and the face of the weld is approximately horizontal
	oxide	a compound of oxygen with another element or substance - rust and mill scale are examples of iron oxides
	oxidisation	the process of forming an oxide eg. a section of rusting steel
	oxygen	a colourless and odourless gas which supports combustion - oxygen makes up about one-fifth of the atmosphere
	parent metal	the metal parts being welding

portability	able to be moved easily
preheat	heat applied before welding or cutting begin - used to prevent distortion, cracking and unwanted hardening
radiation	the transfer of heat through space by wave motion - all bodies that are at a higher temperature than their surroundings radiate heat
semi-automatic welding	welding in which some of the welding variables are automatically controlled but manual guidance is also necessary
shielding	a process in which gases produced during welding exclude the harmful elements in the atmosphere
slag	a fused, non-metallic residue produced from some welding processes
slag inclusion	non-metallic material trapped in a weld
tack weld	a short weld used for assembly purposes only
tip	the generally detachable part of a blowpipe from which gas or gases emerge for welding
toxic	poisonous
vertical welding	welding in a position in which the axis of the weld is almost vertical
volatile	evaporating rapidly
weld pool	the metal pool created while making the weld - it can consist of filler metal, plate material or a mixture of both
weld contamination	the oxidation of the weld pool or the generation of gas from organic materials which cause weakening of the weld.
weld metal	metal in a welded joint which has been melted in making the weld - the weld metal includes the filler and parent metals

NSW Module Resource Manual for the National Metal and Engineering Courses

NF03
Gas Tungsten Arc
Welding 1

Student Workbook

Fabrication
Stream



Contents

Introduction	_____	3
Student organiser	_____	6
Section 1	Gas tungsten arc welding - process and hazards	7
The process	_____	8
Equipment	_____	9
Assembling equipment	_____	12
Uses	_____	14
Advantages	_____	14
Limitations	_____	15
Health and safety hazards	_____	16
Review questions	_____	17
Section 2	Lines of fusion and stringer beads - steel sheet - flat	19
Procedure sheet	_____	20
Work sheet	_____	21
Section 3	Butt weld - stainless steel sheet - flat (temporary backing)	23
Procedure sheet	_____	24
Work sheet	_____	25
Section 4	Butt weld - steel tube - flat (rotated)	27
Procedure sheet	_____	28
Work sheet	_____	29
Section 5	Power sources, polarity and tungsten electrodes	31
Power process	_____	32
Polarity/current	_____	33
Tungsten electrodes	_____	36
Electrode preparation	_____	37
Review questions	_____	39
Section 6	Gases and filler rods	41
Shielding gases and their uses	_____	41
Cylinder colour code	_____	42
Regulators and flow-meters	_____	43
Filler rods	_____	44
Review questions	_____	45
	_____	46


ion 7	Corner fillet weld - stainless steel sheet - flat	49
	Procedure sheet	50
	Work sheet	51
ion 8	Fillet weld - stainless steel sheet - horizontal	53
	Procedure sheet	54
	Work sheet	55
on 9	Gas tungsten arc weld faults	57
	Gas tungsten arc weld faults	58
	Review questions	61
n 10	Stringer beads - aluminium steel sheet - flat	63
	Procedure sheet	64
	Work sheet	65
n 11	Butt weld - aluminium steel sheet - flat (temporary backing)	67
	Procedure sheet	68
	Work sheet	69
12	Corner fillet weld - aluminium steel sheet - flat	71
	Procedure sheet	72
	Work sheet	73
13	Fillet weld - aluminium steel sheet - horizontal	75
	Procedure sheet	76
	Work sheet	77
o review questions		79
need to know		83

Introduction

NF03 - Gas Tungsten Arc Welding (GTAW1) is the first of a series of three modules on this process.

The flow chart shows where **Gas Tungsten Arc Welding** fits into the Metals and Engineering course.

Before enrolling in **NF71 - Welding Certificate 7**, students must meet the prerequisites in Australian Standard **AS1796**.



Gas Tungsten Arc Welding 1 contains thirteen sections designed to give you:

- an understanding of the principles of this process and the hazards of using it
- the knowledge to choose appropriate welding parameters, tungsten electrodes, shielding gases and filler rods for welding ferrous and non-ferrous materials
- a description of typical gas tungsten arc welding faults and the steps to take to correct them
- the knowledge to assemble gas tungsten arc welding equipment safely and competently
- practice in depositing fillet and butt welds on low carbon steel, stainless steel and aluminium sections.

You must reach the specified competency in each related section before moving on to the next.

In this workbook you will find:

- a student organiser allocating time for each section
- background theory notes on the gas tungsten arc welding process
- review questions at the end of each theory section to help you revise what you've learnt
- work and procedure sheets for practical exercises
- answers to review questions
- a page for your comments about the module.

Remember your teacher is there to help you with any part of the module you don't understand.

Review questions

The **review questions** will help you summarise what you're learning and revise the important points in each section. They're not tests or exams so your teacher won't be marking them. The answers are at the back of this workbook.

Words you need to know

You will also find a list of special words and phrases used in this module at the end of this workbook. There is space for you to add the meanings of new or unfamiliar terms.

Safety

Working safely is an essential requirement for workers in the metal industries. It's expected that you will follow all the safety procedures you've learnt from your experience in working in a welding and metal fabrication workshop.

To pass

At the end of most **practical sessions** you'll be assessed on what you've done. **Skill practice exercises** won't be formally assessed but you must make sure you're up to the specified standard for each of these. Your results for practical exercises will be shown by your teacher on your procedure sheets.

At the end of the module you'll do a **written competency test** on the theory sections.

To pass this module you must pass all the formal competency tests.

- If you are assessed by your teacher as having difficulty in reaching levels of practical competency or understanding theoretical concepts, you will then have access to Metals Tutorial Support.
- If you fail to complete a module within a twelve month period of the expected completion date you will be asked to explain why your enrolment in that module should continue.

Learning outcomes for Gas Tungsten Arc Welding 1 as stated in the National Module Descriptor


1. Describe the safety hazards involved in gas tungsten arc welding.
2. Correctly assemble gas tungsten arc welding equipment.
3. Explain the gas tungsten arc welding process.
4. Select the electrodes, gases and accessories appropriate for a particular gas tungsten arc welding task.
5. Deposit welds on low carbon steel/stainless steel and aluminium.
6. Diagnose and rectify common faults in gas tungsten arc welding equipment.
7. Perform visual inspection of weld samples.

Student organiser

This chart gives you an overall picture of the content of this module. It's a record of your progress as you work through each section.

	Section	Suggested hours	Assessed
1	Gas tungsten arc welding - process and hazards	2	
2	Lines of fusion and stringer beads - sheet steel - flat	4	
3	Butt weld - stainless steel sheet - flat (temporary backing)	3	
4	Butt weld - steel tube - flat (rotated)	3	
5	Power sources, polarity and tungsten electrodes	2	
6	Gases and filler rods	1	
7	Corner fillet weld - stainless steel sheet - flat	3	
8	Fillet weld - stainless steel sheet - horizontal	3	
9	Gas tungsten arc weld faults	1	
10	Stringer beads - aluminium sheet - flat	3	
11	Butt weld - aluminium sheet - flat (temporary backing)	3	
12	Corner fillet - aluminium sheet - flat	3	
13	Fillet weld - aluminium sheet - horizontal	4	
	Competency test	1	

Total 36 hours



Theory sections - written assessment

Skill practice section - no assessment

Skill competency section - practical assessment

Section 1

Gas tungsten arc welding - process and hazards

Task

To understand how gas tungsten arc welding works and the hazards of the process.

This section covers learning outcomes 1, 2 and part of 3 of the National Module Descriptor.

Why

So you will be able to use this process safely and competently.

To pass

At the end of the module you will do a competency test on this topic. This consists of multiple choice and short answer questions.



Safety


- Always wear protective clothing.
- Never leave hot metal objects unattended around the workshop.
- Read and learn the safety notes on pages 14 and 15 of this section.

The process

Gas tungsten arc welding (also called TIG welding - tungsten inert gas) was developed during World War II as a better, faster method of welding corrosion resistant and difficult-to-weld metals such as aluminium, magnesium and their alloys. Gas tungsten arc welding is now used for a variety of jobs ranging from general maintenance to extremely critical metal joining in aerospace programs.

Gas tungsten arc welding is an extension of the basic electric arc welding process (manual metal arc welding).

Gas refers to the shielding material which surrounds the arc and molten pool.
Tungsten is the non-consumable electrode which conducts the electric current to the arc.
Arc indicates the welding is done by an electric arc rather than by gas combustion.




Gas tungsten arc is an electric arc process. The heat is produced by drawing an arc between a non-consumable tungsten electrode and the work (parent material). The weld zone, molten weld pool and electrode are shielded from atmospheric contamination. This inert gas shield is concentrated around the area of the arc by a ceramic gas nozzle. Filler material may or may not be used.

Temperatures in the arc area reach 10,000°C and higher depending on the gas shielding mixture. You will learn more about gas shielding mixtures in **Section 6**.

Equipment


The basic components for the gas tungsten arc welding process are:

- power source
- torch with lead/gas hose
- work return lead/clamp
- gas cylinder
- regulator
- flow-meter
- tungsten electrode
- filler rod (if needed)



Power source attachments

- pulse unit used for greater control of bead shape and penetration
- foot control allows the operator to vary the amperage without adjusting the power source
- remote control hand operated control to vary amperage or adjust pulse

gas tungsten arc welding torch

- | | |
|---------------------|-------------------------|
| 1. Torch body | 7. Gas diffuser |
| 2. Handle | 8. O ring |
| 3. Long black cap | 9. O ring |
| 4. Medium black cap | 10. Power cable adaptor |
| 5. Short black cap | 11. Accessory kit |
| 6. Collet | |

Photograph courtesy of Ceramic Nozzles Inc.

Gas tungsten arc welding torches

There are a large number of gas tungsten arc welding torches available: pencil types which allow access to hard-to-reach weld areas, torches with flexible heads and water cooled torches.


Torches are rated on their current carrying capacity:

- | | |
|--------------|--------------|
| air cooled | 2 - 200 amps |
| water cooled | 2 - 500 amps |

Gas hoods

- ceramic (alumina or silicon carbide)
- fused quartz transparent type
- metal (generally water cooled)

Hoods come in various shapes and sizes to suit different metals and applications. Ceramic hoods are by far the most common but they become brittle in use and have to be replaced from time to time. Small mesh screens are available to fit gas hoods for very smooth gas flow.

Range of ceramic hoods

Photograph courtesy of Ceramic Nozzles Inc.

Collets

Collets are used to determine the length the electrode protrudes and to carry current. The collet size must suite the electrode diameter.

**Gas diffuser**

A gas diffuser is used to deliver gas evenly around the electrode.



General purpose gas tungsten arc welding plant



Photograph courtesy CIG

Assembling equipment

To assemble a gas tungsten arc plant for welding:


1. Connect the torch lead (electrode lead) and work return lead to the correct terminals on the power source and tighten securely.

On alternating current (AC) power sources the terminals are marked **work/electrode**. On direct current (DC) power sources, the torch lead is attached to the **negative(-)** terminals and the work return lead to the **positive (+)** terminal.

2. Open the cylinder valve momentarily to blow out any dust or moisture which may be in the gas seating valve.

3. Screw the regulator into the cylinder valve and tighten. Attach the flow-meter to the outlet on the regulator and tighten.
4. Connect the gas hose from the torch to the flow-meter and tighten.
5. Now check all connections with a soapy water solution. If there are no gas leaks, re-open the cylinder valve and set the flow-meter at the required flow rate (five to ten litres per minute is recommended).
6. Check the tungsten electrode is the correct type for the metal being welded and that it is tight in the collet.
7. Attach the work return lead clamp to the base metal to be welded.
8. Switch on the power source.
9. Set the amperage for the job and begin welding.

Blow out the cylinder valve socket before connecting regulator, **cracking-open** the cylinder valve momentarily.



Use correct key to avoid unnecessary strain on the valve.

Uses

Some of the uses of gas tungsten arc welding include:

- welding thin metal sections
- welding pipe, tube and hollow sections
- welding ferrous and non-ferrous materials.

Because the process uses small diameter electrodes on low currents, a high concentrated, controlled arc is produced. This means thin materials can be easily welded.

Pipes and tube and hollow sections in a range of diameters, wall thickness and sizes are often welded. Some uses include:

- butt welds on pipe lines
- welding tubular frames for helicopters and aircraft
- motor cycle frames.

A wide range of ferrous and non-ferrous metals can be welded in all positions by this process. Industrial materials welded include:

- carbon and low alloy steels
- stainless steel and high alloy steels
- aluminium and magnesium alloys (light metals)
- copper and copper alloys
- nickel and nickel alloys
- titanium and other exotic materials.

Advantages

The gas tungsten arc welding process has a number of advantages over other forms of welding. The main ones are:

- the concentrated arc characteristics produce less distortion
- the process produces little if any smoke or fumes
- no slag or fluxes are present before or after welding
- no sparks and spatter are generated from the weld
- the process is suitable for welding many different materials.

Concentrated arc

The concentrated arc allows pinpoint control of heat. The heat affected zone (HAZ) is narrow and there is less distortion of the workpiece.

Because of the concentrated open arc, and harmful rays there are special safety precautions with the process. There is more information on these at the end of this section. Learn the precautions carefully and take note of what they say. Your health and safety and that of others working with you could depend on it.

Absence of smoke and fumes

Smoke and fumes are not produced by the gas tungsten arc process unless the metal contains coatings or elements such as lead or zinc. If the metal is contaminated by oil, grease, paint or other contaminants, smoke and fumes will be produced by the heat of the arc.

No flux or slag

As flux is not required for shielding the arc, there is no slag to obstruct the operator's view of the molten pool or to remove between runs in multi-pass welds.

No sparks and spatter

Unlike most other electric arc processes, the gas tungsten arc process doesn't have to transfer metal across the arc because it's added by a filler rod. This process is generally spark and spatter free.

Welding range

The process is capable of welding a wide range of ferrous and non-ferrous materials from everyday steel to exotic and highly expensive materials used for aerospace, nuclear and scientific research.

Limitations

There are a number of limitations with gas tungsten arc process. They include:

Loss of gas cover

The gas cover is affected by the slightest breeze and the process is not used in the field (site work) unless it's properly screened. Inside a factory, the equipment should not be set up too close to open doors or windows.

Slow welding speeds

Gas tungsten arc is a slow welding process but this is overcome to a degree by using mixed gases, or adapting to automatic travel.

Weld area needs thorough cleaning

The weld area needs to be cleaned well before beginning to weld, especially on aluminium, magnesium and nickel as these metals are affected by contaminants much more than ferrous metals.

Not recommended for welding very thick material

Gas tungsten arc welding is slow and uneconomical compared with some other processes such as gas metal arc welding or manual metal arc welding. The gas tungsten arc process isn't generally used for welding material thicker than 6mm.

Health and safety hazards

Because the gas tungsten arc welding process has a highly concentrated arc there are safety precautions which need to be strictly observed for the welding operator's, and other workers' health and wellbeing. Some of the hazards are:

- arc radiation
- electric shock/high frequency
- asphyxiation when working in confined spaces.

Arc radiation

The gas tungsten arc welding process gives off:

- ultraviolet rays
- infrared rays
- brightness (glare)

The rays of the concentrated arc can quickly **burn** unprotected skin. Protect your eyes with welding helmets fitted with the correct shade lenses. Protect other workers in the area from stray glare and arc flashes by screening your work.

Electric shock

Electric shock can be quite severe with all welding processes but with gas tungsten arc it is effectively increased by the **high frequency (HF)** which is used for a **non-touch** start. There is more information on high frequency in **Section 5**.

Asphyxiation

Welding in confined spaces (such as inside tanks, boilers and containers) produces high levels of ozone, nitrous oxide and other gases which can cause asphyxiation. These areas must be properly ventilated.

Review questions

These questions will help you revise what you've learnt in **Section 1**. The answers are on page 79. Remember your teacher will also help you with anything you haven't understood so far.

Multiple choice questions

Choose the correct answer and write the letter **a, b, c** or **d** in the box.

1. The piece of equipment for controlling the welding current when gas tungsten arc welding is the:

a. tungsten electrode

b. power source

c. filler wire

d. gas cylinder

2. Gas tungsten arc welding is **not** recommended for use on:

a. thin metal sections

b. tubes and pipe

c. non-ferrous metals

d. thick plate

3. Which of the following joints can be welded with the gas tungsten arc process?

a. butt joint

b. lap joint

c. corner joint

d. all of the above

4. Which of the following metals is not normally welded with the gas tungsten arc process?

a. tungsten

b. low carbon steel

c. copper

d. stainless steel

5. Non-consumable electrodes used for welding with this process are made from:

a. magnesium

b. zinc

c. stainless steel

d. tungsten

Short answer questions

6. When assembling a gas tungsten arc welding plant on direct current (DC), to which terminal is the electrode lead connected?
- _____

7. The gas tungsten arc process has advantages over other welding processes. List **three** of these advantages:

- _____
- _____
- _____

8. List **two** limitations of the gas tungsten arc process:

- _____
- _____

Fill in the missing words in the following:

9. Gas refers to the _____ materials which surrounds the arc and molten pool.
10. _____ is the non-consumable _____ which conducts the electric current to the arc.
11. Arc indicates the _____ is done by an electric arc rather than by gas combustion.

Section 2

Lines of fusion and stringer beads - steel sheet - flat

Task

To produce lines of fusion and deposit stringer beads on low carbon steel sheet in the flat position.

This section covers part of learning outcome 5 of the National Module Descriptor.


Why

To develop the necessary manipulative skills to join a range of weld joint preparations.

To pass

Section 2 is a skill practice exercise which is not assessed as part of this module. However, you should make every effort to reach the standard required. The skills you learn in this section are used later for exercises that are formally assessed.

DANGER



Safety

- Learn all the OH&S requirements for the gas tungsten arc process and make sure you follow them.
- Never use trichlorethylene for cleaning or degreasing weld surfaces. It gives off highly poisonous gases when heated.
- Always wear approved face and eye protection.
- Never play practical jokes when using electrical equipment.

PROCEDURE SHEET

Section 2 Lines of fusion and stringer beads - steel sheet - flat



Welding data:

Machine brand

Type of current:

Type of electrode:

Electrode size: Ø

Electrode profile

Type of shielding gas:

Flow rate l/min:

Type of filler rod:

Size of filler rod: Ø

Weld current data

Run:

1 amps 3 amps

2 amps 4 amps

Material data

Type: Classification:

Thickness:

Surface cleaning:

Pre heat temperature:

Ceramic hood size:

Assessment

Complies

Doesn't comply

Correct assembly of equipment

Complete fusion

Smooth regular appearance

Surface defects

Name:

IF IN DOUBT ASK YOUR TEACHER

To develop the gas tungsten arc welding manipulative skills for welding different types of joints.

Flat

Your teacher will demonstrate.

1. Thoroughly clean weld surface and degrease if necessary.

2. Position sheet on support surface.

3. Complete bead exercise and show your work to your teacher.

4. Repeat exercise for further practice. Show your completed job for assessment.

5. Complete your procedure sheet.

REQUIREMENTS

- complete fusion of the parent metal
- smooth regular appearance
- beads to have no surface defects


2 pieces 75 x 3 x 225mm low carbon steel sheet

2


Return unused material and filler rods to the store.

Turn off the shielding gas when you're not using it.

Students will be assessed on the correct assembly of equipment.

Section 2 Lines of fusion stringer beads
(Skill practice - no formal assessment)

Section 2 Lines of fusion stringer beads (Skill practice - no formal assessment)



IF IN DOUBT ASK YOUR TEACHER	
OBJECTIVE	To develop the gas tungsten arc welding manipulative skills for welding different types of joints.
POSITION	Flat
PROCEDURE	Your teacher will demonstrate.
METHOD	<ol style="list-style-type: none"> 1. Thoroughly clean weld surface and degrease if necessary. 2. Position sheet on support surface. 3. Complete bead exercise and show your work to your teacher. 4. Repeat exercise for further practice. Show your completed job for assessment. 5. Complete your procedure sheet.
REQUIREMENTS	<ul style="list-style-type: none"> ■ complete fusion of the parent metal ■ smooth regular appearance ■ beads to have no surface defects
MATERIAL	2 pieces 75 x 3 x 225mm low carbon steel sheet
UNITS	2
ECONOMY	Return unused material and filler rods to the store. Turn off the shielding gas when you're not using it.
Note	Students will be assessed on the correct assembly of equipment.



Photograph courtesy CIG

Gas tungsten arc welding

Section 3

Butt weld - stainless steel sheet - flat (temporary backing)

Task

To deposit single run butt welds on carbon and stainless steel sheet in the flat position.

This section covers part of learning outcome 5 of the National Module Descriptor.

Why

So you will be able to competently weld stainless steel sections together in the flat position as required by industry.

To pass

You will need to complete a single run butt joint on stainless steel sheet in the flat position to the requirements on the work sheet.




Safety

- Learn all the OH&S requirements for the gas tungsten arc process and make sure you follow them.
- Always use approved workshop safety practices.
- Always make sure you have enough ventilation.
- Check your equipment before you use it.

PROCEDURE SHEET

Section 3 Butt weld - stainless steel sheet - flat (temporary backing)



Welding data:

Machine brand

Type of current:

Type of electrode:

Electrode size: Ø

Electrode profile

Type of shielding gas:

Flow rate l/min:

Type of filler rod:

Size of filler rod: Ø

Weld current data

Run:

1 amps 3 amps

2 amps 4 amps

Material data

Type:

Classification:

Thickness:

Surface cleaning:

Pre heat temperature:

Ceramic hood size:

Assessment

Complies

Doesn't comply

Correct alignment, assembly and tacking

Smooth regular contour

Angular distortion

Weld penetration

Weld defects

me:

Section 3 Butt weld stainless steel sheet - flat (temporary backing)
(Formal assessment to pass)

IF IN DOUBT ASK YOUR TEACHER

To deposit a single run butt, weld on 1 to 1.6mm stainless steel using a temporary backing bar.

Flat

Your teacher will demonstrate.



1. Thoroughly clean weld surface and degrease if necessary.
2. Assemble and securely tack weld the workpiece.
3. Dress tack welds.
4. Complete welding exercise and show your work to your teacher.
5. Cut and relocate for further practice.
6. Repeat exercise and show your completed job for assessment.
7. Complete your procedure sheet.

REQUIREMENTS

- correct alignment, assembly and tacking of the job
- smooth regular weld contour
- angular distortion 0° to 5°
- penetration to be no less than 20% of the total weld length
- to have no more than 2 significant defects per 150mm of weld length with an accumulated defect area of less than 4 times the square of the material thickness.



MATERIAL
UNITS4 pieces 75 x 1 to 1.6 x 150mm stainless steel sheet
2

ECONOMY

Return unused material and filler rods to the store.
Turn off the shielding gas when you're not using it.

tacks at 25mm pitch

Section 3 Butt weld stainless steel sheet - flat (temporary backing) (Formal assessment to pass)



IF IN DOUBT ASK YOUR TEACHER

OBJECTIVE

To deposit a single run butt, weld on 1 to 1.6mm stainless steel using a temporary backing bar.

POSITION

Flat

PROCEDURE

Your teacher will demonstrate.

METHOD

1. Thoroughly clean weld surface and degrease if necessary.
2. Assemble and securely tack weld the workpiece.
3. Dress tack welds.
4. Complete welding exercise and show your work to your teacher.
5. Cut and relocate for further practice.
6. Repeat exercise and show your completed job for assessment.
7. Complete your procedure sheet.

REQUIREMENTS

- correct alignment, assembly and tacking of the job
- smooth regular weld contour
- angular distortion 0° to 5°
- penetration to be no less than 20% of the total weld length
- to have no more than 2 significant defects per 150mm of weld length with an accumulated defect area of less than 4 times the square of the material thickness.

MATERIAL UNITS

4 pieces 75 x 1 to 1.6 x 150mm stainless steel sheet
2

ECONOMY

Return unused material and filler rods to the store.
Turn off the shielding gas when you're not using it.

Section 4

Butt weld - steel tube - flat (rotated)

Task

To deposit single run butt welds on low carbon steel tube in the flat position.

This section covers part of learning outcome 5 of the National Module Descriptor.

Why

So you will be able to competently weld tubular sections in the flat position as required by industry.


To pass

You will need to complete a single run butt joint on a tubular steel section in the flat position to the requirements on the work sheet.



Safety

- Follow all OH&S requirements for the gas tungsten arc process.
- Never grind thin sections on a grinding wheel.
- Always use tongs to pick up hot work.



r rod: \emptyset



2 amps 4 amps

Ceramic hood size:

Doesn't comply

ation

Return unused material and filler rods to the store. Turn off the shielding gas when you're not using it.



Suggested joint preparation

Section 5

Power sources, polarity and tungsten electrodes

Task

To understand the power sources, polarity and tungsten electrodes for welding steel, stainless steel and aluminium materials.

This section covers part of learning outcome 5 of the National Module Descriptor.

Why

So you can use this knowledge in a practical workshop environment and select appropriate operating variables.

To pass

At the end of the module you will do a competency test on this topic. This consists of multiple choice and short answer questions.



Safety

- Keep your work area as clean and tidy as possible.
- Make sure your work is cool before touching it.

Power sources

The power sources for gas tungsten arc welding provide either an alternating current (AC) or a direct current (DC) or a combination of both. A high frequency HF unit can be built into the power source or obtained as an add-on unit.

- ACHF transformers
- DC generators
- AC/DC HF transformer rectifiers
- inverters.

Gas tungsten arc welding power sources are fitted with high frequency (HF) so the arc can self start. **Self start** or **non-touch** start means the arc can be initiated without the electrode having to make contact with the workpiece. There is more information on HF later in this section.

ACHF transformers

ACHF (alternating current high frequency) transformers produce a safe and adjustable alternating current for welding. This type of machine is generally used for gas tungsten arc welding aluminium, magnesium and their alloys.

DC generators

DC (direct current) generators are designed to generate an adjustable direct current for welding ferrous and non-ferrous metals. These machines are not often used today because transformer rectifiers and inverters are more efficient and popular. Generators can be fitted with portable HF units for non-touch starting.

AC/DC HF transformer rectifiers

AC/DC HF (alternating current/direct current high frequency) transformer rectifiers are the most popular type of power source. They supply either AC or DC welding current with HF. This power source is suitable for welding all metals, both ferrous and non-ferrous.

Inverters


Inverters are a newer type of power source that is lighter, more portable and multi-functional. Inverters can be used for different types of welding processes. They are designed to produce DC current. More specialised and expensive types provide AC current.

Polarity/current

When using direct current the gas tungsten arc welding process you need to select the correct polarity for the material to be welded. Choosing a polarity is an important part of the welding operation because it affects the operating characteristics of the arc, heat input and level of weld penetration.

- DC (-) negative
- DC (+) positive
- AC-HF.


DC (-) negative



DC straight polarity
(electrode negative)

With the DC negative polarity the electrode (torch) is connected to the negative terminal of the power source. The negative electrons flow from the electrode to concentrate about two thirds of the heat energy into the positive workpiece and produce a deep penetrating weld. DC polarity is used for welding all types of materials except aluminium and magnesium alloys.

DC (+) positive




DC reverse polarity
(electrode positive)

When using DC+ polarity the electrode (torch) is connected to the positive terminal and the workpiece to the negative terminal of the power source.


The electrons flow from the workpiece to concentrate about two thirds of the heat energy into the electrode and the remainder into the workpiece. This causes electrode overheating and much shallower weld penetration and so DC electrode positive is seldom used. It requires larger size electrodes on lower currents to prevent the electrode melting into the weld pool.

AC-HF



AC-HF gives a weld penetration characteristic between that of DC negative and DC positive. Its electrical cleaning action makes it ideally suited to welding aluminium and magnesium alloys.

Examples of arc and weld penetration characteristics



High frequency systems

The term high frequency, as applied to welding processes and power sources, usually refers to electrical pulses in the frequency range of 50,000, to 3,000,000 hertz (cycles) per second at very low amperages. When high frequency is switched on a superimposed secondary voltage is passed through the welding circuit.

High frequency is used to provide:

1. **Arc stabilisation with AC current.** When an AC sine wave passes through zero the arc cuts out, high frequency provides stable re-initiation of the arc which produces very smooth arc conditions.
2. **Gas ionisation.** High frequency when used in conjunction with GTAW provides high voltage at the tungsten tip. Since the ionisation potential of Argon is low the high frequency voltage does create an improved ionised gas path for the welding current to follow.
3. **Arc initiation.** High frequency energy, by ionising a gas path between the electrode and work piece in GTAW bridges the physical distance making non touch starts possible.
4. **High frequency efficiency.** To maintain high frequency efficiency it is necessary to accurately maintain the contact points in the high frequency unit. Qualified electricitians are responsible for the service of the points unit.

Tungsten electrodes

Tungsten (chemical symbol W) is a very hard, silver-grey metal which has the highest melting point (3410°C) of all the metals and stays hard even when red-hot.

Electrodes for gas tungsten arc welding are different from those used for manual metal arc welding. They are not flux coated, do not melt in the arc or leave a slag cover over the finished weld.

Gas tungsten arc electrodes will melt if they are the wrong type or size, if excessive current is used or if the argon runs out or is turned off, if any of these situations occur, thin particles of tungsten can be transferred across the arc into the weld pool.

There are four main types of tungsten electrodes used with the gas tungsten arc process. The choice depends on the metal being welded and the current/polarity used.

The four tungsten electrodes and the recommended current/polarity for each are:

- pure tungsten (ACHF or DC(-))
- thoriated tungsten (DC(-))
- zirconiated tungsten (ACHF)
- ceriated tungsten (ACHF) and DC(-)

Pure tungsten

Pure tungsten electrodes were the first used for gas tungsten arc welding but are rarely used.

Improvements have been made to tungsten electrodes with the addition of alloying elements such as thorium, zirconium and cerium.

Thoriated tungsten

Thoriated tungsten electrodes contain a small percentage (up to 2%) of thorium oxide which improves the qualities of the electrode. These electrodes are used with direct current on negative polarity (DC-).

Zirconiated tungsten

Zirconiated alloyed tungsten electrodes are useful because they form a balled tip and resists oxides. These electrodes are used with alternating current high frequency (ACHF).


Ceriated tungsten

Ceriated electrodes contain small percentages of cerium which combine the features of both the thoriated and zirconiated type electrodes. These electrodes can be used on both ACHF and DC negative.


Electrode preparation

It's most important that you prepare electrodes properly before use. The size and shape of the tip depends on the amount of current that has to pass through the electrode.

When using low currents on thin metals' grind the electrode to a point. The length of the point can be about two to three times the diameter (thickness) of the electrode. This is for electrodes up to 3.2mm diameter.




When using higher currents taper the electrode to about twice the diameter of the electrode and leave the tip flat.




Ball zirconiated electrodes by grinding a shorter taper; about a 45° angle with a flat tip about half the diameter as shown below.

Before beginning to weld, draw the arc between the electrode and a striker plate to allow the tip to ball. Copper is an excellent striker plate.



Grind the electrode with the grind marks running lengthways on the tip as shown in the previous examples. If you grind the electrode round the tip (as shown below), small particles of tungsten may break from the electrode and be thrown across the arc to contaminate the weld metal. When low amperes are used the arc can wander by following the grind marks around the tip.



Note To clean a contaminated zirconiated electrode, when welding aluminium, first switch the machine to DC+. Then draw an arc for a second or two on a copper surface until clean. Remember to switch current back to AC before welding.

Review questions

These questions will help you revise what you've learnt in **Section 5**. The answers are on page 79. Ask your teacher for help with anything you don't understand.

Multiple choice questions

Choose the correct answer and write the letter **a**, **b**, **c** or **d** in the box.

1. Which of the machines listed below is not recommended for gas tungsten arc welding aluminium?

a. ACHF transformers
b. DC generators
c. AC/DC HF transformer rectifiers
d. none of the above.

☐

2. When using DC generators for gas tungsten arc welding the electrode (torch) lead is connected to the:

a. work terminal
b. positive terminal(+)
c. electrode terminal
d. negative terminal(-).

☐

3. Which electrode is recommended for use on ACHF?

a. thoriated tungsten
b. chromium tungsten
c. zirconiated tungsten
d. nickel tungsten.

☐

4. When welding with low amperes on dc - the electrode is:

a. prepared to tapered point
b. prepared to balled tip
c. prepared to taper with flat tip
d. no preparation is required.

☐

Short answer questions

5. About two thirds of the heat of direct current (DC) comes from which terminal?
- _____
6. When using the gas tungsten arc process on ACHF, the high frequency has some important functions. Name one of these functions:
- _____
7. List **three** different types of electrodes used for gas tungsten arc welding.
- _____
 - _____
 - _____
8. When using ACHF, the positive (+) half cycle has an effect on aluminium. What is this effect?
- _____
9. With the aid of a sketch show the correct preparation for a zirconiated tungsten electrode.
- _____
10. List **two** advantages of using zirconiated electrodes:
- _____
 - _____

Section 6

Gases and filler rods

Task

To understand the different types of shielding gases and filler rods used for gas tungsten arc welding steel, stainless steel and aluminium materials.

This section covers learning outcome 4 of the National Module Descriptor.

Why

So you will be able to choose the appropriate consumables for welding.

To pass

At the end of the module you will do a competency test on this topic. This consists of a series of multiple choice and short answer questions.

DANGER



Safety

- Make sure adequate ventilation is provided when welding in confined spaces.
- Always wear non-flammable clothing and footwear.

Shielding gases and their uses

The function of shielding gases in the gas tungsten arc welding process is to protect the tungsten electrode and molten weld pool from contamination from the surrounding air. Without a shielding gas there would be serious damage to the electrode and poor quality welds would be made.

Inert gases are generally used for this process. The shielding gases and gas mixtures most used are:

- argon (Ar)
- helium (He)
- argon/helium (Ar/He) gas mixture
- argon/helium/hydrogen* (Ar/He/H) gas mixture

* Hydrogen is not inert. It is classified as an active gas.

Argon

Argon is the most widely used GTA shielding gas in Australia. It's the least expensive because it's obtained from separating air during the oxygen and nitrogen distillation process. Argon produces a moderately hot arc and is suitable for welding all metals. It has the slowest welding speed of all the gases and gas mixtures but the best arc starting characteristic.

Helium

Helium is the most expensive inert gas used in Australia because it's imported from North America. Helium produces a hotter arc and deeper weld penetration than argon. It can be used on all metals.

Argon/helium mixtures

Argon and helium are mixed together in varying percentages to form a range of gases suitable for welding different materials. Either one can be the base gas. The greater the percentage of helium, the hotter the arc temperature. For example, three parts argon to one part helium produces a hot arc especially good for aluminium. Mixed in the opposite proportions, the arc is very hot with high welding speeds and rapid melting of the metal (without the need for pre-heat) and broad deep penetration. This mixture is an economic alternative to pure helium. It's used for improving weld speeds, penetration and the shape of the weld.


Argon/helium/hydrogen mixtures

The three-gas mixtures produce a hot stable arc for welding steels (low carbon and alloy), stainless steels, some copper alloys and nickel. They produce a very hot arc and better welding speeds than argon/helium mixtures. As the hydrogen content is more than 1%, these mixtures are no longer inert. The relatively small amount of hydrogen doesn't damage the parent material or tungsten electrode.

Cylinder colour code

There is an **Australian Standards** colour code for gas and gas mixture cylinders so they can be easily recognised. The colours for the cylinders used with the gas tungsten arc process are:

argon	peacock blue
helium	middle brown
argon/helium	peacock blue with middle brown shoulder
argon/helium/hydrogen	peacock blue with middle brown shoulder and red band.



Regulators and flow-meters

Regulators

The main function of the regulator is to reduce the high pressure from the cylinder to a safe and usable operating pressure. Regulators used for gas tungsten arc welding are pre-set to a maximum output pressure of 200kPa.

They are colour coded, usually peacock blue, and have a right-hand threaded connection.

Flow-meters



A flow-meter is a device used to control the flow of shielding gas through the torch to the point of welding. Flow-meters have an adjustable valve, a float and a transparent plastic or glass tube to indicate the amount of gas (measured in litres/min) used during welding.

The valve is adjusted to the desired gas flow rate. This is indicated by the level of float in relation to the litres/minutes reading on the transparent tube.

Example of a regulator used for gas tungsten arc welding.



Filler rods

Good quality welds with the gas tungsten arc process depend on matching the type of filler rod to the parent metal and the size of the rod to the size of the weld. The composition of the filler rod should be as close as possible to the parent material.

Low carbon steels

The gas tungsten arc process is particularly suitable for the various types and alloys of low carbon steel. These are usually described as **semi-killed** which means the steel has been de-oxidised during manufacture but can still contain oxygen which may cause problems during welding. Gas bubbles can form in the weld puddle and be trapped in the finished weld as porosity.

The solution to this problem is to use filler wire containing de-oxidisers such as silicon (Si) and manganese (Mn). This is called double de-oxidised rod. A third de-oxidiser, aluminium (Al), is sometimes added and this known as triple de-oxidised rod.

Filler rods for welding low carbon steel are generally colour-coded and are available in diameter (Ø) 1.6mm, 2.4mm and 3.2mm.

Stainless steel

The most common stainless steel for fabrication and welding are the austenitic stainless steel grades. Filler rods for welding these steels contain varying percentages of chromium (Cr) and nickel (Ni). The 18/8 Cr/Ni is one of the most popular.

Austenitic filler rods are stabilised with small additions of niobium (Nb) and Molybdenum (Mo). These stabilisers are added to prevent carbide precipitation (loss of chromium) in the heat affected zone (HAZ) area of the weld. Stabilised austenitic stainless steel filler rods are available in Ø1.6mm, 2.4mm and 3.2mm.

Aluminium

Aluminium filler rods are available in different grades and sizes for many uses. When welding aluminium, it's important to select the correct grade or series number filler rod to suit the composition of the parent material.

Pure aluminium is used for the welding exercises in this module. To weld this grade of material you will need a 1000 series (pure) aluminium filler rod.

1000 series, pure aluminium filler rods are available in Ø1.6mm, 2.4mm, 3.2mm and 4.8mm.

Review questions

These questions will help you revise that you've learnt in **Section 6**. The answer are on page 80. Talk to your teacher, if there's anything you don't understand.

Multiple choice questions

Choose the correct answer and write the letter **a**, **b**, **c** or **d** in the box.

- The most common gas used for shielding with the gas tungsten arc welding process is:
 - argon
 - carbon dioxide
 - acetylene
 - oxygen☐
- The cylinder colour for helium is?
 - peacock blue
 - black
 - middle brown
 - maroon☐
- Which of the gases/gas mixtures in the list below is not an inert gas?
 - helium
 - hydrogen
 - argon/helium
 - argon☐
- The function of the gas regulator is to:
 - regulate the amperes to the torch
 - lower the volts from the power source
 - deliver gas to the torch
 - feed water to the torch☐
- Which type of filler rod would you choose to weld pure aluminium?
 - de-oxidised low carbon steel
 - de-oxidised copper
 - stabilised stainless steel
 - aluminium☐

Short answer questions

- Shielding gases have an important function in gas tungsten arc welding. Briefly describe that function:

- Briefly describe what is meant by the term inert:

- Briefly describe the function of the flow-meter in the gas tungsten arc process:

- Filler rods used for welding low carbon steel contain de-oxidisers to eliminate porosity from the weld metal. Name **two**:

■ _____

■ _____
- Stainless steels can be stabilised to prevent carbide precipitation. Name **two** of the stabilisers that are used for this purpose:

■ _____

■ _____

Notes

Section 7

Corner fillet weld - stainless steel sheet - flat

Task

Deposit single run corner fillet welds on stainless steel sheet in the flat position.

This section covers part of learning outcome 5 of the National Module Descriptor.

Why

So you will be able to competently weld stainless steel sheet sections together in the flat position as required by industry.

To pass

You will be expected to complete a single run corner fillet weld on stainless steel sheet in the flat position to the requirements on the work sheet.

DANGER




Safety

- Follow all the OH&S safety requirements.
- Protect your eyes and skin by wearing proper safety clothing.
- Use screens to protect others from arc rays.

PROCEDURE SHEET

Section 7 Corner fillet weld - stainless steel sheet flat



Welding data:

Machine brand

Type of current:

Type of electrode:

Electrode size: Ø

Electrode profile

Type of shielding gas:

Flow rate l/min:

Type of filler rod:

Size of filler rod: Ø

Weld current data

Run:

1 amps 3 amps

2 amps 4 amps

Material data

Type:

Classification:

Thickness:

Surface cleaning:

Pre heat temperature:

Ceramic hood size:

Assessment

Complies

Doesn't comply

Correct alignment, assembly and tacking

Smooth regular contour

Angular distortion

Weld defects

Name:

Section 7 Corner fillet weld - stainless steel sheet - flat
(Formal assessment to pass)

- IF IN DOUBT ASK YOUR TEACHER**
- OBJECTIVE**
To deposit a single run corner fillet on 1 to 1.6mm stainless steel.
- POSITION**
Flat
- PROCEDURE**
Your teacher will demonstrate.
- METHOD**
1. Thoroughly clean weld surface and degrease if necessary.
 2. Assemble and securely tack weld.
 3. Dress tack welds.
 4. Complete welding exercise and show your work to your teacher.
 5. Repeat the exercise and show your completed job for assessment.
 6. Complete your procedure sheet.


REQUIREMENTS

- correct alignment, assembly and tacking of the job
- smooth regular weld contour
- angular distortion 0° to 5°
- to have no more than 2 significant defects per 150mm of weld length with an accumulated defect area of less than 4 times the square of the material thickness.

MATERIAL 4 pieces 50 x 1 to 1.6 x 150mm stainless steel sheet

UNITS 2

ECONOMY Return unused material and filler rods to the store. Turn off the shielding gas when you're not using it.



Notes

Section 8

Fillet weld - stainless steel sheet - horizontal

Task

To deposit single run fillet welds on stainless steel sheet in the horizontal position.

This section covers part of learning outcome 5 of the National Module Descriptor.

Why

So you will be able to competently weld stainless steel sheet in the flat position as required by industry.

To pass

You will need to complete a single run fillet weld on stainless steel sheet in the horizontal position to the requirements on the work sheet.




Safety

- Follow all OH&S safety requirements.
- Make sure your welding equipment is in good order before you use it.
- Always turn your machine off when not in use.

PROCEDURE SHEET

Section 8 Fillet weld - stainless steel sheet - horizontal



Welding data:

Machine brand

Type of current:

Type of electrode:

Electrode size: Ø

Electrode profile

Type of shielding gas:

Flow rate l/min:

Type of filler rod:

Size of filler rod: Ø

Weld current data

Run:

1 amps 3 amps

2 amps 4 amps

Material data

Type: Classification:

Thickness:

Surface cleaning:

Pre heat temperature:

Ceramic hood size:

Assessment

Complies

Doesn't comply


Correct alignment, assembly and tacking

Smooth regular contour

Angular distortion

Weld defects

Name:

Section 8 Fillet weld - stainless steel sheet - horizontal
(Formal assessment to pass)

IF IN DOUBT ASK YOUR TEACHER

OBJECTIVE To deposit a single run fillet on 1 to 1.6mm stainless steel.

POSITION Horizontal

PROCEDURE Your teacher will demonstrate.

METHOD

1. Thoroughly clean weld surface and degrease if necessary.
2. Assemble and securely tack weld.
3. Dress tack welds.
4. Complete welding exercise and show your work to your teacher.
5. Repeat the exercise and show your completed job for assessment.
6. Complete your procedure sheet.

REQUIREMENTS

- correct alignment, assembly and tacking of the job
- smooth regular weld contour
- angular distortion 0° to 5°
- to have no more than 2 significant defects per 150mm of weld length with an accumulated defect area of less than 4 times the square of the material thickness.

MATERIAL

4 pieces 50 x 1 to 1.6 x 150mm stainless steel sheet

UNITS

2

ECONOMY

Return unused material and filler rods to the store.
Turn off the shielding gas when you're not using it.

Section 9 Gas tungsten arc weld faults

Task	To recognise gas tungsten arc welding faults. This section covers learning outcomes 6 and 7 of the National Module Descriptor.
Why	So you will be able to identify problems and take appropriate corrective action.
To pass	At the end of the module you will do a competency test on this topic. This consists of a series of multiple choice and short answer questions.



Safety

- Always make sure there is adequate ventilation in your work area.
- Never leave hot metal objects unattended around the workshop.

Gas tungsten arc welding faults




Despite your efforts to produce perfect welds, faults sometimes occur with all welding processes. Gas tungsten arc welding is no exception. Faults are caused by human error, equipment not working properly, using the wrong type of filler rod or the wrong welding technique or other things.



Faulty welds add expense to a job because it takes time to put them right. It's important for you to know the types of faults, the likely causes and how to correct them.

The most common gas tungsten arc welding faults are:

- undercut
- overroll
- porosity
- lack of fusion
- tungsten inclusion
- cracking.

You will find the possible causes for these faults and suggestions on how to correct them on the next two pages.

FAULT	POSSIBLE CAUSE	HOW TO CORRECT
<div>Undercut</div> 	<ul style="list-style-type: none">Welding current too highWelding speed too fastNot adding enough filler rod	<ul style="list-style-type: none">Lower the currentUse a slower welding speedAdd more filler rod to the weld pool
<div>Overroll</div> 	<ul style="list-style-type: none">Welding current too lowAdding too much filler rodUsing too large a size filler rod	<ul style="list-style-type: none">Increase the currentReduce the amount you addUse a smaller size filler rod
<div>Porosity</div> 	<ul style="list-style-type: none">Using too long an arc lengthLack of shielding gas covering the weldWorking in draughty areaGas nozzle bore too small (causes a lack of shielding around the arc)Welding over contaminated metal	<ul style="list-style-type: none">Shorten your arcIncrease gas supplyProtect the weld area by closing doors, windows or by screeningUse a larger size nozzleClean surfaces before welding

FAULT	POSSIBLE CAUSE	HOW TO CORRECT
Lack of fusion 	<ul style="list-style-type: none"> Welding current too low Using wrong welding technique Poorly prepared weld joint preparation Using incorrect size filler for the type of work Welding over badly contaminated surfaces 	<ul style="list-style-type: none"> Increase the current Adjust your technique to suit the type of work Adjust preparation Select the correct size for the thickness of metal and position it is to be welded in Clean surfaces before you weld them
Tungsten inclusion 	<ul style="list-style-type: none"> Current too high for the size of the electrode Poor electrode preparation Touching the workpiece with the electrode Welding with a badly contaminated electrode 	<ul style="list-style-type: none"> Lower the current to suit the size of the electrode Prepare the electrode to the dimensions shown in this module Adjust your operating technique Clean and regrind ready for use

Review questions

These questions will help you revise what you've learnt in **Section 9**. The answers are on page 81. Ask your teacher for more help if you need it.

Multiple choice questions

Choose the correct answer and write the letter **a, b, c** or **d** in the box.

- Undercut is mostly likely caused by:
 - welding over contaminated surfaces
 - adding excessive amounts of filler rod
 - using too large a gas nozzle
 - using too high a welding current☐
- Which of the following is a major cause of weld porosity?
 - using too high a welding current
 - welding in draughty conditions
 - using too short an arc length
 - none of the above☐
- When gas tungsten arc welding, which of the following would correct lack of fusion?
 - increasing welding current
 - adding more filler rod
 - increasing gas supply
 - depositing larger size weld☐
- Which of the following would have least influence on cracking of the weld metal?
 - lack of pre-heating parent metal
 - using wrong type of filler rod
 - adding too much filler rod
 - using wrong type of gas☐

5. Tungsten inclusions in a weld are caused by:

- a. the electrode touching the workpiece
- b. using too high a current for the size of electrode
- c. poor electrode preparations
- d. all of the above

☐

6. Contamination of workpiece surfaces is likely to cause:

- a. undercut
- b. porosity
- c. overroll
- d. tungsten inclusion

☐





7. Using too fast a welding speed will result in:

- a. undercut
- b. overroll
- c. porosity
- d. none of the above

☐

Short answer questions

8. Below are four typical gas tungsten arc welding faults. Identify each one and label where indicated:



Section 10 Stringer beads - aluminium sheet - flat

Task

To deposit stringer beads on aluminium sheet in the flat position.

This section covers part of learning outcome 5 of the National Module Descriptor.

Why

To develop the manipulative skills to weld a range of aluminium joint preparations.

To pass

Section 10 is a skill practice exercise which is not assessed as part of this module. However, you should make every effort to reach the standards required. The skills you learn in this section are used later for exercises that are formally assessed.



Safety

- Follow OH&S requirements.
- When using shearing equipment make sure your hands are clear of the cutting edges.
- Never leave hot metal objects around the workshop without first indicating to others that they are hot.
- When using degreasing solvents such as acetone and white spirit, make sure that you have adequate ventilation. These solvents should be stored well away from welding operations.

PROCEDURE SHEET

Section 10 Stringer beads - aluminium sheet - flat



Welding data:

Machine brand

Type of current:

Type of electrode:

Electrode size: Ø

Electrode profile

Type of shielding gas:

Flow rate l/min:

Type of filler rod:

Size of filler rod: Ø

Weld current data

Run:

1 amps 3 amps

2 amps 4 amps

Material data

Type:

Classification:

Thickness:

Surface cleaning:

Pre heat temperature:

Ceramic hood size:

Assessment

Complete fusion of the parent metal

Smooth regular contour

Weld defects

Name:

Complies

Doesn't comply

Section 10 Stringer beads - aluminium sheet - flat (Skill practice - no formal assessment)

IF IN DOUBT ASK YOUR TEACHER

To deposit stringer beads using a filler rod on 3mm pure aluminium sheet.

Flat

Your teacher will demonstrate.


1. Thoroughly clean weld surface and degrease if necessary.
2. Position sheet on support surfaces.
3. Complete bead exercise and show your work to your teacher.
4. Repeat the exercise and show your completed job for assessment.
5. Complete your procedure sheet.

- REQUIREMENTS**
- Complete fusion of the parent metal
 - smooth regular appearance
 - beads to have no surface defects

MATERIAL 3 pieces 75 x 3 x 150mm pure aluminium sheet

UNITS 3

ECONOMY Return unused material and filler rods to the store. Turn off the shielding gas when you're not using it.



Section 11 Butt weld - aluminium sheet - flat (temporary backing)

Task	To deposit single run butt weld aluminium sheet using a backing bar device. This section covers part of learning outcome 5 of the National Module Descriptor.
Why	So you will be able to weld aluminium sheet together in the flat position as required by industry.
To pass	You will be expected to complete a single run butt weld on aluminium sheet in the flat position to the requirements on the work sheet.




Safety

- Follow OH&S requirements.
- Always keep your hands clear of cutting edges when shearing thin materials.
- Never grind aluminium on wheels used for steel.

PROCEDURE SHEET

Section 11 Butt weld - aluminium sheet - flat (temporary backing)



Welding data:

Machine brand

Type of current:

Type of electrode:

Electrode size: Ø

Electrode profile

Type of shielding gas:

Flow rate l/min:

Type of filler rod:

Size of filler rod: Ø

Weld current data

Run:

1 amps 3 amps

2 amps 4 amps

Material data

Type:

Classification:

Thickness:

Surface cleaning:

Pre heat temperature:

Ceramic hood size:

Assessment

Complies

Doesn't comply

Correct alignment, assembly and tacking

Smooth regular contour

Angular distortion

Weld penetration

Weld defects

Name:

Section 11 Butt weld - aluminium sheet - flat (temporary backing)
(Formal assessment to pass)

IF IN DOUBT ASK YOUR TEACHER

To deposit a single run butt on 3mm pure aluminium sheet.

Flat

Your teacher will demonstrate.

PROCEDURE

METHOD

1. Thoroughly clean weld surface and degrease if necessary.
2. Assemble and securely tack weld.
3. Complete the welding exercise and show it to your teacher.
4. Cut and relocate for further practice.
5. Repeat the exercise and show your completed job for assessment.
6. Complete your procedure sheet.

REQUIREMENTS

- correct alignment and assembly
- smooth regular weld contour
- angular distortion 0° to 5°
- penetration to be no less than 20% of the total weld length
- to have no more than 2 significant defects per 150mm of weld length with an accumulated defect area of less than 4 times the square of the material thickness.

MATERIAL



4 pieces 50 x 3 x 150mm pure aluminium sheet

UNITS

2

ECONOMY

Return unused material and filler rods to the store. Turn off the shielding gas when you're not using it.



Tack weld detail

Notes

Section 12 Corner fillet - aluminium sheet - flat

Task

To deposit single run corner fillet welds on aluminium sheet in the flat position.

This section covers part of learning outcome 5 of the National Module Descriptor.

Why

So you will be able to weld aluminium sheet together in the flat position as required by industry.

To pass

You will be expected to complete a single run corner fillet weld on aluminium sheet in the flat position to the requirements on the work sheet.




Safety

- Make sure you have good ventilation when working with acetone.
- Make sure your job is securely located on the work bench.
- Set an example to others by following approved safety procedures.

PROCEDURE SHEET

Section 12 Corner fillet - aluminium sheet flat



Welding data:

Machine brand

Type of current:

Type of electrode:

Electrode size: Ø

Electrode profile

Type of shielding gas:

Flow rate l/min:

Type of filler rod:

Size of filler rod: Ø

Weld current data

Run:

1 amps 3 amps

2 amps 4 amps

Material data

Type:

Classification:

Thickness:

Surface cleaning:

Pre heat temperature:

Ceramic hood size:

Assessment	Complies	Doesn't comply
Correct alignment, assembly and tacking		
Smooth regular contour		
Angular distortion		
Weld defects		

Name:

IF IN DOUBT ASK YOUR TEACHER

To deposit a single run corner fillet weld on 3mm pure aluminium.

Flat

Your teacher will demonstrate.

1. Thoroughly clean weld surface and degrease with acetone.

2. Assemble and securely tack weld.

3. Complete the welding exercise and show it to your teacher.

4. Repeat the exercise and show your completed job for assessment.

5. Complete your procedure sheet.


REQUIREMENTS

- correct alignment and assembly
- smooth regular weld contour
- angular distortion 0° to 5°
- to have no more than 2 significant defects per 150mm of weld length with an accumulated defect area of less than 4 times the square of the material thickness.

MATERIAL 4 pieces 50 x 3.0 x 150mm pure aluminium sheet

UNITS 2

ECONOMY Return unused material and filler rods to the store. Turn off the shielding gas when you're not using it.

Section 12 Corner fillet - aluminium sheet - flat
(Formal assessment to pass)

Section 13 Fillet weld - aluminium sheet - horizontal


Task	Deposit single run fillet welds on aluminium sheet in the horizontal position. This section covers part of learning outcome 5 of the National Module Descriptor.
Why	So you will be able to weld aluminium sheet together in the horizontal position as required by industry.
To pass	You will be expected to complete a single run fillet weld on aluminium sheet in the horizontal position to the requirements on the work sheet.

DANGER**Safety**

- Follow OH&S procedures.
- Always screen your work from others.
- Arc rays can burn, keep your eyes and skin properly covered.

PROCEDURE SHEET

Section 13 Fillet weld - aluminium sheet - horizontal



Welding data:

Machine brand

Type of current:

Type of electrode:

Electrode size: Ø

Electrode profile

Type of shielding gas:

Flow rate l/min:

Type of filler rod:

Size of filler rod: Ø

Weld current data

Run:

1 amps 3 amps

2 amps 4 amps

Material data

Type: Classification:

Thickness:

Surface cleaning:

Pre heat temperature:

Ceramic hood size:

Assessment

Complies

Doesn't comply


Correct alignment, assembly and tacking

Smooth regular contour

Angular distortion

Weld defects

Name:



IF IN DOUBT ASK YOUR TEACHER

OBJECTIVE To deposit a single run fillet weld on 3mm pure aluminium sheet.

POSITION Horizontal

PROCEDURE Your teacher will demonstrate.

METHOD 1. Thoroughly clean weld surface and degrease with acetone..

2. Assemble and securely tack weld.

3. Complete the welding exercise and show it to your teacher.

4. Repeat the exercise and show your completed job for assessment.

5. Complete your procedure sheet.

REQUIREMENTS

- correct alignment and assembly
- smooth regular weld contour
- angular distortion 0° to 5°
- to have no more than 2 significant defects per 150mm of weld length with an accumulated defect area of less than 4 times the square of the material thickness.

MATERIAL 4 pieces 50 x 3 x 150mm pure aluminium sheet

UNITS 2

ECONOMY Return unused material and filler rods to the store. Turn off the shielding gas when you're not using it.

Section 13 Fillet weld - aluminium sheet - horizontal (Formal assessment to pass)

Notes

Answers to review questions

Section 1 Gas tungsten arc welding - process and hazards

- 1b. power source
- 2d. thick plate
- 3.c all of the above
- 4a. tungsten
- 5d. tungsten
- 6. DC negative (-)
- 7. Less smoke and fumes are produced.
Produces a concentrated arc which leads to less distortion.
No slag or fluxes are used.
- 8. affected by wind and draughts
slow welding speeds
- 9. shielding
- 10. Tungsten electrode
- 11. welding

Section 5 Power sources, polarity and tungsten electrodes

- 1b. DC generators
- 2d. negative terminal
- 3c. zirconiated
- 4a. tapered point
- 5. the positive (+) terminal
- 6. reignite the arc as it passes through zero
- 7. pure tungsten
thoriated tungsten
zirconiated tungsten

8. To assist in the surface cleaning of the material by breaking up its oxide.

9.



The electrode should be ground to a taper twice the diameter with a flat left on the tip to one third that of the diameter.





10. Good arc starting when used on AC current.
High resistance to contamination when welding aluminium and magnesium.

Section 6 Gases and filler rods

- 1a. argon
- 2c. middle brown
- 3b. hydrogen
- 4c. deliver gas to the torch
- 5d. aluminium
6. To prevent the weld and surrounding weld area from contamination from the atmosphere.
7. The gas is chemically inactive and therefore doesn't break down in the arc to form other elements.
8. Flow-meters are used to control the amount of gas flow to the arc via the torch.
9. silicon
manganese
10. niobium
molybdenum

Section 9 Gas tungsten arc welding faults


- 1d. using too high a weld current
- 2b. welding in draughty conditions
- 3a. increasing welding current
- 4c. adding too much filler rod
- 5d. all of the above
- 6b. porosity
- 7a. undercut
- 8.



Notes

Words you need to know

Ø	symbol representing diameter
alternating current (AC)	an electric current that regularly alters its direction of flow; first flowing in one direction and then reversing to flow in the opposite direction
aluminium	silvery coloured non-ferrous element that is lightweight and non-corrosive
asphyxiation	suffocation owing to lack of oxygen
carbide precipitation	localised corrosion along the HAZ in unstabilised stainless steel owing to a lack of chromium
de-oxidise	the process of removing oxygen from the weld area
direct current (DC)	an electric current that flows in one direction only
HF ignition spark starting	ignition of an arc by a high frequency spark applied across the arc gap
HF ignition unit	a high voltage, high frequency electrical oscillator used to enable an arc to be initiated without contact between the electrode and the workpiece
HF re-ignition spark starting	re-ignition of an AC arc, after extinction at zero current, by a high voltage high frequency spark applied across the arc gap
inert gas	a gas which will not chemically combine with other elements
inverter	a welding machine which changes rectified DC current to AC current at a much lower frequency; this allows a lightweight transformer to be used before the current is finally rectified back to DC
low carbon steel	an iron-based alloy containing between 0.08% to 0.3% carbon
rectifier	a welding machine used for changing AC current to DC current
stabilised	a stainless steel that contains small quantities of niobium or molybdenum to prevent carbide precipitation



AUTOMOTIVE HEATING AND WELDING PROCEDURES

7292G

Statement of Intent

The following notes and exercises have been prepared to help you learn the principle operations and safety procedures required when using welding or heating equipment on or around automotive vehicles and is aimed at promoting a safe working environment.

These principle operations and safety procedures have been developed over many years and are recommended safe working practices that will maximise protection and minimise the risk of injury to you and others when welding or heating in a potentially hazardous and dangerous environment.

The intent of this module is to provide the learner with the underpinning knowledge and skills through instruction and practical experiences to enable them to apply simple heating and welding processes relative to automotive service and repair operations.

On successful completion of this module the learner should be able to:

- * state the safety precautions that must be followed when using welding or heating equipment on or around automotive vehicles.
- * perform the procedures involved in using heat on automotive component parts to affect their assembly or disassembly without damage.
- * use the oxy/acetylene welding equipment to lap weld low carbon steel sheeting.
- * use the oxy/acetylene cutting equipment to cut low carbon steel plate.
- * use the Gas Metal Arc Welding (GMAW) process to lap weld low carbon steel sheeting.
- * explain the procedure for welding low carbon steel sheet with the Manual Metal Arc Welding (MMAW) process.

This module should serve as a general guide for the more experienced trade person, and as a training aid for those newly introduced to the trade.

CONTENTS

Purpose and what to learn

Oxy/Acetylene Principle Operations and Safety Procedures

- ☐ Gases used for welding, heating and cutting applications
- ☐ Personal and site safety
- ☐ Equipment handling
- ☐ Vehicle component safety
 - Welding damage
 - Components
 - Damage prevention
- ☐ Questions

Using Heat on Automotive Component Parts

- ☐ Temperature measurement
- ☐ Heating effect
- ☐ Heat for the removal of component parts
- ☐ Practical exercises
 - Bearing retaining ring
 - Flywheel ring gear
- ☐ Questions

Oxy/Acetylene Lap Welding on Low Carbon Steel Sheet

- ☐ Weld terminology
 - Butt and fillet joints
- ☐ Practical exercise
 - Lap weld 1.6mm low carbon steel
- ☐ Questions

Oxygen - Fuel Gas Cutting

- ☐ Principles of flame cutting
- ☐ Types of fuel gasses used
- ☐ Fuel gas hazards
- ☐ Oxygen hazards
- ☐ Plasma cutting process
- ☐ Practical exercise
 - Oxy - fuel gas cutting 6mm Low Carbon Steel
- ☐ Questions

Metal Arc Welding Process

- ☐ GMAW operating principles
- ☐ Equipment used
- ☐ Practical exercise
 - Lap weld 1.6mm low carbon steel
- ☐ Questions

Manual Metal Arc Welding Process

- ☐ Describe the procedure required to lap weld 1.6mm low carbon steel
- ☐ Advantages and disadvantages of MMAW process in automotive applications
- ☐ Questions

OXY/ACETYLENE WELDING, HEATING AND CUTTING

Introduction

The oxy/acetylene process is basically a heating process and is built upon two fundamental principles, firstly, the acetylene and oxygen is burnt to form a flame which is the hottest combination of any two known gases and is capable of fusing most of the common metals and their alloys and secondly, if a stream of oxygen is directed on to a heated piece of iron or steel, it is possible to cut those metals to any desired shape. These principles are applied in the workshop for the cutting of steel. The principles, safety and applications are:

Gases used for welding, heating and cutting applications

OXYGEN (O ₂)	ACETYLENE (C ₂ H ₂)
Natural Occuring Gas (21% Approx. by volume in earths atmosphere)	Manufactured Gas (calcium carbide to water)
* Sustains all life.	* Hydrocarbon gas. (fuel gas)
* Supports Combustion.	* Exothermic gas.
* Combustion occurs at a higher temperature.	* Flame temperature 3350°C..
* Colourless.	* Colourless.
* Odourless.	* Distinctive acrid odour.
* Tasteless.	* Tasteless.
	* Heavier than air.

Oxygen is used industrially in conjunction with acetylene for such universal purposes as metal cutting, welding, flame hardening, flame cleaning, hardfacing and heating applications. This chemical flame combination produces a flame temperature of approximately 3100°C., making it the hottest of all flames in commercial use.

Note: The automotive industry uses the oxy/acetylene process to aid in the service and repair of light and heavy vehicles. This involves the use of the oxy/acetylene process for metal cutting, welding, and heating applications on low carbon steel.

PERSONAL AND SITE SAFETY

OXYGEN	ACETYLENE
<p>Never:</p> <ul style="list-style-type: none"> * allow industrial oxygen, under pressure, to come into contact with grease, oil, soap or fatty matter. * permit oxygen cylinders to contact any electrical circuit. * dust clothing down with industrial oxygen. * ventilate the air with industrial oxygen. * use industrial oxygen for pressure testing lines or containers. * exceed more than 1/7 cylinder draw off rate per hour maximum. * use industrial oxygen in place of compressed air. * smoke in close proximity to pure oxygen. * expose asphalt paving or fuel to industrial oxygen. <p>Note: Oxygen, in a free state, is compressed in cylinders at extremely high pressures. (13700 KPa.) Cylinders are colour coded - BLACK.</p>	<p>Never:</p> <ul style="list-style-type: none"> * use free acetylene gas outside the cylinder at a pressure exceeding 100 kPa. * use acetylene in direct contact with unalloyed copper, due to the possible formation of explosive acetylides. * use the cylinder in a position other than upright. * exceed 1/5 cylinder draw off rate per hour maximum. * "crack" an acetylene cylinder. * check for leaks with a naked flame. * decant acetylene from the cylinder. * use acetylene equipment in confined areas without adequate ventilation. <p>Note: The standard cylinder is fitted with fusible plugs, which melt at 100°C., allowing the gas to escape from overheated cylinders before an explosion temperature is reached. It is possible to fill the cylinders at pressures up to 1550 KPa without the risk of explosion. Regulator max. working gauge pressure 100 KPa. Cylinders are colour coded - CRIMSON.</p>

If industrial oxygen, under pressure, is misused it can result in a fire or explosion, which may cause serious damage/injury to property and personnel.

Acetylene in its liquid or solid state, or as gas under pressure exceeding 100 KPa. is very unstable and can explode with great violence, even without the presence of air.

Personal Protective Clothing And Equipment Used For Welding, Heating And Cutting

Personnel should be suitably dressed when carrying out welding, heating or cutting operations and it is important that the dress be comfortable and afford proper protection from the various hazards associated with the processes.

Students who are engaged in practical exercises in TAFE designated practical workrooms, workshops, laboratories or any area off campus site used for practical training, shall be required to comply with industry or the TAFE Commissions requirements relative to protective clothing and equipment.

The items of personal protective clothing and equipment are required to protect the operator and others working around the welding, heating or cutting processes from burns, scalds, ultra violet and infra red arc radiation, excessive brightness and electric shock.

Students will be required to wear as a minimum standard the following items:

Process Used Protective Item	Oxy/acetylene Heating	Oxy/acetylene Welding or Cutting	Electric Arc Welding
Clothing *	*	*	*
Safety Boot/Shoe Wear	*	*	*
Leather Gauntlets/Gloves	*	*	*
Face or Head Shield	-	-	* Fitted with approved Shade Lens
Oxy Welding Goggles	-	* Fitted with approved Shade Lens	-
Leather Apron	*	*	*
Leather Jacket	*	*	*
Safety Glasses	-	-	*
Anti-Flash Glasses	*	-	*
Leather or Cotton Hat	-	*	*

Legend: * Yes - No Clothing* - Material to be Industrial Quality Cotton Drill.


Note: Protective clothing worn must be free from grease or oil.

An approved Oxy/acetylene welding or Cutting Shade Lens No. 5. (GW)


An approved Electric Arc Welding Shade Lens to 200 Amperes is No. 10 (EW)




1. Place oxygen and fuel gas cylinders together where they are to be used and secure them from falling.




2. Examine the cylinder valve threads to ensure that they are free from damage, then blow out any dust or dirt by "cracking" the oxygen valve. This operation must not be carried out if hands are oily or greasy or in the presence of sparks or naked flames. **DO NOT "CRACK" Acetylene valves, but instead wipe clean with a lint free cloth.**




3. Attach the regulators to their respective cylinders (**R.H. Thread OXYGEN - L.H. Thread ACETYLENE**) using the correct spanner and sufficient force to tighten the connection nut firmly. With the regulator adjusting screw in the "out" position open each cylinder valve slowly until the cylinder contents gauge registers the cylinder pressure then continue opening the valve to a **maximum of 1½ turns.**



4. Connect hoses to their respective regulators (**R.H. Thread OXYGEN - L.H. Thread ACETYLENE**) and purge each hose in turn by turning the regulator adjusting screw to supply a pressure of approx. 35KPa. **This operation must not be carried out in the presence of sparks or naked flames.**



5. Connect the free ends of the oxygen and acetylene hoses to the welding or cutting torch. (**R.H. Thread OXYGEN - L.H. Thread ACETYLENE**)




6. Partially open the torch oxygen valve and adjust the regulator to the required pressure, then shut the valve. Repeat the procedure for the acetylene pressure.

Note: Pressure will increase slightly in the hoses when torch valves are closed.

OXY/ACETYLENE CLOSING DOWN PROCEDURE

When you have finished your welding, cutting or heating operation.

1.	First shut off the torch acetylene valve, then shut off the torch oxygen valve.
2.	Close both cylinder valves.
3.	Open the torch acetylene valve and release the pressure in the line.
4.	Release the adjusting screw on the acetylene gas regulator.
5.	Open the torch oxygen valve, and let the oxygen in the lines drain out.
6.	Release the adjusting screw on the oxygen regulator.



STORAGE OF GAS CYLINDERS

Keep all cylinders, whether empty or full away from radiators, furnaces, or other sources of heat, and from contact with electric circuits.

The storage area should display a warning sign notice, **DANGER- NO SMOKING- KEEP FIRE AWAY.**

Close the valves of empty cylinders.

Keep oil and grease away from cylinders.

Store acetylene cylinders not in use at least 8 metres from full oxygen cylinders.

Ensure that there is adequate ventilation where gases are stored.

Identify the contents of a cylinder by the label and not by the cylinder colour alone.

Flammable gases (acetylene) stored indoors must not exceed 56m³ by gas volume.

Avoid dropping cylinders. They could burst or the valves might be broken off or seriously damaged.

Cylinders should never be used as rollers or supports.

PROTECTION OF PLANT AND EQUIPMENT

Equipment Generally

Don't work with damaged equipment. If any part of the plant is leaking or damaged, have the repairs carried out by an authorised technician. In simple terms, give your welding equipment the care you would give any other dependable tool.

Rubber Hose

Only use hose which is designed specifically for oxygen and fuel gases. i.e. Red for fuel gases and black for oxygen.

New hose should be blown out before being put into use.

Avoid the use of excessively long lines of hose.

Protect lines of hose from becoming kinked or tangled, tripped over, or run over by vehicles, barrows, etc..

Protect hoses from molten slag and hot metal.

Do not interchange hoses, as an explosive mixture within the hose may be the result.

Never use copper tubing in a hose joint. Use only fittings of an approved type.

Regulators

As the pressures in both oxygen and acetylene cylinders are much higher than the pressures required at the welding and cutting blowpipes, it is necessary to use a pressure reducing device between each cylinder and the blowpipe. This device is known as a gas regulator.

The following rules should be observed:

Never have greasy hands or gloves when fitting a regulator to a cylinder.

When attaching a regulator ensure that the bull nose nipple and the cylinder valve seat are perfectly clean.

Important: If seating is faulty do not, under any circumstances, use lead or plastic washers to prevent leakage.

Never use a hammer to tighten the nut when attaching the regulator.

Having attached a regulator to a cylinder, make sure that the tee-screw is loose before opening the cylinder valve.

Note: If a regulator is leaking or damaged, have the repairs carried out by an authorised technician.

Welding Blowpipe


The oxy/acetylene welding blowpipe is designed to mix oxygen and acetylene in the correct proportions, and to control the volume of gases burned at the welding tip.

Operational Problems

Problem	Description	Cause
Backfire	A loud "pop" or snapping sound, from the flame going out, and if the metal is hot enough, will relight the acetylene.	1. Shutting off the oxygen first and then the fuel gas.
		2. Touching the work with the tip.
		3. Operating the torch at too low a fuel gas pressure.
Flashback	When the flame leaves the tip and burns back into the mixing chamber.	4. A loose tip.
		5. Dirt on the seating surface of the tip, mixer or head, causing a leak.
		6. Overheating the tip.

Acetylene regulator

Learning Notes 7292G-1



MAINTENANCE PROCEDURES

There are occasions when the individual neglects to exercise "reasonable care" with regards to carrying out maintenance procedures on oxy/acetylene equipment. It is not until an accident happens that it is recalled that with a little thought, the accident could have been averted. The oxy/acetylene process has added dangers to average workshop practices, but these can be minimised if the equipment/plant is kept in good working condition by regular maintenance.

Hoses

Only use standard connections to join hoses to regulators, etc..

Always tape long hoses together to prevent tangling or kinking.

If a hose becomes damaged and requires a joint, only use approved hose connectors of the correct size and blow out all loose particles of rubber, etc., before the joint is made.

Always examine hoses periodically for leaks, etc., by immersing them in water at working pressure. Any leakage of gas can be detected by the presence of bubbles.

Regulators

Should be of an approved type.

All joints between cylinder valve, regulator and hose connections must be metal to metal. Gas leaks can be detected on these connections by the use of clean soapy water.

Regulators should not be handled roughly.

Regulator Operational Defects

Defect	Description	Remedy
Scratched bull nose nipple	Leaking seat between bull nose nipple and cylinder valve.	Regulator seat will need replacing.
CREEP	Marked increase in the low pressure gauge reading when blowpipe valve is closed.	Remove and replace regulator seat.
Surging	Fluctuation or variation of the blowpipe flame.	Replace regulator seat.
Whistling or Humming noise	Whistling or humming noise during use.	Replace worn regulator seat.
FREEZING	Occurs with oxygen regulators in cold weather when a large volume of gas is being used.	The regulator may be thawed by pouring on warm, not boiling, water.

POTENTIAL VEHICLE WELDING COMPONENT DAMAGE

Introduction

Welding is used in the automotive industry to join metals in accordance with the manufacturers/clients specifications and expectations.

Repairs by welding can be effected with a minimum loss of time and strength, either in the workshop or on the field site. Parts can often be fabricated, machined and then assembled on the vehicle.

A correctly executed weld has distinct advantages over other methods of joining. i.e. saving of weight, material, cost and time. etc..

When service and/or repair on a vehicle is required, it is important, that the person carrying out the repairs is aware and exercises caution when applying heat, to minimise the risk of damage through heat conduction, radiation and hot metal globules.

Electrical/Electronic Damage

All modern automotive vehicles use some type of electrical/electronic component part. These components and electronic control units (ECU) and sensors are very susceptible to high temperatures.

It is very easy to cause heat damage to electrical/electronic parts on a automotive vehicle. This damage may occur when using incorrect methods during arc and gas welding.

List of Component Parts	Result
<ul style="list-style-type: none"> * Capacitors * Diodes * Resistors * Transistors * Wiring * Wiring Harness 	<p>Too much heat being applied to component parts may result in operational problems being inbuilt into the vehicles functional system/systems.</p>

Note: Any arc welding process has the potential to cause damage to the ECU and other sensors due to high voltage surges. Precaution is essential to safe guard the components by isolating the electrical/electronic systems. i.e. disconnect the battery and ECU harness connector at the computer.

SENSITIVE COMPONENT PARTS

Introduction

The mechanical properties of metals used in the construction and design of a automotive vehicle, differ, dependent to the operational service condition of the preforming part.

Metals are generally selected because of their suitability, some, can be stretched, twisted, compressed, etc., while others offer great resistance to these actions.

Many metal parts have special welding procedures imposed to ensure these properties are retained after welding.

Others are subject to an engineering report to Australian Design Rules and Authorised Inspection Station Rules governing the use of welding in accordance with Australian Standards AS 1554 Part 1 - "Welding of Steel Structures" SP (Structural Purpose) unless otherwise specified.

Examples of sensitive component parts

Component Parts	Metals Used	Recommendation
SAFETY RELATED SYSTEMS * STEERING - Connecting Rods - Tie Rods - Pitman or Idler arms * BRAKES * SUSPENSION - struts - Control arms - Springs - Stabiliser arms - Cross members	Alloy Steel or Heat Treated Steel or Super Saturated steel	Welding, heating, bending or deforming of components should be avoided if at all possible. Non-Destructive testing is required if these processes are used.

Remember: This module only deals with the arc and fuel gas welding of Low Carbon Steel(mild steel)

Painted Parts, Plastic Materials and Electrical/Electronic Units

When heat from the arc or oxy/acetylene flame contacts or nears painted parts, plastic materials and electrical/electronic units, it will melt, burn or scorch the surface. The resulting fumes are also a hazard to the operator.

Material	Hazard	Precaution
PLASTIC FUMES	SHORT TERM Eye, skin, throat and lung irritation and burns. Suffocation. Poisoning.	1. Clean contaminants from the metal to be welded for a minimum distance of 50mm either side of the joint. 2. Ensure that coatings are removed safely before welding. 3. If the coating or grease cannot be removed, use local exhaust ventilation and airfed respirators.
	LONG TERM Lung and colon cancer, liver damage (from some epoxy-coated metals)	
PRIMERS, PAINT, GREASE FUMES	LONG TERM Cancer. Kidney damage.	4. Appropriate local exhaust ventilation.

In cases where fumes occur in welding, heating or cutting operations it is essential to provide ample ventilation. Fumes are produced when the heat of the process, melt and vaporise metals and treated surfaces and produce welding fumes, which can have an adverse effect on health.

Note: Of particular danger are heavy metals and treated surfaces including, Chromium, Lead, Nickel, Cadmium, Aluminium, Iron oxide, Zinc, Anodised and Power Coated surfaces.

Welding Or Cutting Containers Which Have Held A Flammable Substance

Introduction

Serious explosions and fires may result if welding, heating or cutting is done on containers that may not be entirely free of flammable solids, liquids, gases and dusts. Precautions are therefore necessary and must be taken to render containers safe for such work.

The following cleaning methods are regarded as satisfactory if properly applied.

Method	Procedure
Steam Cleaning	The filler caps and drain plugs are removed and the contents drained. Low pressure steam is admitted into the container which is positioned so that steam and condensation drains from the lowest point. The steaming process should continue for at least a half-hour after the container has become hot to the touch.
Boiling	The filler caps and drain plugs are removed and the contents drained. The container is then immersed in boiling water. Degreasing agents may be added to the water if desired provided they will have no corrosive effect on the container. Boiling should continue for at least one-half hour.

The following additional safety measures are recommended before welding or cutting operations are carried out on cleaned containers, and should be applied whenever possible.

Filled with Water	Filled with an Inert Gas
The container may be filled with water to a level just below the section to be cut or welded and the area above the water level should be vented to the atmosphere.	During cutting or welding the container may be kept filled with an inert gas. i.e. Nitrogen, Argon or Carbon Dioxide.

Prevention Methods

Before doing any welding, heating or cutting on a automotive vehicle the operator needs and assess whether any damage is likely occur to the component, adjacent component parts or systems of the vehicle. If there is a need to disconnect, remove, shield, clean and replace component parts, this must be done in accordance with the manufactures workshop manual recommendations. This may involve the use of special tools and accessories to achieve satisfactory repair.

OXY/ACETYLENE PRINCIPLES AND SAFETY OPERATIONS

These exercises will help you revise what you've learnt in **learning outcome 1**. If you are having difficulty in understanding or answering any exercises then ask your teacher for help.

Exercises

Answers ↓

OXYGEN (O₂)

a) Why is industrial oxygen used in combination with acetylene gas?

Answer: 1) _____
2) _____

Refer to P.4/table

b) Why must you never allow industrial oxygen, under pressure, to come into contact with grease, oil, soap or fatty matter?

Answer: _____

Refer to P.5

c) Never use industrial oxygen in place of compressed air because this can result in a _____ or _____ taking place.

Refer to P.5

d) Oxygen is compressed in a cylinder to what pressure?

Answer: _____ kPa..

Refer to P.5

e) Oxygen cylinders are colour coded _____.

Refer to P.5

f) Why should you never dust clothing down with industrial oxygen?

Answer: _____

Refer to P.5

OXY/ACETYLENE PRINCIPLES AND SAFETY OPERATIONS

These exercises will help you revise what you've learnt in **learning outcome 1**. If you are having difficulty in understanding or answering any exercises then ask your teacher for help.

Exercises

Answers ↓

ACETYLENE (C₂H₂)

a) What type of fuel gas is acetylene?

Answer: _____

Refer to P.4/Table

b) Never use free acetylene gas outside the cylinder at a pressure exceeding _____ kPa..

Refer to P.5

c) What can result, if acetylene has direct contact with unalloyed copper?

Answer: _____

Refer to P.5

d) An acetylene cylinder is used in the _____ position.

Refer to P.5

e) Why are Acetylene cylinders fitted with safety devices called fusible plugs?

Answer: _____

Refer to P.5

f) To avoid the risk of explosion, acetylene cylinders are filled to a maximum pressure of:

Answer: _____ kPa..

Refer to P.5

g) Acetylene regulators are set to a maximum working gauge pressure of _____ kPa..

Refer to P.5

h) Acetylene cylinders are colour coded _____.

Refer to P.5

OXY/ACETYLENE PRINCIPLES AND SAFETY OPERATIONS

These exercises will help you revise what you've learnt in **learning outcome 1**. If you are having difficulty in understanding or answering any exercises then ask your teacher for help.

Exercises

OXY/ACETYLENE COMBINATION

a) The oxy/acetylene chemical combination produces a flame temperature of approximately _____ °C.

Answers
↓

b) The oxy/acetylene chemical flame combination produces a flame temperature which is what in commercial use?

Refer to P.4

Answer: _____

c) The automotive industry uses the oxy/acetylene process to aid in the service and repair of which vehicles?

Refer to P.4

Answer: _____

Refer to P.4

PERSONAL PROTECTIVE CLOTHING AND EQUIPMENT

a) List the safety items of personal protective clothing and equipment to be worn when oxy/acetylene heating operations are to be carried out?

Answers: 1. _____ 2. _____
3. _____ 4. _____
5. _____

Refer to P.6

b) List the safety items of personal protective clothing and equipment to be worn when oxy/acetylene welding or cutting operations are to be carried out?

Answers: 1. _____ 2. _____
3. _____ 4. _____
5. _____ 6. _____

Refer to P.6

ASSEMBLY PROCEDURES FOR OXY/FUEL GAS EQUIPMENT

These exercises will help you revise what you've learnt in **learning outcome 1**. If you are having difficulty in understanding or answering any exercises then ask your teacher for help.

Exercises

Answers
↓

a) Why are oxygen and fuel gas cylinders placed securely together before they are used?

Answer: _____

Refer to P.7

b) How does the operator ensure dust or dirt is removed from:

Answers:

An oxygen cylinder valve _____

An acetylene cylinder valve _____

Refer to P.7

c) All connections used for oxygen use a thread type of:

Answer: _____

Refer to P.7

d) All connections used for acetylene use a type thread of:

Answer: _____

Refer to P.7

e) What is the maximum number of turns each cylinder valve should be opened?

Answer: _____

Refer to P.7

f) During the purging of each hose, you must not carry out this operation in the presence of _____

Refer to P.7

g) After purging each hose, the operator connects the free ends of the oxygen and acetylene hoses to the _____

Refer to P.7

POTENTIAL DAMAGE TO VEHICLE COMPONENTS CAUSED BY WELDING

These exercises will help you revise what you've learnt in **learning outcome 1**. If you are having difficulty in understanding or answering any exercises then ask your teacher for help.

ExercisesAnswers
↓

- a) Metal joining problems arising in the automotive industry are often solved by what welding processes?

Answer: _____
Refer to P.12

- b) How is damage caused to electrical/electronic component parts, by welding on automotive vehicles?

Answer: _____
Refer to P.12

- c) List six (6) different electrical/electronic component parts which can be damaged by welding?

Answers: 1. _____ 2. _____
3. _____ 4. _____
5. _____ 6. _____

Refer to P.12

- d) Names three (3) different types of steels that are used in the construction and design of a automotive vehicle?

Answers: 1. _____
2. _____
3. _____

Refer to P.13

- e) Is welding of these steels recommended?

Answer: _____
Refer to P.13

- f) If no proper precautions were taken during welding of painted parts and plastic materials, what would the effect be on:

1. the surface? _____
2. the operator? _____

Refer to P.13

DAMAGE PREVENTION METHODS

These exercises will help you revise what you've learnt in **learning outcome 1**. If you are having difficulty in understanding or answering any exercises then ask your teacher for help.

ExercisesAnswers
↓

- a) Name two (2) methods in which a container may be freed of a flammable solid, liquid, gas or dust?

Answer: 1. _____
2. _____

Refer to P.15

- b) What two additional safety measures, should be applied before welding, heating or cutting operations are carried out on cleaned containers?

Answer: 1. _____
2. _____

Refer to P.15

- c) Can degreasing agents be added to the water if they have no corrosive effect on the container?

Answer: Yes. No.

Refer to P.15

- d) Should filler caps and drain plugs be removed from the container before cleaning?

Answer: Yes. No.

Refer to P.15

- e) If there is a need to disconnect, remove, shield, clean and replace component parts, how would you achieve this?

Answer: _____

Refer to P.16

- f) Referring to the above question, what may this involve?

Answer: _____

Refer to P.16

HEAT ON AUTOMOTIVE COMPONENT PARTS

Introduction

During this learning outcome you will perform the procedures involved in using heat on automotive component parts to affect their assembly or disassembly without damage. In order for you to complete this learning outcome you will need to have the knowledge to determine, understand and apply practical application in temperature measurement, heating affect, heat for the removal of components and shrink fitting.

Temperature Measurement

Temperature is the degree of hotness or coldness measured in respect to an arbitrary zero in the celsius scale.

Our sense of determining hotness by touch is extremely inaccurate, since metal will always feel colder than plastic, for example, even when actually at the same temperature.

Two methods used in the automotive industry to accurately determine temperature are:

Temperature crayons

The operator selects the appropriate crayon and makes a mark on the workpiece, if the work is at the required temperature the mark changes colour. These are available in a range from 30°C to 1650°C.

Contact thermometer

These devices are in common use, i.e. body temperature (medical), atmospheric temperature, home heating systems, cooking and engine temperatures. The thermometer is meant for use in the range of ice to steam. (Up to 330°C.)

One other relatively accurate way to determine temperature is the use of a pine match, which chars at a temperature of 335°C. This method is normally associated with the use in aluminium and aluminium alloys.

Heating Effect

In general when a body receives heat its temperature rises and when heat is taken away its temperature falls.

When a solid receives sufficient heat it will melt to produce a liquid. If the substance continues to receive heat it will eventually boil and produce a gas.

The metals metallurgical character is affected by heat and character changes are accelerated when the temperature is raised.

Alloy steel, hardened steel and non-ferrous metals can suffer character change if the temperature rise is too high. This may result in the loss of mechanical properties by either hardening or softening the base metal.

To further complicate matters it is quite often the situation where distortional problems occur from too large an heat input.

Heat for the Removal of Components

Metals expand when heated and contract when cooled, i.e. A specimen of low carbon steel, if not restrained in any way, will increase its dimensions in all directions .000012 times the original dimensions for every degree Celsius the temperature rises. On cooling the dimensions will decrease a similar amount, so restoring the specimen to its original size and shape before heating. The figure .000012 is called the **coefficient of linear expansion** for low carbon steel, and is used to calculate the expansion of a specimen of low carbon steel of any unit of length, and at any desired rise in temperature.

HEAT ON AUTOMOTIVE COMPONENT PARTS

Stud Removal: Demonstration by teacher only on the application of heat for stud removal.

BEARING RETAINING RING


Oxy/acetylene Information

Oxygen and Acetylene regulator pressures: 50 kPa

Heating Tip Size: 15

Flame Setting: Neutral

Cone Length: 10mm



Procedure

1. Place retaining ring on refractory brick.
2. Select temperature crayon (200°C) and mark the retaining ring.
3. Apply pre-heat to retaining ring until marks change colour.
4. Slide the retaining ring onto the axle.
5. Press the retaining ring to the bearing face.

Precautions

1. Wear eye protection during heating and pressing operations.
2. There must be no space between the bearing and the retaining ring after pressing.
3. Do not quench the job after completion.

FLYWHEEL RING GEAR

Oxy/acetylene Information


Oxygen regulator pressure: 85 kPa.

Acetylene regulator pressure: 100 kPa.

Heating Tip Size: 20

Flame Setting: Neutral

Cone Length: 25mm



Procedure

1. Uniformly heat ring gear until it is expanded enough to be removed.
2. Place new ring gear on refractory bricks.
3. Select temperature crayon (240°C.) and mark the ring gear.
4. Apply pre-heat to ring gear until marks change colour.
5. Locate ring gear to flywheel and tap into place.

Precautions

1. Wear eye protection during this operation.
2. Do not overheat the ring gear as the teeth will be softened.
3. Do not quench the job after completion.

COMPARE TEMPERATURE MEASUREMENT OPTIONS

These exercises will help you revise what you've learnt in **learning outcome 2**. If you are having difficulty in understanding or answering any exercises then ask your teacher for help.

Exercises

- a) Temperature is a degree of measure in what arbitrary zero value?

Answer: _____

Answers
↓

Refer to P.23

- b) Name two methods used in the automotive industry to accurately determine temperature?

Answer: 1. _____
2. _____

Refer to P.23

HEATING EFFECT ON MECHANICAL PROPERTIES AND METAL DISTORTION

Exercises

- a) What is likely to occur if the temperature rise is too high for alloy steel, hardened steel or non-ferrous metal?

Answer: _____

Answers
↓

Refer to P.23

- b) If too large an heat input is applied, this will quite often result in a situation where what occurs?

Answer: _____

Refer to P.23

- c) Metals when heated, if not restrained in any way, will increase in dimensions for every degree Celsius the temperature rises. What is the name given to this figure?

Answer: _____

Refer to P.23

HEAT SHRINKING AND STUD REMOVAL PROCEDURES

These exercises will help you revise what you've learnt in **learning outcome 2**. If you are having difficulty in understanding or answering any exercises then ask your teacher for help.

Exercises

- A) List four (4) items of personal protective clothing and equipment required to be worn when carrying out heating operations?

Answer: 1. _____ 2. _____
3. _____ 4. _____

Answers
↓

Refer to P.6 7292G-1

- b) What type of flame setting is required when carrying out heating operations?

Answer: _____

Refer to P.24

- c) If overheating of the occurs, what will happen to the ring gear teeth?

Answer: _____

Refer to P.24

- d) What is not recommended after completion of the job?

Answer: _____

Refer to P.24

- e) One method used to remove a manifold stud from a cylinder head is by the _____

Refer to P.24

OXY/ACETYLENE LAP WELDING ON LOW CARBON STEEL SHEET

Introduction

During this learning outcome you will perform the procedures involved in using the oxy/acetylene welding process to lap weld 1.6mm low carbon steel sheeting. In order to complete this learning outcome you will need to have an knowledge to identify a range of weld joints and preparations.

Welding Terminology

The practical application of the oxy/acetylene process is greatly assisted by placing the work in the most convenient position, but the actual strength of the joint depends on the type of weld. This is controlled by the angles formed by the parts to be joined. If these parts meet on the same plane, they can be joined completely, by depositing the weld metal through the full section of the joint. This is not always possible especially if the parts meet on opposing planes and a different type of weld is employed. The types of welds in common use for the joints described are known as:

Fillet Welds

A connection between the end or edge of one part and the face of the other part, which is triangular in cross-section.


Butt Welds

A connection between the ends or edges of two parts abutting each other in a straight line.


Joint Preparations

The following joint preparations are used with the oxy/acetylene process and are varied reliant to the position, type of weld and plate thickness.

Fillet Joints



Butt Joints



Weld Sizes

Fillet and butt welded joints are designed for the purpose of carrying certain loads in service. A great deal of welding is used on parts and structures which are either unstressed or very highly stressed. If the welding operator deposits an undersize or oversize weld on the work, it must be understood there is the possibility for the weld to fail in service. In order to offset this, it may involve such items as the checking of the blowpipe size, gas pressures in use, Type and size of filler rod, correct welding technique and any other matters which affect the quality of the welded joint.

OXY/ACETYLENE LAP WELDING OF 1.6mm LOW CARBON STEEL


Oxy/acetylene Information

Oxygen and Acetylene Regulator Pressures: 50 kPa.

Welding Tip Size: 8

Flame Setting: neutral

Cone Length: 5 - 6mm




Oxy/acetylene Welding Technique

Method: Forehand Filler Rod Dia.: 1.6mm

Torch Angle: 50° - 60° Filler Rod Angle: 30° - 40°

Distance of cone from material surface: 1.6 - 3mm



Procedure

1. Overlap the metal parts to be joined a minimum of 8mm.
2. Place tack welds on one side spaced 25mm apart.
3. After tacking the first side, place the job on an anvil and lightly tap the tack welds to align the metal surfaces closely together.
4. On the opposite side finish tacking. This will minimise distortion during welding.
5. Before commencing to complete the joint, ensure the metal surfaces are closely aligned.
6. During the welding operation make sure the filler rod is kept up to the molten pool.

Precautions

1. Personal protective clothing and equipment must be worn.
2. Oxy goggles must be fitted with an approved lens. (shade 5 GW)
3. Do not use a match or a gas lighter to light the torch.
4. Do not walk away from the work bench without turning the torch off.

Remember: It is your responsibility to exercise REASONABLE CARE when working and using workshop tools and equipment.

OXY/ACETYLENE LAP WELDING ON LOW CARBON STEEL

These exercises will help you revise what you've learnt in **learning outcome 3**. If you are having difficulty in understanding or answering any exercises then ask your teacher for help.

Exercises**Answers**
↓

- a) List six (6) items of personal protective clothing and equipment required to be worn when carrying out welding operations?

Answers: 1. _____ 2. _____
3. _____ 4. _____
4. _____ 6. _____

Refer to P.6 7292G-1

- b) Name two types of joints used for the welding of steels?

Answers: 1. _____
2. _____

Refer to P.27

- c) What type of flame setting is required to be used when lap welding low carbon steel?

Answer: _____

Refer to P.28

- d) State the type of welding method used to join 1.6mm low carbon steel?

Answer: _____

Refer to P.28

- e) Oxy/acetylene welding goggles must be fitted with an approved lens. What shade lens is recommended for use with this process?

Answer: _____

Refer to P.28

OXYGEN - FUEL GAS CUTTING PROCESS**Introduction**

During this learning outcome you will preforming the procedures required in using the oxygen - fuel gas cutting process to cut 6mm low carbon steel plate.

In order to complete this learning outcome you will need to have the knowledge of how oxidation is applied to cut ferrous metals.

Principles of Flame Cutting

The flame cutting process used for cutting iron and steel is dependent on a chemical reaction between heated iron and oxygen.

The steps in the flame cutting action are as follows:

- (a) The flame is used to raise a small section of the metal to ignition temperature. The ignition temperature for low carbon steel is about 815°C.
- (b) The high speed jet of oxygen is released on the heated section.
- (c) Rapid oxidation, or burning of the metal occurs in the path of the oxygen jet.
- (d) The force of the oxygen jet removes the molten oxide from the metal.
- (e) By moving the blowpipe nozzle in the desired direction the oxidising action continues and forms a cut through the metal. In cutting practice this cut through the steel is called the **kerf**.

Types of Fuel Gases

The two most common fuel gases used for manual flame cutting are acetylene and propane. Propane is marketed under trade names such as Handigas, Portagas and Blue Ray gas.

Fuel Gas Hazards

Acetylene - Refer to **Gases used for welding, heating and cutting applications**.

Propane - No attempt should be made to use propane with a cutting blowpipe which is normally used with acetylene. When there is any doubt in this regard the manufacturers of the blowpipe should be consulted.

The method of igniting propane as it issues from the blowpipe nozzle is a little different to the lighting of acetylene.

Oxygen and its Hazards

Refer to **Gases used for welding, heating and cutting applications**.

Oxy/acetylene Cutting Process

Apart from the blowpipe, flame cutting equipment is generally identical to oxy/welding equipment.

Selection of cutting nozzles

A number of factors can affect both the accuracy and the quality of a flame cut surface. Good quality flame cutting results largely from the use of the correct gas pressures and a blowpipe nozzle of suitable size.

To provide guidance, tables need to be consulted for information regarding requirements in relation to different thicknesses of steel, nozzle size and oxygen/acetylene gas pressures.


OXYGEN - FUEL GAS CUTTING PROCESS

Plasma Cutting Process

Plasma is the result of an arc heating a gas to such a high temperature that the gas becomes ionised. At this temperature the gas consists of positive ions, negative electrons and neutral atoms. Plasma is often referred to as the fourth state of matter, the others being gas, liquid and solid.

This process can be applied to the cutting of carbon steels, aluminium, stainless steels, nickel and nickel alloys and many of the hard to cut metals.

With this process there is virtually no distortion, whereas distortion may occur in the oxygen - fuel gas flame cutting process.



OXY - FUEL GAS CUTTING 6mm LOW CARBON STEEL


Oxy/acetylene Information

Oxygen Regulator Pressures: 180 kPa.

Acetylene Regulator Pressure: 100 kPa.

Cutting nozzle Size: 8

Flame Setting: **neutral**



Oxy/acetylene Cutting Technique

1. Raise a small section of the metal to ignition temperature.
2. Release the high speed jet of oxygen onto the heated section.
3. Move the blowpipe in the desired direction and a cut or kerf will appear.

Precautions

1. Personal protective clothing and equipment must be worn.
2. Oxy goggles must be fitted with an approved lens. (shade 5 GW)
3. Do not use a match or a gas lighter to light the torch.
4. Do not walk away from the work bench without turning the torch off.

Note: A number of factors can affect both the accuracy and the quality of a flame cut surface. These may be listed as follows:

- | | |
|--|-----------------------------|
| 1) The composition of the metal. | 2) Cleanliness of the work. |
| 3) Correct selection of blowpipe and cutting nozzle. | 4) Gas pressures. |
| 5) Cleanliness of the blowpipe nozzle. | 6) Correct cutting speed. |

Remember: It is your responsibility to exercise **DUTY OF CARE** when working and using workshop tools and equipment.

OXYGEN - FUEL GAS CUTTING LOW CARBON STEEL

These exercises will help you revise what you've learnt in **learning outcome 4**. If you are having difficulty in understanding or answering any exercises then ask your teacher for help.

Exercises

Answers ↓

- a) List six (6) items of personal protective clothing and equipment required to be worn when carrying out oxygen - fuel gas cutting operations?

Answers: 1. _____ 2. _____
3. _____ 4. _____
4. _____ 6. _____

Refer to P.6 7292G-1

- b) What is the basic principle on which the flame cutting of iron and steel depends?

Answers: _____

Refer to P.30

- c) What type of flame setting is required to be used when oxygen - fuel gas cutting low carbon steel?

Answer: _____

Refer to P.32

- d) State the ignition temperature for low carbon steel?

Answer: _____

Refer to P.30

- e) Name two common fuel gases used for manual flame cutting?

Answer: 1. _____
2. _____

Refer to P.30

- f) Name the type of process used for the cutting of carbon steels, aluminium, stainless steels, nickel and nickel alloys and many of the hard to cut metals?

Answer: _____

Refer to P.31

GAS METAL ARC WELDING PROCESS

Introduction

During this learning outcome you will be performing the procedures required in using the Gas Metal Arc Welding (GMAW) process to join 1.6mm low carbon steel sheet. In order to complete this learning outcome you will need to have the knowledge to identify the component parts and understand how the process operates.

Gas Metal Arc Welding Operating Principles


An electric arc is formed between a continuous wire electrode and the workpiece. Once this is established, the wire is fed at a set speed from a wire spool into the arc to form a weld pool. Both the weld pool and wire electrode are fully protected from atmospheric contamination by a inert shielding gas. The wire, shielding gas and electric current required to form the weld are activated semi-automatically by the operator.

The Gas Metal Arc Welding (GMAW) process is very popular in the automotive industry because of its advantages over other types of welding.

Gas Metal Arc Welding Equipment

The equipment for gas metal arc welding consists of:

- power source (transformer/rectifier)
- wire feed unit (designed to allow the wire to feed freely and evenly)
- wire rollers
- regulator (reduces high cylinder pressure to a safe working pressure)
- flow meter (adjusts and maintains a constant/even gas flow rate)
- gas cylinder
- gas shielding (protects weld from atmospheric contamination)
- contact tip



GAS METAL ARC WELDING PROCESS

GMAW Information

Mode of Transfer: Short Circuit (Dip)


Wire Size: 0.8mm

Arc volts Setting:

Arc Current Setting:

Wire Feed Rate:

Shielding Gas Used: Argoshield 51 (Argon/Helium)



GMAW Technique

1. Overlap the metal parts to be joined a minimum of 8mm.
2. Place tack welds on one side spaced 25mm apart.
3. After tacking the first side, place the job on an anvil and lightly tap the tack welds to align the metal surfaces closely together.
4. On the opposite side finish tacking. This will minimise distortion during welding.
5. Before commencing to complete the joint, ensure the metal surfaces are closely aligned.

Precautions

1. Personal protective clothing and equipment must be worn.
2. Arc welding helmets must be fitted with an approved lens. (shade 10 EW)
3. Do not strike the arc while your face is unprotected from arc radiation.
4. Ensure adequate ventilation is employed to remove harmful fumes.

Remember: It is your responsibility to exercise DUTY OF CARE when working and using workshop tools and equipment.

GAS METAL ARC WELDING OF 1.6mm LOW CARBON STEEL

Exercises will help you revise what you've learnt in **learning outcome 5**. If you are having difficulty understanding or answering any exercises then ask your teacher for help.

Answers ↓

Exercises

List six (6) items of personal protective clothing and equipment required to be worn when carrying out Gas Metal Arc Welding (GMAW) operations?

- Answers: 1. _____ 2. _____
3. _____ 4. _____
4. _____ 6. _____

Refer to P.6 7292G-1

What is the purpose of the wire feed control?

Answers: _____

Refer to P.34

What function does the voltage control have?

Answer: _____

Refer to P.34

d) List four safety hazards associated with the GMA Welding?

- Answer: 1. _____ 2. _____
3. _____ 4. _____

Refer to P.34

e) How is the weld pool and wire electrode protected from atmospheric contamination ?

Answer: _____

Refer to P.34

f) Name a shielding gas which you have used while attending this college for general purpose GMAW of low carbon steel?

Answer: _____

Refer to P.35

MANUAL METAL ARC WELDING PROCESS

Introduction

During this learning outcome you are to describe the procedures required in using the Manual Metal Arc Welding (MMAW) process to join 1.6mm low carbon steel sheet. In order to complete this learning outcome you will be shown a practical demonstration, describing the procedure that is required to lap weld low carbon steel sheet and an explanation on the advantages and disadvantages of using the MMAW process in automotive applications.

Manual Metal Arc Welding


Manual Metal Arc Welding is a fusion welding process which uses the heat of an arc formed between the consumable electrode and the workpiece to melt the joint area. The arc and weld pool are shielded by gases and slag which result from the deposition of the coating material surrounding the electrode. The electrode material is transferred across the arc to fill the joint and must be continuously fed forward by the operator to maintain a constant arc length.

The Manual Metal Arc Welding (MMAW) process is very popular in the automotive industry because its advantages over other types of welding.

Manual Metal Arc Welding Equipment

The equipment for Manual Metal Arc Welding consists of:

- A welding power source (transformer or generator)
- Electrode Holder
- Electrode Cable
- Return Clamp
- Return Cable



MANUAL METAL ARC WELDING PROCESS

MMAW Information


Material Size: 1.6mm low carbon steel

Type of Joint: Lap Joint

Electrode Size: 2.4mm dia.

Current Setting: 45 to 50 ampere

Arc Gap: 2.4mm Max.



MMAW Technique

- Overlap the metal parts to be joined a minimum of 8mm.
- Place tack welds on one side spaced 25mm apart.
- After tacking the first side, place the job on an anvil and lightly tap the tack welds to align the metal surfaces closely together.
- On the opposite side finish tacking. This will minimise distortion during welding.
- Before commencing to complete the joint, ensure the metal surfaces are closely aligned.

Precautions

- Personal protective clothing and equipment must be worn.
- Arc welding helmets must be fitted with an approved lens. (shade 10 EW)
- Do not strike the arc while your face is unprotected from arc radiation.
- Ensure adequate ventilation is employed to remove harmful fumes.

Remember: It is your responsibility to exercise DUTY OF CARE when working and using workshop tools and equipment.

MANUAL METAL ARC WELDING OF 1.6mm LOW CARBON STEEL

These exercises will help you revise what you've learnt in **learning outcome 6**. If you are having difficulty in understanding or answering any exercises then ask your teacher for help.

Exercises**Answers**

↓

- a) List six (6) items of personal protective clothing and equipment required to be worn when carrying out Manual Metal Arc Welding (MMAW) operations?

Answers: 1. _____ 2. _____
3. _____ 4. _____
4. _____ 6. _____

Refer to P.6 7292G-1

- b) List the equipment required for Manual Metal Arc Welding?

Answers: 1. _____ 2. _____
3. _____ 4. _____
5. _____

Refer to P.37

- c) How is the arc and weld pool shielded from atmospheric contamination?

Answer: _____

Refer to P.37

- d) List four safety hazards associated with the MMA Welding?

Answer: 1. _____ 2. _____
3. _____ 4. _____


Refer to P.37

- e) Describe how the electrode material is transferred across the arc to fill the joint in MMAW ?

Answer: _____

Refer to P.37

NSW Module Resource Manual for the National Metal and Engineering Courses



Fabrication
Stream

NF04

Oxyacetylene Welding 1

Student Workbook

Section 12 Braze weld fillet-horizontal

Suggested duration

2 hours

Purpose

To deposit a braze welded fillet in the horizontal position.

Objectives


At the end of this section you should be able to:

- Deposit a braze weld fillet on low carbon steel sheet in the horizontal position to the following requirements
 - correct alignment and assembly
 - smooth regular weld contour
 - angular distortion 0° to 5°
 - an accumulated defect area of less than four times the square of the sheet thickness in each 150mm weld length
 - weld size not less than the material thickness
- Record the weld procedure
- Follow Occupational Health and Safety (OH&S) workshop procedures



- Wear safety glasses.
- Take care when grinding or finishing thin sheet steel.
- Wash your hands after using brazing flux.
- Take care when you hold thin sheet steel for grinding.


Skill practice NF04-SP10
Competency test NF04-CT8 Learning outcome 3



- 20 minutes
- To braze weld low carbon sheet steel to the specifications listed below.
- 1 piece 50 x 1.6 x 150mm low carbon steel
 - 1 piece 25 x 1.6 x 150mm low carbon steel
- 3
- Ø1.6mm or 2.5mm manganese bronze
- Number 8 or 10
- Copper and brass flux
- Join all short ends of filler rods
- Horizontal
1. Finish bonding surfaces of the steel to improve tinning properties
 2. Tack weld the sheet
 3. Flux the joint and/or filler rod and complete the weld
 4. The tip is moved forward and back along the joint to allow the bronze filler to flow smoothly through out the joint
 5. Show your work to your teacher
 6. Repeat the exercise using the second sheet as shown
 7. Show your work to your teacher
 8. Complete your procedure sheet
 9. For assessment repeat the task using the control data on the procedure sheet
- correct alignment and assembly
 - smooth regular weld contour
 - angular distortion 0°-5°
 - an accumulated defect area of less than four times the square of the sheet thickness in each 150mm weld length
 - weld size - not less than the material thickness

Skill practice NF04-SP10 Braze weld fillet, horizontal
Competency test NF04-CT8 Learning outcome 3

Procedure sheet



Complete the control data table below:


Gas data regulator pressure: O ₂ _____ C ₂ H ₂ _____ flame type: weld tip size:		Consumables data filler type: filler diameter: flux: angles: torch: rod:	
Material data type: thickness:		Weld time start: finish:	

Assessment

You will be assessed on your ability to meet the following specifications:

- correct alignment and assembly
- smooth regular weld contour
- angular distortion 0°-5°
- an accumulated defect area of less than four times the square of the sheet thickness in each 150mm weld length
- weld size not less than the material thickness

Skill practice NF04-SP10
Competency test NF04-CT8 Learning outcome 3




Braze weld fillet - horizontal (formal assessment)

Total time	2 hours
Assessment	20 minutes
Task	To braze weld low carbon sheet steel to the specifications listed below.
Material	1 piece 50 x 1.6 x 150mm low carbon steel 1 piece 25 x 1.6 x 150mm low carbon steel
Units	3
Filler rod	Ø1.6mm or 2.5mm manganese bronze
Tip size	Number 8 or 10
Flux	Copper and brass flux
Economy	Join all short ends of filler rods
Position	Horizontal
Instructions	1. Linish bonding surfaces of the steel to improve tinning properties 2. Tack weld the sheet 3. Flux the joint and/or filler rod and complete the weld 4. The tip is moved forward and back along the joint to allow the bronze filler to flow smoothly through out the joint 5. Show your work to your teacher 6. Repeat the exercise using the second sheet as shown 7. Show your work to your teacher 8. Complete your procedure sheet 9. For assessment repeat the task using the control data on the procedure sheet
Specifications	<ul style="list-style-type: none">correct alignment and assemblysmooth regular weld contourangular distortion 0°-5°an accumulated defect area of less than four times the square of the sheet thickness in each 150mm weld lengthweld size - not less than the material thickness

Skill practice NF04-SP10 Braze weld fillet, horizontal
Competency test NF04-CT8 Learning outcome 3

Procedure sheet



Complete the control data table below:

Gas data regulator pressure: O ₂ _____ C ₂ H ₂ _____ flame type: weld tip size:	Consumables data filler type: filler diameter: flux: angles: torch: rod:
Material data type: thickness:	Weld time start: finish:

Assessment




You will be assessed on your ability to meet the following specifications:

- correct alignment and assembly
- smooth regular weld contour
- angular distortion 0°-5°
- an accumulated defect area of less than four times the square of the sheet thickness in each 150mm weld length
- weld size not less than the material thickness

Braze weld fillet - horizontal (formal assessment)**Total time** 2 hours**Assessment** 20 minutes**Task** To braze weld low carbon sheet steel to the specifications listed below.**Material**
1 piece 50 x 1.6 x 150mm low carbon steel
1 piece 25 x 1.6 x 150mm low carbon steel**Units** 3**Filler rod** \varnothing 1.6mm or 2.5mm manganese bronze**Tip size** Number 8 or 10**Flux** Copper and brass flux**Economy** Join all short ends of filler rods**Position** Horizontal

- Instructions**
1. Finish bonding surfaces of the steel to improve tinning properties
 2. Tack weld the sheet
 3. Flux the joint and/or filler rod and complete the weld
 4. The tip is moved forward and back along the joint to allow the bronze filler to flow smoothly through out the joint
 5. Show your work to your teacher
 6. Repeat the exercise using the second sheet as shown
 7. Show your work to your teacher
 8. Complete your procedure sheet
 9. For assessment repeat the task using the control data on the procedure sheet

- Specifications**
- correct alignment and assembly
 - smooth regular weld contour
 - angular distortion 0° - 5°
 - an accumulated defect area of less than four times the square of the sheet thickness in each 150mm weld length
 - weld size - not less than the material thickness



Method of attachment
for maximum material use

Notes


Section 13 Braze weld lap joint-flat

Suggested duration	1 hour
Purpose	To deposit a braze welded lap joint in the flat position.
Objectives	At the end of this section you should be able to: <ul style="list-style-type: none"> ▪ Deposit a braze weld on a lap joint in the flat position on low carbon steel sheet to the following requirements <ul style="list-style-type: none"> - correct alignment and assembly - smooth regular weld contour - an accumulated defect area of less than four times the square of the sheet thickness in each 150mm weld length - weld size not less than the material thickness ▪ Record the weld procedure ▪ Follow Occupational Health and Safety (OH&S) workshop procedures



- **Wear safety glasses when grinding or finishing eliminate "plate".**
- Oxygen and acetylene cylinders should always be opened slowly.
- Suitable protective oxy-goggles must always be worn when cutting or welding.
- Always be careful when cooling welds by quenching, especially welded pipes.
- Take care when you hold thin sheet steel for finishing.

Skill practice NF04-SP11
Competency test NF04-CT9 Learning outcome 3




Braze weld lap joint, flat

Total time	1 hours
Assessment	20 minutes
Task	To braze weld low carbon sheet steel to the specification listed below.
Material	2 pieces 50 x 2.5 x 150mm low carbon steel
Units	3
Filler rod	Ø1.6mm or 2.5mm manganese bronze
Tip size	Number 8 or 10
Flux	Copper and brass flux
Economy	Join all short ends of filler rods
Position	Flat
Instructions	<ol style="list-style-type: none">1. Linish bonding surfaces of the steel to improve tinning properties2. Locate steel as per sketch and tack weld3. Flux the joint and/or filler rod and complete the weld4. The tip is moved forward and back along the joint to allow the bronze filler to flow smoothly through out the joint5. Show your work to your teacher6. Repeat the exercise7. Show your work to your teacher8. Complete your procedure sheet9. For assessment repeat the task using the control data on the procedure sheet
Specifications	<ul style="list-style-type: none">correct alignment and assemblysmooth regular weld contourangular distortion 0°-5°an accumulated defect area of less than four times the square of the sheet thickness in each 150mm weld lengthweld size - not less than the material thickness

Skill practice NF04-SP11 Braze weld lap joint, flat
Competency test NF04-CT9 Learning outcome 3

Procedure sheet



Complete the control data table below:

Gas data regulator pressure: O ₂ _____ C ₂ H ₂ _____ flame type: weld tip size:	Consumables data filler type: filler diameter: flux: angles: torch: rod:
Material data type: thickness:	Weld time start: finish:

Assessment

You will be assessed on your ability to meet the following specifications:

- correct alignment and assembly
- smooth regular weld contour
- angular distortion 0°-5°
- an accumulated defect area of less than four times the square of the sheet thickness in each 150mm weld length
- weld size not less than the material thickness

Notes

Section 14 Braze weld tube-flat

Suggested duration

3 hours

Purpose

To deposit a braze weld on tubular branch section.

Objectives


At the end of this section you should be able to:

- Deposit a braze weld on tubular branch sections in the flat position to the following requirements
 - correct alignment and assembly
 - smooth regular weld contour
 - angular distortion 0° to 5°
 - an accumulated defect area of less than four times the square of the tube thickness in each 150mm weld length
 - weld size not less than the material thickness
- Record the weld procedure
- Follow Occupational Health and Safety (OH&S) workshop procedures



- Wear proper eye protection.
- Take care when grinding or finishing thin sheet steel
- Wash your hands after using brazing flux
- It is important to have good ventilation or use a respirator when braze welding


Skill practice NF04-SP12
Competency test NF04-CT10 Learning outcome 3



Braze weld tube - flat	
Total time	3 hours
Assessment	30 minutes
Task	To braze weld low carbon tube to the specification listed below.
Material	1 pieces Ø32 NB tube x 300mm
Units	3
Filler rod	Ø1.6mm or 2.5mm manganese bronze
Tip size	Number 8 or 10
Flux	Copper and brass flux
Economy	Join all short ends of filler rods
Position	Flat and rotated
Instructions	<ol style="list-style-type: none"> 1. Mark out, cut and file branch to fit tube. 2. Clean and degrease tube 3. Assemble and tack weld branch to tube 4. Flux the joint and/or filler rod and complete the weld 5. Complete your procedure sheet 6. For assessment repeat the task using the control data on the procedure sheet
Specifications	<ul style="list-style-type: none"> ■ correct alignment and assembly ■ smooth regular weld contour ■ angular distortion 0°-5° ■ an accumulated defect area of less than four times the square of the tube thickness in each 150mm weld length ■ weld size - not less than the material thickness

Skill practice NF04-SP12 Braze weld tube-flat
Competency test NF04-CT10 Learning outcome 3

Procedure sheet



Complete the control data table below:

Gas data regulator pressure: O ₂ _____ C ₂ H ₂ _____ flame type: weld tip size:		Consumables data filler type: filler diameter: flux: angles: torch: rod:	
Material data type: thickness:		Weld time start: finish:	

Assessment

You will be assessed on your ability to meet the following specifications:

- correct alignment and assembly
- smooth regular weld contour
- angular distortion 0°-5°
- an accumulated defect area of less than four times the square of the tube thickness in each 150mm weld length
- weld size not less than the material thickness

Section 15

Butt weld cast iron-braze weld-semi vertical

Suggested duration

2 hours

Purpose

To deposit a braze weld on grey cast iron in the semi vertical position.

Objectives

At the end of this section you should be able to:



- Deposit a braze weld on grey cast iron in the semi-vertical position to the following requirements
 - correct alignment and assembly
 - smooth regular weld contour
 - angular distortion 0° to 5°
 - an accumulated defect area of less than the square of the material thickness in each 150mm weld length
 - weld penetration for a minimum of 20% of the weld length.
 - weld size - not less than the material thickness
- Record the weld procedure
- Follow Occupational Health and Safety workshop procedures




- Always make sure you have proper ventilation when you're welding.
- Never stand directly in front of the oxygen cylinder valve when you're opening the cylinder.
- Never allow a gas cylinder near an electric arc or flame, as it may explode.

Technical information

Cast iron braze welding applications




Cast iron braze weld



Brazing steel tube

Skill practice NF04-SP13

Competency test NF04-CT11 Learning outcome 3



Butt weld cast iron - braze weld - semi vertical

Total time	2 hours
Assessment	30 minutes
Task	To butt weld grey cast iron with the braze welding process to the specifications listed below
Material	2 pieces 38 x 12 x 130mm grey cast iron coupons
Units	2
Filler rod	Ø3, 5 or 6mm manganese bronze
Tip size	Number 12 (1.2mm) or 15 (1.5mm)
Flux	Bronze flux
Economy	Join all short ends of filler rods
Position	Semi-vertical
Instructions	<ol style="list-style-type: none"> 1. File bonding faces to remove impurities and the oxide layer 2. Assemble and tack coupons at each end 3. Incline the coupons in a semi-vertical position and lightly pre-heat 4. Build a bronze ledge at the base of the preparation and commence to weld 5. After completion, fracture the casting through the weld and examine for bond and internal defects 6. Show your work to your teacher 7. Complete your procedure sheet 8. For assessment repeat the task using the control data on the procedure sheet
Specifications	<ul style="list-style-type: none"> correct alignment and assembly smooth regular weld contour angular distortion 0°-5° an accumulated defect area of less than the square of the material thickness in each 150mm weld length weld penetration for a minimum of 20% of the weld length weld size - not less than the material thickness