


Welding

Welding

Welding is a process of joining two pieces of metal by heating them to a high temperature and then cooling them to form a strong bond.

1. Electric welding
2. Gas welding
3. Cutting with gas



metallurgy
Electrical
framing
maths
machine


fittling - arrangement of parts
welding - joining of parts
machine - cutting of parts

Welding temperature $7000^{\circ}\text{F} \rightarrow 10000^{\circ}\text{F}$

1. Arc welding (Electric welding)
2. Gas cutting (Gas welding)
Oxygen + Acetylene

3. Machine cutting
Welding (Gas welding filter)

3. Gas welding (Gas welding)
 $\text{O}_2 + \text{C}_2\text{H}_2$
(Acetylene)
Electrical





$7000^{\circ}\text{F} \rightarrow 10000^{\circ}\text{F}$

welding electrode size - of 1/8" of current (ampere) in 1/2"

(2) Gas welding is used for joining of parts in pressure oil pipe up to 1000 psi.

(1) Gas welding is used for joining of parts in pressure oil pipe up to 1000 psi.



(1) Part

Part: 2 parts: 1st: 62%

(2) Part

(1) Part: 62%


(2) Part: 62%

(3) Part: 62%

(4) Part: 62%

(5) Part

Part: 62%



Part: 62%

Part: 62%

Part: 62%

Part: 62%

Part: 62%

welding machine of 62% volt of 62% amp of 62%

bottom | Engine room of 62% 2000watt 2000watt

7000watt 2000watt 2000watt

Part: 62%

Part: 62%

Part: 62%

Part: 62%

Part: 62%

Part: 62%

Part: 62%

Part: 62%

Part: 62%

Part: 62%

Part: 62%

Part: 62%

Part: 62%

Part: 62%

Part: 62%


Part: 62%

Part: 62%

Part: 62%

[illegible]

- welding on: overgr. 2nd 6 months in 7th and 8th Oct 1 power on
 (?) overgr. diff. in 6th and 7th Nov overgr. 1st and 2nd glass
 - overgr. 2nd 6 months in 7th and 8th Oct 5. 2nd Oct



1. The first part of the document is a list of items, including:


- 1. The first part of the document is a list of items, including:
- 2. The second part of the document is a list of items, including:
- 3. The third part of the document is a list of items, including:
- 4. The fourth part of the document is a list of items, including:
- 5. The fifth part of the document is a list of items, including:
- 6. The sixth part of the document is a list of items, including:
- 7. The seventh part of the document is a list of items, including:
- 8. The eighth part of the document is a list of items, including:
- 9. The ninth part of the document is a list of items, including:
- 10. The tenth part of the document is a list of items, including:

[illegible]

cast steel trans - Q: on ~~the~~ of 1000: 1200 x 4000

Boiler suit of 7 1/2: 25 out on: 11 1/2 over 12: 25 out on: 11 1/2
out 11

(5/9) म. १७. ७१. ७२. ७३. ७४. ७५. ७६. ७७. ७८. ७९. ८०.

[illegible][illegible]

① താഴെ ഉൾപ്പെടെ: 24

② non-mut. egg stored in 70% Glycerol


③ 4. 6. 8. 10. 12. 14. 16. 18. 20. 22. 24. 26. 28. 30. 32. 34. 36. 38. 40. 42. 44. 46. 48. 50. 52. 54. 56. 58. 60. 62. 64. 66. 68. 70. 72. 74. 76. 78. 80. 82. 84. 86. 88. 90. 92. 94. 96. 98. 100.




O_2 C_2H_2
Chemical reactions involving oxygen

Write the balanced chemical equations for the following reactions:

- ① Magnesium reacts with oxygen to form magnesium oxide.
- ② Carbon reacts with oxygen to form carbon dioxide.
- ③ Iron reacts with oxygen to form iron oxide.



(Oxygen)



(Acetylene)

- ③ Write the balanced chemical equations for the following reactions:

- ③ Write the balanced chemical equations for the following reactions:

Write the balanced chemical equations for the following reactions:

- ① Magnesium reacts with oxygen to form magnesium oxide.
- ② Carbon reacts with oxygen to form carbon dioxide.
- ③ Iron reacts with oxygen to form iron oxide.




Acetone (2-methylpropan-2-ol)

- ④ Write the balanced chemical equations for the following reactions:

- ④ Write the balanced chemical equations for the following reactions:

- ④ Write the balanced chemical equations for the following reactions:



A hand-drawn diagram of a simple microscope. It consists of a circular object on the left, connected by a horizontal tube to a rectangular eyepiece on the right. The eyepiece is labeled 'A' and 'B'.

① ΔH_{comb} is a measure of the heat of combustion of a substance.
② ΔH_{comb} is a measure of the heat of combustion of a substance.

act: 170 call ABN, 145, 1006 more and for
Short date 6/6/08
any day in Prof. 2/2/08

2.11 7 mms diameter: 24; But 1/2 inch 24
 1/4 O₂ cylinder 24; 1/2: 24; 3/4: 24; 1 inch: 24; 1 1/2 inch: 24; 2 inch: 24
 1/2 inch: 24.


478; 24000000, 24000000.

gives rise to a new set of variables, $\{x_i, y_i\}$, which are the coordinates of the points in the new space.

၆။ အောက်ဖော်ပြပါအတိုင်း ဖြေဆိုပါ။
 ၇။ အောက်ဖော်ပြပါအတိုင်း ဖြေဆိုပါ။

225 (3)

Topic: Electric welding




Arceuthobium

29. 5621

Major component of: (Ave) Glycolic acid

Proof: Let us assume gas was in equilibrium.

Electrode (-) is more active than (+) electrode




Welding of (one half)


Welding is done by means of electric arc. It is a process of joining two metal parts by heating them to a temperature above their melting point. The heat is generated by an electric arc between an electrode and the workpiece. The electrode is a consumable metal rod that melts and forms part of the weld metal. The workpiece is the metal to be joined. The process is used for joining metal parts in a variety of applications, including construction, manufacturing, and repair work.

One half of the workpiece is heated by the electric arc.

1. The workpiece is heated by the electric arc.
2. The electrode is melted and forms part of the weld metal.
3. The workpiece is joined to the electrode.
4. The workpiece is cooled and the weld metal solidifies.



Welding of (spatter)



Welding is done by means of electric arc. It is a process of joining two metal parts by heating them to a temperature above their melting point. The heat is generated by an electric arc between an electrode and the workpiece. The electrode is a consumable metal rod that melts and forms part of the weld metal. The workpiece is the metal to be joined. The process is used for joining metal parts in a variety of applications, including construction, manufacturing, and repair work.

1. Arc blow is a phenomenon that occurs when the arc is deflected from the electrode to the workpiece.
2. Arc blow is caused by the magnetic field of the arc.
3. Arc blow can be prevented by using a non-magnetic electrode.
4. Arc blow can be prevented by using a non-magnetic workpiece.

பெரிய

- ① அளவுகோல்
- ② அளவுகோல்
- ③ அளவுகோல்
- ④ அளவுகோல்


அளவுகோல்

① அளவுகோல்

② அளவுகோல்

③ அளவுகோல்

④ அளவுகோல்



- ① அளவுகோல்
- ② அளவுகோல்
- ③ அளவுகோல்
- ④ அளவுகோல்
- ⑤ அளவுகோல்
- ⑥ அளவுகோல்

பெரிய அளவுகோல்

- ① அளவுகோல்
- ② அளவுகோல்

- ③ அளவுகோல்
- ④ அளவுகோல்

- ⑤ அளவுகோல்
- ⑥ அளவுகோல்

⑦ அளவுகோல்

⑧ அளவுகோல்


- ⑨ அளவுகோல்
- ⑩ அளவுகோல்
- ⑪ அளவுகோல்
- ⑫ அளவுகோல்
- ⑬ அளவுகோல்
- ⑭ அளவுகோல்
- ⑮ அளவுகோல்
- ⑯ அளவுகோல்
- ⑰ அளவுகோல்
- ⑱ அளவுகோல்
- ⑲ அளவுகோல்
- ⑳ அளவுகோல்
- ㉑ அளவுகோல்
- ㉒ அளவுகோல்
- ㉓ அளவுகோல்
- ㉔ அளவுகோல்
- ㉕ அளவுகோல்
- ㉖ அளவுகோல்
- ㉗ அளவுகோல்
- ㉘ அளவுகோல்
- ㉙ அளவுகோல்
- ㉚ அளவுகோல்
- ㉛ அளவுகோல்
- ㉜ அளவுகோல்
- ㉝ அளவுகோல்
- ㉞ அளவுகோல்
- ㉟ அளவுகோல்
- ㊱ அளவுகோல்
- ㊲ அளவுகோல்
- ㊳ அளவுகோல்
- ㊴ அளவுகோல்
- ㊵ அளவுகோல்
- ㊶ அளவுகோல்
- ㊷ அளவுகோல்
- ㊸ அளவுகோல்
- ㊹ அளவுகோல்
- ㊺ அளவுகோல்
- ㊻ அளவுகோல்
- ㊼ அளவுகோல்
- ㊽ அளவுகோல்
- ㊾ அளவுகோல்
- ㊿ அளவுகோல்

The image contains two hand-drawn diagrams illustrating welding circuits. The top diagram is labeled "generator welding set (DC)" and shows an electrode connected to the positive terminal (+) and a workpiece connected to the negative terminal (-). A circular arrow indicates the direction of current flow. The bottom diagram is labeled "Transformer welding set (AC)" and shows an electrode connected to the positive terminal (+) and a workpiece connected to the negative terminal (-). A circular arrow indicates the direction of current flow. Both diagrams include a circular arrow indicating the direction of current flow.

E 6010 AC or DC
 E 6010 AC
 & electric welding


[illegible]

~~De 2nd 1st 2nd 3rd 4th 5th 6th 7th 8th 9th 10th 11th 12th~~

$$2.74 \times 10^4 \text{ g}$$


AC Transistor

~~Dc motor is given supply from AC 2 phase motor
if generator is given supply from AC contact~~



DC Electric supply is 400-6440 VAC voltage is
rectified and then the Transformer is used for
the supply of the AC supply. $AC \rightarrow DC \rightarrow AC \rightarrow DC$

Step down
230-400-440V $\rightarrow$ 25-80V
as per the req.

SEP
Chapters

Working on the side of the circle

Definition

When a circle is cut by a line, the part of the circle which is cut off is called a segment. The line which cuts off the segment is called a secant.

Proof of the theorem



Let a circle be cut by a secant line. Let the part of the circle which is cut off be a segment. Let the line which cuts off the segment be a secant.

Let the center of the circle be O. Let the secant line be AB. Let the segment be ACB. Let the angle AOB be θ .

Let the radius of the circle be r. Let the length of the secant line be s. Let the length of the segment be l.

Let the area of the segment be A. Let the area of the sector be B. Let the area of the triangle be C.

Let the perimeter of the segment be P. Let the perimeter of the sector be Q. Let the perimeter of the triangle be R.



1) A secant line is a line that intersects a circle at two points. The part of the circle which is cut off by the secant line is called a segment. The line which cuts off the segment is called a secant.

2) The area of a segment is the area of the sector minus the area of the triangle. The perimeter of a segment is the length of the arc plus the length of the secant line.

3) The area of a sector is the area of the circle multiplied by the angle in radians divided by 2. The perimeter of a sector is the length of the arc plus the length of the two radii.

generator up: 20000

of generator up: 20000

of generator up: 20000

of generator up: 20000

of generator up: 20000

of generator up: 20000

of generator up: 20000

DC arc - 20000

AC arc - 20000

welding machine, lathe machine

AC - 20000

DC - 20000

Ref: (9)

generator up:

generator up: 20000

① mild steel electrode (M.S. electrode) *

② Broom zoid electrode

③ cast Iron electrode

④ Aluminium electrode

⑤ mild, hardening electrode

⑥ 2-3 electrodes up: 20000

no electrode

* 6 electrodes up: 20000

generator up:

* 6 electrodes up: 20000

oxide outside surface of work piece
 and welding process of CO₂ arc welding
 gas shielded arc welding process
 arc shielded arc welding process

oxidation / overcutting
 X-ray and metal surface analysis

Bronze - 66 - shaft type of engine

Cast Iron - 20% (cast iron engine) type

At - 20% of 100%

AL - 20% of 100%


function of coating

cover coated electrode

20% of 100% mild steel electrode

20% of 100% mild steel electrode
 20% of 100% high carbon steel electrode
 electrode of 20% of 100% stainless steel
 base electrode of 20% of 100% stainless steel
 in 20% of 100% stainless steel electrode

arc - 1. start of arc (undercutting) 2. base
 metal 3. arc 4. surface electric arc 5. 6. 7. 8. 9. 10. 11. 12. 13. 14. 15. 16. 17. 18. 19. 20. 21. 22. 23. 24. 25. 26. 27. 28. 29. 30. 31. 32. 33. 34. 35. 36. 37. 38. 39. 40. 41. 42. 43. 44. 45. 46. 47. 48. 49. 50. 51. 52. 53. 54. 55. 56. 57. 58. 59. 60. 61. 62. 63. 64. 65. 66. 67. 68. 69. 70. 71. 72. 73. 74. 75. 76. 77. 78. 79. 80. 81. 82. 83. 84. 85. 86. 87. 88. 89. 90. 91. 92. 93. 94. 95. 96. 97. 98. 99. 100.




arc - 1. start of arc (undercutting) 2. base
 metal 3. arc 4. surface electric arc 5. 6. 7. 8. 9. 10. 11. 12. 13. 14. 15. 16. 17. 18. 19. 20. 21. 22. 23. 24. 25. 26. 27. 28. 29. 30. 31. 32. 33. 34. 35. 36. 37. 38. 39. 40. 41. 42. 43. 44. 45. 46. 47. 48. 49. 50. 51. 52. 53. 54. 55. 56. 57. 58. 59. 60. 61. 62. 63. 64. 65. 66. 67. 68. 69. 70. 71. 72. 73. 74. 75. 76. 77. 78. 79. 80. 81. 82. 83. 84. 85. 86. 87. 88. 89. 90. 91. 92. 93. 94. 95. 96. 97. 98. 99. 100.

arc - 1. start of arc (undercutting) 2. base
 metal 3. arc 4. surface electric arc 5. 6. 7. 8. 9. 10. 11. 12. 13. 14. 15. 16. 17. 18. 19. 20. 21. 22. 23. 24. 25. 26. 27. 28. 29. 30. 31. 32. 33. 34. 35. 36. 37. 38. 39. 40. 41. 42. 43. 44. 45. 46. 47. 48. 49. 50. 51. 52. 53. 54. 55. 56. 57. 58. 59. 60. 61. 62. 63. 64. 65. 66. 67. 68. 69. 70. 71. 72. 73. 74. 75. 76. 77. 78. 79. 80. 81. 82. 83. 84. 85. 86. 87. 88. 89. 90. 91. 92. 93. 94. 95. 96. 97. 98. 99. 100.

arc - 1. start of arc (undercutting) 2. base
 metal 3. arc 4. surface electric arc 5. 6. 7. 8. 9. 10. 11. 12. 13. 14. 15. 16. 17. 18. 19. 20. 21. 22. 23. 24. 25. 26. 27. 28. 29. 30. 31. 32. 33. 34. 35. 36. 37. 38. 39. 40. 41. 42. 43. 44. 45. 46. 47. 48. 49. 50. 51. 52. 53. 54. 55. 56. 57. 58. 59. 60. 61. 62. 63. 64. 65. 66. 67. 68. 69. 70. 71. 72. 73. 74. 75. 76. 77. 78. 79. 80. 81. 82. 83. 84. 85. 86. 87. 88. 89. 90. 91. 92. 93. 94. 95. 96. 97. 98. 99. 100.


- (1) start of arc (undercutting)
- (2) base metal
- (3) arc
- (4) surface electric arc
- (5) 6. 7. 8. 9. 10. 11. 12. 13. 14. 15. 16. 17. 18. 19. 20. 21. 22. 23. 24. 25. 26. 27. 28. 29. 30. 31. 32. 33. 34. 35. 36. 37. 38. 39. 40. 41. 42. 43. 44. 45. 46. 47. 48. 49. 50. 51. 52. 53. 54. 55. 56. 57. 58. 59. 60. 61. 62. 63. 64. 65. 66. 67. 68. 69. 70. 71. 72. 73. 74. 75. 76. 77. 78. 79. 80. 81. 82. 83. 84. 85. 86. 87. 88. 89. 90. 91. 92. 93. 94. 95. 96. 97. 98. 99. 100.

(1)



horizontal (Down hand) (Flat hand)

(2)




vertical electrode

(3) start of arc (undercutting)


(4) base metal

cost HOB, 800m: 357187 (cont), 26820 2990.

62

 (CH_2)

657



10. 11. 2019

127

[illegible]

millions, lost from all forest life & birds



[illegible]

(5) 1118 m f d r e : f h k o u n o p g s t , j b g o
2 c c z p o u m f i n o t g r e m m o , j o i f h w a n o v


mild steel non alloy - all types : mild : medium : strong (high tensile),
alloyed : mild : strong : non alloyed : mild : medium : strong : very strong
steel

(9) $\frac{1}{2} : \frac{1}{3} :: \frac{1}{4} : \frac{1}{6}$ $\frac{1}{2} : \frac{1}{3} :: \frac{1}{4} : \frac{1}{6}$ $\frac{1}{2} : \frac{1}{3} :: \frac{1}{4} : \frac{1}{6}$
 $\frac{1}{2} : \frac{1}{3} :: \frac{1}{4} : \frac{1}{6}$ $\frac{1}{2} : \frac{1}{3} :: \frac{1}{4} : \frac{1}{6}$ $\frac{1}{2} : \frac{1}{3} :: \frac{1}{4} : \frac{1}{6}$
 $\frac{1}{2} : \frac{1}{3} :: \frac{1}{4} : \frac{1}{6}$ $\frac{1}{2} : \frac{1}{3} :: \frac{1}{4} : \frac{1}{6}$ $\frac{1}{2} : \frac{1}{3} :: \frac{1}{4} : \frac{1}{6}$
 $\frac{1}{2} : \frac{1}{3} :: \frac{1}{4} : \frac{1}{6}$ $\frac{1}{2} : \frac{1}{3} :: \frac{1}{4} : \frac{1}{6}$ $\frac{1}{2} : \frac{1}{3} :: \frac{1}{4} : \frac{1}{6}$

of 60000



of benzene: condensation
 hydrogenation with 6 hydrogen atoms




Ex: $2\text{H}_2\text{O} \rightarrow \text{H}_2 + \text{O}_2$ / Penetration
Ground


1. $\text{Fe} + \text{O}_2 \rightarrow \text{FeO}$ (oxidation)
 2. $\text{Fe} + \text{H}_2\text{O} \rightarrow \text{Fe(OH)}_2$ (hydrolysis)
 3. $\text{Fe} + \text{CO}_2 \rightarrow \text{FeCO}_3$ (carbonation)

4. $\text{Fe} + \text{N}_2 \rightarrow \text{Fe}_3\text{N}_2$ (nitridation)
 5. $\text{Fe} + \text{S} \rightarrow \text{FeS}$ (sulfidation)


6. $\text{Fe} + \text{Si} \rightarrow \text{FeSi}$ (silicification)
 7. $\text{Fe} + \text{Mn} \rightarrow \text{FeMn}$ (manganization)



8. $\text{Fe} + \text{Al} \rightarrow \text{FeAl}$ (aluminization)
 9. $\text{Fe} + \text{Cr} \rightarrow \text{FeCr}$ (chromization)



10. $\text{Fe} + \text{Cu} \rightarrow \text{FeCu}$ (copperization)



11. $\text{Fe} + \text{Zn} \rightarrow \text{FeZn}$ (zinc plating)

12. $\text{Fe} + \text{Ni} \rightarrow \text{FeNi}$ (nickel plating)

13. $\text{Fe} + \text{P} \rightarrow \text{Fe}_3\text{P}$ (phosphorization)

14. $\text{Fe} + \text{B} \rightarrow \text{Fe}_2\text{B}$ (boronizing)

15. $\text{Fe} + \text{C} \rightarrow \text{Fe}_3\text{C}$ (cementation)

16. $\text{Fe} + \text{N} \rightarrow \text{Fe}_4\text{N}$ (nitriding)

17. $\text{Fe} + \text{O} \rightarrow \text{FeO}$ (oxidation)

Alloy Ferro Titanium (75% Fe - 25% Ti)

(a) 6 mm diameter wire gauge

6 mm diameter wire gauge is used for the purpose of measuring the diameter of the wire. The wire is measured at different points along its length to ensure uniformity. The wire is then used for the purpose of making the electrode.

(c) 2 mm diameter wire gauge (for the purpose of measuring the diameter of the wire)

2 mm diameter wire gauge is used for the purpose of measuring the diameter of the wire.

(d) 1 mm diameter wire gauge

1 mm diameter wire gauge is used for the purpose of measuring the diameter of the wire. The wire is then used for the purpose of making the electrode.

The wire is then used for the purpose of making the electrode. The wire is measured at different points along its length to ensure uniformity. The wire is then used for the purpose of making the electrode.

Standard wire gauge size
 Sw G No 10 → steel wire gauge 10 (3.2 mm)
 Sw G No 8 (4 mm) size
 Sw G No 6 (5 mm)

Standard wire gauge size

mm size of 1.5 mm size wire gauge

1.5 mm size wire gauge

(1) 6 mm diameter wire gauge (extraction) - for the purpose of measuring the diameter of the wire

(2) 2 mm diameter wire gauge (extraction with reinforcement) - for the purpose of measuring the diameter of the wire

(3) 1 mm diameter wire gauge (dipping) - for the purpose of measuring the diameter of the wire

(4) 0.5 mm diameter wire gauge (for the purpose of measuring the diameter of the wire)

Winds of Electrodes (for the purpose of measuring the diameter of the wire)

(1) 2 mm diameter wire gauge (Acid Type)

(2) 1 mm diameter wire gauge (cellulose)

(3) 0.5 mm diameter wire gauge (batile)

(4) 0.2 mm diameter wire gauge (Low Hydrogen)

(5) 0.1 mm diameter wire gauge (iron powder contact) for the purpose of measuring the diameter of the wire

Acid Type


(1) 2 mm diameter wire gauge (for the purpose of measuring the diameter of the wire)

Down hand → 6 mm diameter wire gauge
 horizontal fillet - one mm diameter wire gauge

Straight polarity (rod electrode) [electrode (-) work (+)]
 American Welding Society (AWS) "E"

③ Cellulose


① Vertical 6mm y nauri. 300mm 10mm 5 45



② Down hand, 

1666 f 2 p 66a

③ over head



(စက်ဝိုင်းပေါ်မေးခွဲများ)

④ All position - equalizer in 6.6 R.

of the welding out

AC (or) DC

Ans 10 → E 6010 (or) E 6011

③ Rutila

not vertical, round hand, overhead all position
no gl. d. r. straight (not: grown up)
out as (st) polarity

ANS NO E6012 (or) E6013

Zone of SF, zone of 2 1/2 of PDI

④ Low Hydrogen

(4) Low Hydrogen
Hydrogen arc welding AC DC both are ok for
all applications except for 60% TIG welding
application of diff or overhead etc. can give medical
applications All positions reverse (re)
DC straight polarity is best (electrode pos)


Ans NO EGO15 and EGO16

Bother odz miz: afobu standing od amral baf.
nab m: n maral: (200 af: 6 am @ f: 9 af: 6 m d: 9 af)
o af: mif m standing af m d af 70 m no af ob

⑤ Iron Powder Contact

non-coating of 50% and
coating of 50% on all ACDCJ and 0% on all
GPN (All position) and all

NWS NO E 6024 and E 6027



ASTM E 601


AWS, ASTM (American Society of Testing of Material)

BS (British, Japan, German)

American Standard

AWS E 601 X X X X (conf: is it a good idea)

60000 psi



E 601 60000 psi
70000 psi
80000 psi
Higher

E 60 2 0
3

20000 E 6010 { 60000 psi

and it is: AC, DC reverse polarity, y

② E 6030 { 60000 psi and it is: AC or DC

③ E 6027 { 60000 psi and it is: AC or DC
downward, for AC, DC (ST) it is: AC or DC

60000 psi

E 60 11

60000 psi: ① → 60000 psi { callulose is: Titanium 30%,
AC or DC, Deo: reverse

E 6012

60000 psi

② → 60000 psi { Rutile titanium, Sodium
AC or DC, Deo: straight
Polarity 1

E 6013

60000 psi

③ → 60000 psi { Rutile titanium, Sodium
AC or DC, Deo: straight
polarity y

E 6014

60000 psi

④ → 60000 psi { Titanium
AC, DC

E 6015

60000 psi

⑤ Low hydrogen sodium
AC, DC (reverse)

E 6016

60000 psi

⑥ Low hydrogen, for AC or DC
AC - DC (DC → reverse)

⑦

⑦ it is: AC, DC

E 60 11 { 60000 psi: extraction, 60000 psi

tensile strength all position
callulose; AC or DC, Deo: reverse

E6013 - mild steel (only) / ES E207

Approved company

E → electric electrode

60 → 60000 psi

1 → all position

3 → Rutile Titanium Dioxide

AC - DC (St) DC (St) - 60 amp

rod of 4mm (size of amp)

Flat → Down hand flat of amp 105 → 130

vertical overhead of amp 120 → 130

Chinese Electrode

Heavy { company } No. 100

amp of size of 60

	Flat	vertical (F)	O (overhead)
3.2 mm (1/8")	90 → 130	80 → 100	80 → 100
4 mm (5/16")	130 → 190	110 → 130	110 → 130
5 mm (3/8")	160 → 240	160 → 210	160 → 240

90 → 130

→ 90, 105, 110 → 130

Size 3/8" (9) 6 mm diameter: new work: se. gas port.

Keep dry

m. T20 corresponding to BS E316

Forchiness

Size in

9-3-1971 6 mm diameter: new work: → 20 G. mm

Gas port: → 20 G. mm

6 mm diameter: 3/8" 6/16"

(1) new work: 3/8" 6/16"

(2) new work: 3/8" 6/16"


(3) new work: 3/8" 6/16"

(4) new work: 3/8" 6/16"

60 3/8" 6/16"

(5) new work: 3/8" 6/16"

Key



(6) new work: 3/8" 6/16"

(7) new work: 3/8" 6/16"

(8) new work: 3/8" 6/16"

(9) new work: 3/8" 6/16"

(10) new work: 3/8" 6/16"

(11) new work: 3/8" 6/16"

(12) new work: 3/8" 6/16"

(13) new work: 3/8" 6/16"

(14) new work: 3/8" 6/16"

(15) new work: 3/8" 6/16"

(1) regulator (to be used for welding)

explosion

(2) 1/4 inch (to be used for welding)

(3) 1/2 inch (to be used for welding)

(4) 3/4 inch (to be used for welding)

1000 psi

110 psi

3300 psi

2 lb (1/4 inch)

oxygen

oxygen cylinder

(1) oxygen cylinder

(2) oxygen cylinder

(3) oxygen cylinder

oxygen cylinder

oxygen cylinder

oxygen cylinder

oxygen cylinder

oxygen cylinder

oxygen cylinder

oxygen cylinder

oxygen cylinder

oxygen cylinder

oxygen cylinder

oxygen cylinder

oxygen cylinder

oxygen cylinder

sparker

leather hard glove


spark lighter

comparator

tip of nozzle

tip of nozzle

tip of nozzle



Fitting of oxygen acetylene welder

oxygen acetylene welder



oxygen acetylene welder

oxygen acetylene welder

oxygen acetylene welder

oxygen acetylene welder

oxygen acetylene welder

oxygen acetylene welder

oxygen acetylene welder

oxygen acetylene welder

oxygen acetylene welder

oxygen acetylene welder

$2 \text{ AgNO}_3 \cdot 2 \text{ H}_2\text{O} \rightarrow 2 \text{ Ag} + 2 \text{ HNO}_3 + \text{O}_2$
 $2 \text{ Ag} + \text{O}_2 \rightarrow 2 \text{ Ag}_2\text{O}$
 $\text{C}_2\text{H}_2 \rightarrow \text{C}_2\text{H}_4$

pipe $\rightarrow$ Iron: (red) - 74 m (30)

C_2H_2 - $\{ \text{monomer: } (n \text{ mol}) \text{ now } - 2 \text{ mol} / 2 \text{ mol} \}$

2007000 value up of 10:0000. 9 or 1000. 1000000

C_7H_{12} by IR indicates 7 carbon



$\frac{d}{dt} \ln \rho = -\frac{\partial}{\partial x} v$





∴ 2nd value of $\log 7$ or 7 is infinite

* ଅନୁସନ୍ଧାନ ଯୋଗୁଁ ଗୋଟିଏ ନିର୍ଦ୍ଦିଷ୍ଟ ପଦାର୍ଥର C_2H_2 ଗଠନ

Er-Hz regulator of $\sigma_{\text{eff}} = 10^{-2} \text{ cm}^2$


of Key 94.

of Regulatory (G)M




hose
not
yead



red value of



* Regulator of working pressure of actuator



6. 800 value up to 6 of Jan



Types of communication:

ଓଡ଼ିଆ ଶାସ୍ତ୍ରରେ ଓଡ଼ିଆ
~ ~ ~ ସାମାଜିକ
ଗୋପନୀୟ

प्रत्येक विलेय C_2H_2  प्रत्येक

- d. d. 18: 2-2m - 2 2m

$$\text{trans-}C_2H_2Cl_2 \text{ Pol}$$

පිටිපිටි ගැසීමේ ක්‍රියාව:

පහළින් පිටි, මැදින්
පිටි ගැසීමේ ක්‍රියාව

සාමාන්‍යයෙන් ගැසීමේ ක්‍රියාව:


- Nozzle එකේ සිටින්නා
- C_2H_2 වායුව ගැසීමේ ක්‍රියාව
- Nozzle එකේ
- පාලක, මැද
- Nozzle එකේ සිටින්නා

Backfire (පරිසරයේ, පිටිපිටි ගැසීම)

- i. පහළින් පිටි, මැදින් regulator ගැසීමේ ක්‍රියාව
සාමාන්‍යයෙන් පරිසරයේ, පිටිපිටි ගැසීම:
- ii. පහළින් පිටි, මැදින්, පිටිපිටි ගැසීම (valve ගැසීමෙන්
පිටිපිටි ගැසීම) (පිටිපිටි ගැසීම)
- iii. පහළින් පිටි, මැදින්, පිටිපිටි ගැසීමෙන් පිටිපිටි ගැසීම
ගැසීමේ ක්‍රියාවෙන් පිටිපිටි ගැසීමේ ක්‍රියාව:

(Flash back) { පිටිපිටි ගැසීම }

- i. Regulator එකේ පිටි, මැදින් පිටිපිටි ගැසීමේ ක්‍රියාව
පිටිපිටි ගැසීමේ ක්‍රියාව
- ii. පහළින් පිටි, මැදින්, පිටිපිටි ගැසීමෙන් (nozzle) ගැසීම
පිටිපිටි ගැසීමේ ක්‍රියාව (nozzle on tip)
- iii. පහළින් පිටි, මැදින්, පිටිපිටි ගැසීමෙන් පිටිපිටි ගැසීමේ ක්‍රියාව




- i. පහළින් පිටි, මැදින්, පිටිපිටි ගැසීමෙන් පිටිපිටි ගැසීමේ ක්‍රියාව
(nozzle ගැසීමේ ක්‍රියාවෙන් පිටිපිටි ගැසීමේ ක්‍රියාව)
- ii. පහළින් පිටි, මැදින්, පිටිපිටි ගැසීමෙන් පිටිපිටි ගැසීමේ ක්‍රියාව
පිටිපිටි ගැසීමේ ක්‍රියාවෙන් පිටිපිටි ගැසීමේ ක්‍රියාව

ප්‍රසාරණය: පීඩනය: ප්‍රතිදාය (Pressure/volume ratio) (පීඩන: ප්‍රතිදාය)

ප්‍රධාන ලක්ෂණ

- * ප්‍රතිදාය: පීඩනය: ප්‍රතිදාය (Pressure/volume ratio) ප්‍රතිදාය: පීඩනය: ප්‍රතිදාය
- * ප්‍රතිදාය: පීඩනය: ප්‍රතිදාය (Pressure/volume ratio) ප්‍රතිදාය: පීඩනය: ප්‍රතිදාය
- * ප්‍රතිදාය: පීඩනය: ප්‍රතිදාය (Pressure/volume ratio) ප්‍රතිදාය: පීඩනය: ප්‍රතිදාය

ප්‍රධාන ලක්ෂණ



ප්‍රධාන ලක්ෂණ → heaters

ප්‍රධාන ලක්ෂණ → heaters
ප්‍රධාන ලක්ෂණ → heaters
ප්‍රධාන ලක්ෂණ → heaters
ප්‍රධාන ලක්ෂණ → heaters

ප්‍රධාන ලක්ෂණ (3 types of flame)

(1) ප්‍රධාන ලක්ෂණ (natural flame)

(2) ප්‍රධාන ලක්ෂණ (oxidizing flame) (car burzing flame)

(3) ප්‍රධාන ලක්ෂණ (oxidizing flame)

ප්‍රධාන ලක්ෂණ



ප්‍රධාන ලක්ෂණ: ප්‍රතිදාය: ප්‍රතිදාය (Pressure/volume ratio) ප්‍රතිදාය: පීඩනය: ප්‍රතිදාය

ප්‍රධාන ලක්ෂණ: ප්‍රතිදාය: ප්‍රතිදාය (Pressure/volume ratio) ප්‍රතිදාය: පීඩනය: ප්‍රතිදාය

ප්‍රධාන ලක්ෂණ: ප්‍රතිදාය: ප්‍රතිදාය (Pressure/volume ratio) ප්‍රතිදාය: පීඩනය: ප්‍රතිදාය


(1) ප්‍රධාන ලක්ෂණ (natural flame)



ප්‍රධාන ලක්ෂණ: ප්‍රතිදාය: ප්‍රතිදාය (Pressure/volume ratio) ප්‍රතිදාය: පීඩනය: ප්‍රතිදාය

High carbon steel, Alloy steel, Stainless steel
(6) 6mm diameter (1) 1/2 inch (Chromium)
Semi steel (1) 1/2 inch (1) 1/2 inch (1) 1/2 inch
of 6mm diameter (1) 1/2 inch (1) 1/2 inch (1) 1/2 inch

(2) 6mm diameter (1) 1/2 inch (1) 1/2 inch



6mm diameter (1) 1/2 inch (1) 1/2 inch (1) 1/2 inch
(copper + zinc) (brass) (1) 1/2 inch (1) 1/2 inch

Gas welding (1) 1/2 inch (1) 1/2 inch (1) 1/2 inch
Gas welding (1) 1/2 inch (1) 1/2 inch (1) 1/2 inch

6mm diameter (1) 1/2 inch (1) 1/2 inch (1) 1/2 inch
(1) 1/2 inch (1) 1/2 inch (1) 1/2 inch (1) 1/2 inch

(1) 6mm diameter (1) 1/2 inch (1) 1/2 inch (1) 1/2 inch

6mm diameter (1) 1/2 inch (1) 1/2 inch (1) 1/2 inch
(1) 6mm diameter (1) 1/2 inch (1) 1/2 inch (1) 1/2 inch
(1) 6mm diameter (1) 1/2 inch (1) 1/2 inch (1) 1/2 inch
(1) 6mm diameter (1) 1/2 inch (1) 1/2 inch (1) 1/2 inch

oxy - act:	
oxy - Hydro	oxy - petrol
oxy - natural gas	oxy + petrol = petmolgen

U. Hay Nung's lecture

Electric arc welding of mild steel plate in ship building has superseded riveting as the main form of structural attachment. The main advantages are

- (1) substantial saving in steel weight
- (2) economy of construction
- (3) greater fabrication potential
- (4) better continuity of strength
- (5) greater freedom of design and
- (6) The provision of water tightness without caulking

On other hand, the effect of joint depends upon the weld and the position in which operating. Also the rapid heating and cooling tend to distort the plate. and locked up stresses occur to the construction

These can be minimized if the structure is suitably prepared and the correct sequence of welding is followed.

Usual welding process

① Manual metal arc welding

A fusion weld is one where there is actual melting of the material being joined although the weld metal is composed very largely of added material which generally has the same characteristics as the parent metal. The heat necessary for making fusion welds is usually supplied by electrical means. The most common of welding processes is still the one which is manual metal arc welding with a coated stick electrode.

② Automatic Arc welding

Early efforts at automation of the metal arc welding process included devices which deposited contact electrode in a prepared joint, and the limitation of the above technique for continuous welding is the difficulty of transferring the arc from one electrode to the next without incurring corrosion in the weld. The answer to the problem was found by using a coated electrode in coil form and this is what is commonly done.





submerged arc process


This method employs a coiled bare wire and a welding flux which is supplied separately, as a free flowing powder. The flux is delivered from a hopper and deposited on the joint to be welded a head of the electrode wire. The arc is completely blanketed and hidden from view and is very quiet and there is no alloy anode from fume or glare.

welded connections

The two basic types of welded connections are the butt and fillet and variations of these types will be described.

Fig (1) shows a general type of butt weld and the preparation of this one is shown in fig (2). The angle of chamfer and the gap between the plates and the rolling, may be sliding and different grades. These are generally provided by local sub-surface of the classification societies and before work design began. The preparation of plate edges is done by either planning or burning machine in the shop but on the ship during construction the chamfer can either be hand machine chip or burn.

Method	Preparation	Plate thickness	Job	Method
a		under 0.63"	Plate top bottom shell seams and butts to plates deck beams bulk head beams and butt	weld (1) and (2) manual or machine
b		over 0.63"	Bottom shell and side seams or butts bulk head deck seam and butt Tank top beams	"
c		under 0.63"	Shell seams and butt markings and tank top centre line storage butt bulk head seams and butt	weld (1) manual
d		under 0.28 manual under 0.56 machine	Bulk head beams and any seams or butts to be completed with plates horizontal	weld (1) and (2) manual or machine

	under 0.56" plate edges are strength over 0.56" plate are chanter ed.	Tank top butts Deck butts Deck house side butts	weld (1) manual machine continuous weld if floors are water tight or oil tight intermediate otherwise
---	---	--	--







Fig (3) Shows the basic fillet weld and welds generally done by hand vibration of the are shown in fig (4). The factor governing the leg length of the type of weld is the thickness of the two plates making the joint. The rules of the classification societies give the leg length in relation to the important of connection and state also whether the weld is continuous or intermittent with intermittent weld the spacing of weld also stated.

Plan of weld	Type	Job
(a) 	continuous weld both sides of plate	All main water tight strength work e.g. bulkhead Tank top vertical Centre veel Beam knees etc
(b) 	continuous weld one side inter mittent weld the other	Secondary water tight and gas tight work e.g. w.c.s galley Deck houses netting space.



Intermittent weld both sides - staggered

beams, beams bulkheads, stiff frame, floor etc.



Intermittent weld both side - Chain.

Fig (5) Fillet weld spacing

Fig (5a) to (d) show the various conditions and intermittent weld and where they are used. Before a fillet weld is begun it should be seen that the gap between the plate is never greater than $\frac{1}{8}$ " If a larger gap occurs one side of the gap should be sealed by welding and then the opposite side gouged to meet this weld, before completing the weld of the second side. The strength of welded joint depends particularly upon the skill and reliability of the welder. It must be met carefully in cleaning the joint keeping it dry, and leaving away the slag or flux in a multiplex weld. The tight, sides and shape of weld also are important. If all these points are considered, there is no reason why a first class attachment should not be produced. If there is

Excessive loading of any particular welded joint
 cracks occasionally occur in spot welding adjacent
 to joint and only in the weld itself if the above
 points have not been followed. In both butt and
 fillet weld it is important that they are run
 towards a free end, for otherwise locked up
 stresses occur which calls cracking of weld and
 distortion of plating. Therefore it is important
 that the joint is suitably prepared and
 be tared and the sequence of welding checked
 before the operator allowed to begin.

Welding of iron & steel

Ship building, Railways, Motor car & aircrafts, reventing
 work, repair & maintenance

Fusion welding (E.T.E.C)

Two types of fusion welding are (1) Fusion without
 mechanical pressure (2) Fusion with
 mechanical pressure. (1) Fusion without mechanical pressure
 is of two types (a) Gas process (b) Arc process. (2) Fusion with
 mechanical pressure is of two types (a) Cold chisel (b) Hot chisel.

Fusion without pressure is of two types (a) Gas process (b) Arc process.

- (1) Gas process (a) oxy acetylene (b) oxy hydrogen
 (c) oxy-hydrocarbon (d) Air Acetylene

Gas welding of iron with oxygen and acetylene is done by using
 a flame of oxygen and acetylene gas.

(2) Arc process

- (1) metal arc (2) Atomic arc (3) submerged arc

- (4) carbon arc (5) inert gas arc (6) electro slag.


Arc welding is done by using an electrode and an electric arc
 or arc as a heat source. The electrode is of two types (a) carbon
 electrode (b) metal electrode.

Carbon arc welding is used for joining of ferrous & non ferrous metal
 - iron & steel, copper, aluminium, etc.

oxy-acetylene welding

Gas welding or oxy acetylene welding is done by using
 oxygen & acetylene gases. The flame is of two types (a) neutral
 flame (b) oxidizing flame (c) reducing flame. The temperature
 of the flame is about 3500°C. It is used for joining of ferrous
 metal & non ferrous metal.

Advantages of oxy acetylene welding are (1) It is a portable
 process. (2) It is a versatile process. (3) It is a clean process.
 Disadvantages of oxy acetylene welding are (1) It is a slow process.
 (2) It is a dangerous process. (3) It is a costly process.

Typical (Low)

fit carbonising frame -



carbureting cone (or)

long with pointed or regged end

wie im. Gross Metzger

Flame or Reducing


Flame out of control

ind. of society of

பெருந்தேவியே, நம: ||


Acetylene feather or luminous intermediate cone of
1st combustion stage in carbon white cone of light
1st combustion stage in ~~carbon white cone of light~~
carbon cone of light: C_2H_2 C_2H_4 C_2H_6 C_2H_2 C_2H_4 C_2H_6 C_2H_2 C_2H_4 C_2H_6
feather or outer edge of carbon cone of light: C_2H_2 C_2H_4 C_2H_6 C_2H_2 C_2H_4 C_2H_6
particular cone of light: C_2H_2 C_2H_4 C_2H_6 C_2H_2 C_2H_4 C_2H_6 C_2H_2 C_2H_4 C_2H_6
carbon content of light: C_2H_2 C_2H_4 C_2H_6 C_2H_2 C_2H_4 C_2H_6 C_2H_2 C_2H_4 C_2H_6
Excess oxygen

2) Oxidising Flame




 oxidizing effect
 of hot metal in oxidizing effect
 of flame or oxygen of gas by the surface
 of hot metal point of view of the surface
 of hot metal in the air, brass, bronze of, and
 of the air

(3) Neutral flame




oxygen & acetylene
at 2:1 or 1.5:1 ratio
of 1:1 ratio neutral
flame is formed

Intermetallic metal of weld joint is not affected by the flame of neutral flame. It is not affected by the flame of neutral flame.

metal	Flame
Mild steel	Neutral flame
stainless steel	"
cast iron	"
copper	"
Aluminium	"
Nickel	"
monel	"
Brass	oxidizing flame
bronze	"
Aluminium alloy	slightly carburizing
magnesium alloy	"
zinc brass alloy	"

Method of welding



or vice versa. non ferrous metal is not affected by the flame of neutral flame. It is not affected by the flame of neutral flame. It is not affected by the flame of neutral flame.

leftward or forward tip of torch is moved leftward or forward. It is not affected by the flame of neutral flame. It is not affected by the flame of neutral flame. It is not affected by the flame of neutral flame.


Backward tip of torch is moved backward. It is not affected by the flame of neutral flame. It is not affected by the flame of neutral flame. It is not affected by the flame of neutral flame.

For flame welding of iron: welded portion of margin
on surface of plate of iron: 20% $\frac{1}{8}$ " max conc down
Steel plates: butt joint max of 6" or less molten
metal & can be heated in various

In order to use a blow torch, the tank must contain clean, white (unleaded) gasoline. and the pump on the tank must be operated to build up sufficient pressure to cause the gasoline to spray through the burner tube when the valve is opened. A piece of shot metal or other convenient means is provided to shield the end of the burner

To extinguish a blow torch, close the V/V after the torch has been extinguished. It is good practice to loosen the filling plug and relieve the pressure within the tank. When the pressure has been relieved, the filling plug is tightened again.

The V/V is then opened slightly and left open. If the V/V is not left open the metal around the V/V will contract and the V/V may stick so tight by that it will be damaged.



- 1/ soldering iron rest
- 2/ soldering iron hose
- 3/ V/V
- 4/ fuel pump
- 5/ fuel pan
- 6/ burner tube

In wire solder, paste fluxes, commercially manufactured are available in cans of various sizes. These fluxes which contain grease for counter acting corrosion, are substitute for acid.

Please Pass me —
may I have ^{from} water
waiter
yes

Fluxes After a chemical preparation (powder, paste or liquid) used to keep the metal clean so that the solder will stick to it. If flux is not used, the heat will cause oxides to form on the metal surface and prevent the solder from adhering firmly. A list of common fluxes and the metals on which they are used is given in the following.

metals	Fluxes
Brass, copper, iron	Resin
Lead	Tallow, rosin
Iron steel	Sorax, sal ammoniac
Aluminum	Either corrosive or non corrosive
The commonly used corrosive fluxes are zinc chloride, sal ammoniac, powder the metal.	
It allowed to remain on it after soldering.	
They should therefore be completely removed by thorough washing after the work is done. It is for this reason that rosin, a non corrosive flux is used when soldering electrical connections. The rosin is used in paste form or as liquid.	

Tinning is spreading a thin layer of solder on the surface of the metals that are to be soldered together causing the solder to adhere to the metal and make a firm union with it. The purpose of tinning is to prepare the surfaces so that they will unite readily in the process of soldering, and make a firm joint. It is recommended that all metals except lead & tin, be tinned before soldering. Lead & tin need only to be scraped & clean.

Copper brass and ungalvanized iron may be prepared to receive solder by cleaning the surface and applying zinc chloride. Galvanized iron or sheet zinc should be cleaned with muriatic acid before the

solder is applied. Where a metal has become tarnished or necessary to remove the tarnish and expose the bare, clean metal before tinning it, otherwise the solder ordinarily will not adhere to the metal.

Tinning the soldering iron. The point of a soldering iron must be tinned before it will do a good job of soldering. Tinning in this instance refers to the process of coating the point with solder to prevent oxidation when heated. The general steps in tinning procedure are as follows.

1. File the faces of the point (or rub them with emery cloth) until they are smooth and flat.
2. Heat the point hot enough to melt the solder readily, but do not heat it red hot.
3. Rub the faces of the point of a sal-ammoniac brick, applying a small amount of solder to the point as it is rubbed on the sal-ammoniac. The solder will form a thin bright film on the face of the point.

4. If a sal-ammoniac brick is not available, the point can be tinned by rubbing it in pulverized rosin and solder. When a soldering iron is over heated the tinning is destroyed, & if this happens the point should be allowed to cool and then should be filed and retinned.

Dipping Solution. When soldering iron is heated the scales that tend to form on the point can be removed by dipping the point in a dipping solution made of one part of sal-ammoniac powder mixed with 40 parts of water. Only the tip of the point should be dipped in the solution and it should be withdrawn quickly. The tinned point will emerge bright and clean.

A soldering iron should never be dipped into zinc chloride or other acid solution, as the acid may spatter into the eyes or on the skin and clothing, and possibly cause blindness or severe burns.