

Unit	UEPOPS456A Perform switching to a switching program - - - -	Test Number	2/2
Total Marks	50	Time allowed	2 HR

Instruction to assessors

- Please provide the blank A4 sheets to students to write the answers on them
- Please tell the students not to write on the question papers
- Online test can also be supplemented.
- The marking can be done by referring the attached marking guide
- Giving the marks based on students' effort & demonstration of the absorbed study & competency rather than the final answer is to made
- The necessary formulas can be provided on the white board.
- The formula which can be provided will be advised separately.
- No notes, digital storage devices, programmable calculators are allowed.
- Page 1 = Instruction to assessors & students
- Page 2+(3)= Question Paper
- Page (3)+4 and the remaining pages= Marking Guide


Instruction to students

- Write the answers on provided A4 blank sheets
- Do not write the answers on the question papers
- Online test can also be supplemented.
- The marking can be done by referring the attached marking guide
- The necessary formulas can be provided on the white board on request..
- The formula which can be provided will be advised separately.
- No notes, digital storage devices, programmable calculators are allowed.

Unit		Test Number	2/2
Total Marks	50	Time allowed	2 HR

30 Marks

1. Find the real power supplied by Generator A and Generator B




GA- Generator A 200MW 6% Drop

GB- Generator B 400MW 7% Drop

(9 marks)

2



Generator TX/330kv

Load 300MW 0.9PF Lagging Base 100MVA

In above diagram, what total MW and MVAR must the generator supply and at what power factor? (9 marks)

3. Sketch power angle curve of synchronous machine.

(4 marks)

4. Explain how reactive power is controlled by using Static Var Compensation system

(4 marks)

5. How will you connect reactive power control capacitor bank to 3 phase power supply system? (4 marks)

Unit		Test Number	
------	--	-------------	--

Total Marks

Time allowed

Answer

Marks


POWER SYSTEM OPERATION

KHANH NGUYEN

Test 2

29/30


① Find the real power supplied by Gen. A & Gen. B



* Generator A - 200 MW 6% Drop

* Generator B - 400 MW 7% Drop

Both machines are supplying 300 MW load

B load share = X A load share = $300 - X$ ① $\Delta aed \sim \Delta afc$ are similar

$$\frac{ad}{ac} = \frac{ed}{fc} \rightarrow \frac{0.07}{0.01+y} = \frac{400}{X} \quad (1)$$

② $\Delta bdh \sim \Delta bcg$ are similar

$$\frac{bd}{bc} = \frac{dh}{cg} \rightarrow \frac{0.06}{y} = \frac{200}{300-X} \quad (2)$$

10

Unit		Test Number	
Total Marks		Time allowed	

Answer

Marks

$$\begin{aligned} \textcircled{1) \text{ From (1) } \rightarrow \frac{0.07}{0.01+y} &= \frac{400}{X} \\ 0.07X &= 400(0.01+y) \\ 0.07X &= 4 + 400y \\ 0.07X - 4 &= 400y \end{aligned}$$

$$\text{Hence } y = \frac{0.07X - 4}{400} \quad \textcircled{3}$$

$$\textcircled{2) \text{ From (2) } \rightarrow \frac{0.06}{y} = \frac{200}{300-X}$$

$$\therefore y = \frac{0.06(300-X)}{200} = \frac{18 - 0.06X}{200} \quad \textcircled{4}$$

$\textcircled{3} = \textcircled{4}$:

$$y = \frac{(0.07X) - 4}{400} = \frac{18 - 0.06X}{200}$$

$$\frac{0.07X - 4}{2} = 18 - 0.06X$$

$$0.07X - 4 = 36 - 0.12X$$

$$0.07X + 0.12X = 36 + 4$$

$$0.19X = 40$$

$$X = \frac{40}{0.19} = 210.5 \text{ MW}$$

$$\text{Then B load share} = X = \underline{210.5 \text{ MW}}$$

$$\textcircled{2) \text{ A load share} = 300 - X$$

$$= 300 - 210.5 = 89.5 \text{ MW}$$

$$\underline{\text{A load share} = 89.5 \text{ MW}}$$

Unit		Test Number	
Total Marks		Time allowed	

Answer

Marks

KHANH NGUYEN

$$\text{base VA} = 100 \text{ MVA} \quad \text{VA} = 1 \text{ pu}$$

$$\text{load A} = 60 + j0 \text{ MVA}$$

$$\text{load A (pu)} = \frac{60 + j0 \text{ MVA}}{100 \text{ MVA}} = 0.6 + j0$$

$$X_{CA} \begin{array}{|c|c|} \hline 0.1 & 0.1 \\ \hline \text{---} & \text{---} \\ \hline 0.1 & 0.1 \\ \hline \end{array} = \begin{array}{|c|c|} \hline 0.05 & 0.05 \\ \hline \text{---} & \text{---} \\ \hline \end{array} = \begin{array}{|c|} \hline 0.1 \\ \hline \text{---} \\ \hline \end{array} X_{CA} = 0.1 \text{ pu}$$

$$\frac{0.1 \times 0.1}{0.1 + 0.1} = 0.05 \quad E = \sqrt{\left(V + \frac{QX}{V}\right)^2 + \left(\frac{PX}{V}\right)^2}$$

$$V_C = \sqrt{\left(1 + \frac{0.6 \times 0.1}{1}\right)^2 + \left(\frac{0.6 \times 0.1}{1}\right)^2}$$

$$= \sqrt{1^2 + 0.06^2}$$

$$V_C = 1.002 \text{ pu}$$

$$I_{CA} = \frac{\text{Power flow } C \rightarrow A}{\text{VA}} = \frac{0.6 + j0}{1} = 0.6 \text{ pu}$$

$$\text{Power from C} = \text{Power flow } C \rightarrow A + \text{Power loss}$$

$$= 0.6 + j0 + I^2 X_{CA}$$

$$= 0.6 + j(0.6)^2 \times 0.1$$

$$= 0.6 + j0.036 \text{ pu}$$

$$0.9 \text{ pF}$$

$$\cos 0.9 = 26^\circ \quad \text{load C} = 300 + j300 \times \tan 26$$

$$= 300 + j146 \text{ MVA}$$

$$\text{load C / VA} = \frac{300 + j1.46}{100} = 3 + j1.46$$

$$P_{EC} + jQ_{EC} = 3 + j1.46 + 0.6 + j0.036$$

$$= 3.6 + j1.496 \text{ pu}$$

$$X_{EC} \begin{array}{|c|c|} \hline 0.1 & 0.04 \\ \hline \text{---} & \text{---} \\ \hline \end{array} = \begin{array}{|c|c|} \hline 0.05 & 0.02 \\ \hline \text{---} & \text{---} \\ \hline \end{array} = \begin{array}{|c|} \hline 0.07 \\ \hline \text{---} \\ \hline \end{array} X_{EC} = 0.07 \text{ pu}$$

$$V_E = \sqrt{\left(V_C + \frac{Q_{EC} X_{EC}}{V_C}\right)^2 + \left(\frac{P_{EC} X_{EC}}{V_C}\right)^2}$$

Unit		Test Number	
Total Marks		Time allowed	


Answer	Marks
$= \sqrt{1.002 + \left(\frac{1.496 \times 0.07}{1.002}\right)^2 + \left(\frac{3.6 \times 0.07}{1.002}\right)^2}$ $= 1.135 \text{ pu}$ $I_{EC} = \frac{\text{Power from } E \rightarrow A}{V_C} = \frac{3.6 + j1.496}{1.002}$ $= \sqrt{\frac{3.6^2 + 1.496^2}{1.002}}$ $= 3.89 \text{ pu}$ $\text{Power from } E = \text{Power from } E \rightarrow A + \text{Power loss}$ $= 3.6 + j1.496 + jI_{EC} \times X_{EC}$ $= 3.6 + j1.496 + j(3.89)^2 \times 0.07$ $= 3.6 + j1.496 + j1.06$ $= 3.6 + 2.556$ $\text{Power} = \sqrt{3.6^2 + 2.556^2}$ $= 4.41 \angle 35.37^\circ \text{ pu}$ $\text{Power supplied by generator} = \text{pu} \times 100 \text{ MVA}$ $= 4.41 \times 100 \text{ MVA}$ $= 4.41 \text{ MVA}$ $\cos 35.37^\circ = 0.815$ $\text{PF} = 0.815 \text{ lagging PF}$	

Unit		Test Number	
Total Marks		Time allowed	


Answer		Marks
--------	--	-------

KHANH NGUYEN


10



excitation




3 phase supply.



Synchronous machine power factor is adjustable. Depending on field excitation current, it can be lagging or leading or unity.

The synchronous motor is connected to busbar terminal of the substation.

By adjusting its power factor by field excitation, the power of over all plant can be adjusted.



Unit		Test Number	
Total Marks		Time allowed	

Answer	Marks
<div style="text-align: right; margin-bottom: 10px;">(5)</div> <p>Adjust Excitation Generated voltage is adjusted</p> <p>3ϕ Regulator adjusts the load voltage</p> <p>Power Factor Improvement 3ϕ Capacitor Bank</p>	<p>10</p>


Unit		Test Number	
Total Marks		Time allowed	

Answer

Marks

④

KHANH NGUYEN



Static Var Compensator (S.V.C) system utilizes silicon control rectifiers (SCR) whose conduction depending on gate firing signal provided by gate control circuit.


If more current is allowed to pass through inductor by SCR, P.F becomes lagging.

If more current is allowed to pass through capacitor P.F becomes leading.

The gate control circuit senses the system Power Factor and produces the gate firing signal to SCR that allow the current to pass through the inductor or capacitor.

The overall plant P.F can automatically be adjusted by SVC.

Current Conduct



10


Unit		Test Number	
------	--	-------------	--

Total Marks		Time allowed	
-------------	--	--------------	--

Answer	Marks
<p> S Base $V_A = 100 \text{ mVA}$ $V_A = 1 \text{ pu}$ Haeji nider keng load $A = 60 + j0 \text{ mVA}$ (load at pu) = $\frac{60 + j0.4 \text{ mVA}}{100 \text{ mVA}} = 0.6 + j0$ 1 pu </p> <p> K_{CA} </p> <p> $\frac{0.1 \times 0.1}{0.1 + 0.1} = 0.05$ </p> <p> $E = \sqrt{\left(\frac{V + PX}{Z}\right)^2 + \left(\frac{PX}{V}\right)^2}$ </p> <p> $= V_C = \sqrt{\frac{(1 + 0 \times 0.1)^2}{1} + \frac{(0.6 \times 0.1)^2}{1}}$ </p> <p> $= \sqrt{1^2 + 0.06^2}$ </p> <p> $V_C = 1.002 \text{ pu}$ </p> <p> $I_{CA} = \frac{\text{Power flow } C \rightarrow A}{V_A} = \frac{0.6 + j0}{1} = 0.6 \text{ pu}$ </p> <p> $\text{power from } C = \text{power flow } C \rightarrow A + \text{power loss}$ </p> <p> $= 0.6 + j0 + I_{CA}^2 \times K_{CA}$ </p> <p> $= 0.6 + j(0.6)^2 \times 0.1$ </p> <p> $= 0.6 + j0.36 \text{ pu}$ </p> <p> 0.9 pf </p> <p> $\cos^{-1} 0.9 = 26^\circ$ </p> <p> $\text{load } C = 300 + j300 + \text{form } 26$ </p> <p> $= 3000 + j196 \text{ mVA}$ </p> <p> $\text{load } C/V_A = 300 + j1.96 = 3 + j1.46$ </p> <p> $P_{EC} + jQ_{EC} = 3 + j1.46 + 0.6 + j0.36$ </p> <p> $= 3.6 + j1.496 \text{ pu}$ </p>	<p>23</p> <hr style="width: 20px; margin: 0 auto;"/> <p>30</p>

Unit		Test Number	
------	--	-------------	--

Total Marks		Time allowed	
-------------	--	--------------	--

Answer	Marks
<p>③ →</p>  <p>DC excitation</p> <p>3 phase supply.</p> <p>Improved power factor</p> <p>original Power factor</p> <p>load</p> <p>lagging</p> <p>Syn motor</p> <p>Synchronous machine power factor is adjustable depending on field excitation current it can be lagging or leading or unity.</p> <p>The synchronous motor is connected to busbar terminal of the substation.</p> <p>By adjusting its power factor by field excitation the power of over all plate can be adjusted.</p> <p>current</p> <p>PF</p> <p>PF</p> <p>IPC</p>	<p>10</p>

Unit		Test Number	
------	--	-------------	--

Total Marks		Time allowed	
-------------	--	--------------	--


Answer	Marks
<p> $X_{ec} = \begin{matrix} 0.1 & 0.04 \\ \text{---} & \text{---} \\ 0.1 & 0.04 \\ \text{---} & \text{---} \end{matrix} = \begin{matrix} 0.05 & 0.02 \\ \text{---} & \text{---} \\ 0.07 & \\ \text{---} & \end{matrix} \times FC = 0.02$ </p> <p> $V_c = \sqrt{\left(\frac{V_c + Q_{ec} + V_{ec}}{V_s}\right)^2 + \left(\frac{P_{ec} \times X_{ec}}{V_c}\right)^2}$ </p> <p> $\sqrt{1.0002 + \left(\frac{1.496 \times 0.07}{1.002}\right)^2} + \left(\frac{3.6 + 0.07}{1.002}\right)^2$ </p> <p> $= 1.135 \text{ pu}$ </p> <p> $I_{ec} = \frac{\text{Power factor} \rightarrow A}{V_c} = \frac{3.6 + j 1.496}{1.002}$ </p> <p> $= \sqrt{\frac{(3.6)^2 + 1.096^2}{1.002}}$ </p> <p> $= 3.89 \text{ pu}$ </p> <p> $\text{Power from } \rightarrow \text{Power from } \rightarrow \text{Power from}$ </p> <p> $= 3.6 + j 1.496 + j I_{ec} \times X_{ec}$ </p> <p> $= 3.6 + j 1.496 + j (3.89)^2 \times 0.07$ </p> <p> $= 3.6 + j 1.496 + j 1.06$ </p> <p> $= 3.6 + j 2.556$ </p> <p> $\text{Power} = \sqrt{3.6^2 + 2.556^2}$ </p> <p> $= 4.4 \angle 35.37^\circ \text{ pu}$ </p> <p> $\text{Power supplied by generator} = 10 \times 10.0 \text{ mVA}$ </p> <p> $= 4.41 \times 100 \text{ mVA}$ </p> <p> $\cos 35.37^\circ = 0.815 = 4.41 \text{ mVA}$ </p> <p> $\text{PF} = 0.815 \text{ lagging P.F.}$ </p>	10

Unit		Test Number	
------	--	-------------	--

Total Marks		Time allowed	
-------------	--	--------------	--

Answer		Marks
--------	--	-------

10



Adjust Exciter
 ↓
 Quantities
 u adjust

3φ Regulator
 adjust the
 load volt

Power factor
 Improved
 3φ Capacitor
 Bank

$$I_{sc} = \frac{V_{oc}}{Z_{sc}}$$

$$I_{sc} = \frac{100}{0.2} = 500 \text{ A}$$

$$P_{sc} = 3 \times I_{sc}^2 \times R_{sc}$$

$$P_{sc} = 3 \times 500^2 \times 0.02 = 150000 \text{ W} = 150 \text{ kW}$$

$$P_{sc} = 150 \text{ kW}$$