

PC II Switch Gear Instrumentation

PC II Switch gear Instrumentation 2

Page 32

Q1 Δ connection of motor 2 phase 3600 rpm

Page 38

Q2 Start / Stop / Jog of 3 phase motor 3600 rpm

Page 44

Q3 Forward / Reverse of 3 phase motor 3600 rpm

PC II Switch gear Instrumentation 3

motor starter of 3 phase motor 3600 rpm

Page 44-45

of 3 phase AC Theory of 3 phase motor

Page 45-46

Q4 Relay of 3 phase motor 3600 rpm

Q5 Over current Relay 3600 rpm

Q6 Oil circuit Breaker of 3 phase motor 3600 rpm

PC II Switch gear Instrumentation 4

Page 12

Q7 Surge Reactor 3600 rpm

Page 25

Q8 Sub feeder 3600 rpm

Page 39

Q9 Δ connection of motor 3600 rpm

PC II Switch gear Instrumentation 5

Page 4

Q10 magnetic moving coil Instrument 3600 rpm

Page 11

Q11 Electrostatic volt meter 3600 rpm

Page 17

Q12 Δ connection of motor 3600 rpm

Page 26

Q13 clamp on meter of 3 phase motor 3600 rpm

PC II Switch gear Instrumentation 7

3 phase. 3600 rpm. Specification of 3 phase motor 3600 rpm